



National Aeronautics and
Space Administration

JSC 14651

Lyndon B. Johnson Space Center
Houston Texas 77058

ORBITER SUBSYSTEM

HARDWARE/SOFTWARE INTERACTION ANALYSIS

VOLUME VIII: FORWARD REACTION CONTROL SYSTEM

(NASA-TM-80960)	ORBITER SUBSYSTEM	N80-18089
HARDWARE/SOFTWARE INTERACTION ANALYSIS.		
VOLUME 8: AFT REACTION CONTROL SYSTEM, PART		
2 (NASA)	136 p HC A07/MF A01	CSCL 09B
		Unclas
		G3/16 14302

January 1980



PREFACE


The Orbiter subsystem hardware/software interaction analysis examines software interaction with hardware failure modes. Each failure mode identified in subsystem FMEA (failure mode and effects analysis) is examined for interaction with software. The analysis is based upon key questions which identify potential issues. These potential issues are to be resolved by providing rationale for retention or identifying and implementing changes to eliminate the issue.

The figure on the following page illustrates the relationship of the hardware/software interaction analysis to the verification process which leads to the statement of flight readiness. As shown, the analysis is a supporting item which is a portion of the data base utilized by the FRAT's (flight readiness assessment teams) and the associated SEAM (Systems Engineering Assessment Meeting) teams in planning and controlling the verification process. The overall issue of hardware/software interface compatibility is addressed by the verification process itself. The analysis scope is limited to examination of single failure modes, as identified in the FMEA, and the interaction of these failure modes with the software as reflected by the software requirements.

The hardware/software interaction analysis is performed on a preliminary basis by the JSC Reliability Division. Results are then coordinated with JSC engineering and Rockwell/Space Systems Group engineering and reliability to obtain inputs and approval signatures. The approval sheet for the Forward Reaction Control System are presented below. The Rockwell signatures represent their review of the open issues and risks, if any, performed against the summarization of the analysis. Section 5.0 presents the analysis summary which groups the failure modes by similar retention rationale and is a convenience in identifying groups of failure modes in which the analysis is similar. The reviews with Rockwell did not cover each checklist. The minutes presented in the appendix document the nature and depth of the Rockwell analysis review.


This analysis verified that no open issues remain.

Approved:



Joseph H. Levine
Chief, Reliability Division

VERIFICATION



VERIFICATION PLANNING AND MANAGEMENT


THE HARDWARE/SOFTWARE INTERACTION ANALYSIS IS PREPARED BY RELIABILITY. IT IS ONE OF MANY ANALYSES AND DOCUMENTS USED BY THE SEAM TEAMS AND FRAT'S IN THE PLANNING AND MANAGEMENT OF THE VERIFICATION PROCESS. THE OVERALL VERIFICATION PROCESS LEADS UP TO THE FINAL FLIGHT READINESS STATEMENT FOR EACH SUBSYSTEM AND THE VEHICLE AS A WHOLE.

OTHER ACTIVITIES

DESIGN
MML
SDM
ICD'S

RELIABILITY
FMEA/CIL
HARDWARE/SOFTWARE
INTERACTION ANALYSIS
PRACA
CERTIFICATION

SYSTEM ENGINEERING
FSSR
CPDS
INT. SCHEMATIC
OMRSD/TRSD



HARDWARE/SOFTWARE INTERACTION ANALYSIS

Forward Reaction Control System
SUBSYSTEM

FMEA # SD75-SH-0016A

ANALYSIS DATE June 25, 1979

D. M. Galt
For W. R. Cagle
HARDWARE/SOFTWARE ANALYST

APPROVED:

Kara Smith
JSC Reliability

J. P. Ostrode 1/4/80
Rockwell Reliability

W. Jackson
JSC Engineering - FRAT Sponsor

Wm. F. Meyers
Rockwell Engineering - FRAT Sponsor

20

~~PRECEDING PAGE BEING NOT FILMED~~

TABLE OF CONTENTS

	<u>Page</u>
1.0 INTRODUCTION	1
2.0 SCOPE	1
3.0 APPLICABLE DOCUMENTS	1
4.0 DESCRIPTION	2
5.0 ANALYSIS SUMMARY SHEETS	9
6.0 ANALYSIS CHECKLIST SHEETS	11

LIST OF FIGURES

4-1 HARDWARE/SOFTWARE ANALYSIS CHECKLIST	3
4-2 CHANGE/RETENTION RATIONALE	6
4-3 HARDWARE/SOFTWARE ANALYSIS SUMMARY	7

Appendix	A-1
--------------------	-----

1.0 INTRODUCTION. This report documents the results of the analysis of the hardware/software interaction analysis for the Forward Reaction Control System. This analysis examines the interaction between hardware failure modes and software in order to identify associated issues/risks. These issues/risks are resolved through changes to software requirements to remove them, or surfaced to project/program management with appropriate retention rationale.

2.0 SCOPE. All Orbiter subsystems and interfacing program elements which interact with the Orbiter computer flight software are analyzed. The analysis for each subsystem or interfacing element is presented in a separate volume of this report (see section 3.1).

The analysis examines failure modes identified in the subsystem/element FMEA (failure mode and effects analysis). Potential interaction with software is examined through evaluation of the software requirements, not detailed implementation. The analysis is restricted to flight software requirements only, and excludes utility/checkout software. The BFS (backup flight system) software is considered only as necessary, and only as it differs from the primary; the basic thrust of the analysis is keyed to the primary system.

The analysis is based upon the hardware design and software requirements as they existed as of the date of the analysis. Future updates will be published as necessary to incorporate changes to either the hardware or software.

3.0 APPLICABLE DOCUMENTS.

3.1 HARDWARE/SOFTWARE INTERACTION ANALYSIS REPORT VOLUMES. The hardware/software interaction analysis results are reported on a subsystem basis, each in a separate volume. The separate volumes which make up this report are as follows:

<u>Volume</u>	<u>Subsystem</u>
I	Purge, Vent, and Drain
II	Payload Deployment and Retention
III	Payload Bay Doors
IV	Main Propulsion
V	Data Processing Subsystem
VI	Hydraulics
VII	Auxiliary Power Unit
VIII	Reaction Control
IX	Electrical Power
X	Orbital Maneuvering
XI	Environmental Control and Life Support
XII	Integrated Avionics
XIII	Electrical Power Distribution & Control
XIV	GNC (Guidance, Navigation & Control) Support
XV	Displays & Controls
XVI	Communications & Tracking
XVII	Instrumentation

3.2 REFERENCE DOCUMENTS. The primary documents used in performing the analysis included the following:

- a. SD75-SH-0016A, "Failure Mode Effects Analysis, Forward Reaction Control Subsystem," Dec 18, 1978.
- b. JSC 11174, "OV-102 Space Shuttle Systems Handbook," September 22, 1977.
- c. SD76-SH-0026A, "Functional Subsystem Software Requirements, Sequence Requirements," March, 1978.
- d. SD76-SH-0020, "Functional Subsystem Software Requirements, Displays and Controls," February 1, 1978.
- e. SD76-SH-0027D, "Functional Subsystem Software Requirements, Systems Management," October 16, 1978.
- f. MG038103, "Backup Flight System Management/Special Processes and Sequencing Program Requirements Document," December 20, 1978.
- g. SD75-SH-0010E, "Functional Subsystem Software Requirements, Redundancy Management," June 1, 1979.

4.0 DESCRIPTION.

4.1 GROUND RULES. The hardware software analysis is performed according to the following ground rules:

- a. The hardware/software analysis will be limited to investigating the software interaction with the failure modes of the hardware as delineated in the subsystem FMEA's.
- b. Software interaction will be limited to involvement of software of the onboard computers.
- c. Only failure modes of hardware with software interfaces (software monitoring and/or software control) are analyzed.
- d. The software detection must be considered with respect to each phase of the mission [prelaunch (OPS 1 only), ascent, onorbit, and entry].

4.2 ANALYSIS CHECKLIST. The basic tool for the analysis is the checklist (figure 4-1). A separate checklist is used for each failure mode analyzed. Note that the "FMEA Number" in the heading refers to the FMEA document number, not the page number on which the failure mode is treated.

The checklist consists of three sections: Body, change/retention rationale summary, and explanation/comments. Each of these sections is discussed below.

Hardware/Software Analysis Checklist

SUBSYSTEM _____
ITEM _____

FMEA NUMBER _____
FAILURE MODE _____

1. DOES THE FLIGHT SOFTWARE DETECT THIS FAILURE MODE (i.e., AUTOMATICALLY ANNUNCIATE OR TAKE ACTION IN RESPONSE)? YES ☐ NO ☐
- 1a. IF NOT, DOES THE HARDWARE PROVIDE INFORMATION THAT THE FLIGHT SOFTWARE COULD USE TO DETECT THE FAILURE? *YES ☐ NO ☐
2. ARE THE ANSWERS TO QUESTIONS 1 AND 1a CONSISTENT WITH THE FMEA EVALUATION OF IN-FLIGHT DETECTABILITY? YES ☐ *NO ☐
3. DOES THE FLIGHT SOFTWARE TAKE ACTION TO NEGATE THE EFFECTS OF THE FAILURE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? YES ☐ NO ☐
- 3a. IF NOT, DOES THE CAPABILITY EXIST FOR THE SOFTWARE TO COMPENSATE FOR THIS FAILURE MODE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? *YES ☐ NO ☐
4. AS A RESULT OF THIS FAILURE MODE, CAN THE SOFTWARE OVERSTRESS THE HARDWARE OR INDUCE ANOTHER FAILURE? *YES ☐ NO ☐
5. CAN THIS FAILURE MODE, IN COMBINATION WITH SOFTWARE LOGIC, ADVERSELY AFFECT OTHER FUNCTIONS? *YES ☐ NO ☐
6. HOW MANY OF THESE HARDWARE FAILURES CAN THE SHUTTLE TOLERATE (CONSIDER CREW ACTION AND HARDWARE/SOFTWARE OPERATION)? NOTE CHANGE TO FMEA CRITICALITY. *0 ☐ *1 ☐ 2 ☐
7. IF CREW ACTION IS REQUIRED TO RESPOND TO THIS FAILURE MODE, ARE CUES PROVIDED TO SIGNAL THE NEED FOR INTERVENTION AND THE REQUIRED CORRECTIVE ACTION? N/A ☐ YES ☐ NO ☐
8. IF THE ANSWER TO EITHER 1 OR 3 IS YES:
 - A. CAN THE BFS BE ENGAGED AFTER OCCURRENCE? YES ☐ *NO ☐
 - B. WILL BFS TOLERATE FAILURE WITHOUT LOSS OF CREW/VEHICLE? YES ☐ *NO ☐

*EXPLANATION REQUIRED (SEE BELOW)

CHANGE/RETENTION RATIONALE SUMMARY

- | | | |
|---|---|--|
| 1. <input type="checkbox"/> NO H/S ISSUES | 3. <input type="checkbox"/> NO SOFTWARE DETECTION | 5. <input type="checkbox"/> ACCEPTANCE RATIONALE BELOW |
| 2. <input type="checkbox"/> HARDWARE ACCEPTS RISK | 4. <input type="checkbox"/> DETECTION DURING CHECKOUT | 6. <input type="checkbox"/> RECOMMENDED CHANGES BELOW |

☐ FMEA CHANGE RECOMMENDED

EXPLANATION/COMMENTS:

Figure 4-1. Hardware/Software Analysis Checklist.

The questions in the checklist body are answered using the following guidelines:

a. Question 1. Will the information provided to the onboard software and the processing of that information cause annunciation of the failure and/or initiation of a corrective action in response to this failure mode?

b. Question 1a. Answer question 1a. if the answer to question 1 is "no." Information available to the software could be in the form of (1) sensor data used by onboard software but not for automatic fault detection (data used in software routines or fault detection available through callup or dedicated displays); (2) system and/or subsystem performance parameters; or (3) measurements which are downlisted. Answer "yes" if such information could be used to annunciate the failure condition or initiate responsive action. In explanation comments, specifically identify the information available for software detection.

c. Question 2. If all of the following questions are answered "no," check the "no" block and explain the difference in the explanation/comments section:

(1) Are the master measurements listed under "Failure Detectability In-flight" on the FMEA (1) used by the onboard software in detecting time critical failures (if routed to GPC), or (2) used by the onboard software in annunciating non-time critical failures via callup displays, or (3) downlisted for non-time critical failures?

(2) Are other measurements, dedicated displays, crew detection, and system/subsystem parameters available or able to detect this failure mode?

(3) If "failure detectability in-flight" specifies only software action, does the software actually initiate the corrective action as called out in the "corrective action" portion of the FMEA?

d. Question 3. The question considers only the cases wherein the software determines a failure.

e. Question 3a. Answer question 3a if the answer to 3 is "no." If the answer to 3a is "yes," call out the possible corrective action in the explanation/comments section.

f. Question 4. The question is considered for both the detected and the undetected failure. The overstress or inducement of another failure may be acceptable action. Overstress by software is improper commands, sequencing, or timing resulting in action exceeding hardware design requirements or exposing hardware to excessive environments.

g. Question 5. The question is considered for both the detected and the undetected failure. Limit adverse effects to effects directly resulting from software commands or subsequent actions resulting from erroneous inputs as a result of the failure.

h. Question 6. The hardware/software may change the method of detection and/or correction after the first or the second failure; consider this in answering the question. Determine if the software will be able to use the redundancy of the hardware. If the hardware/software interaction following the particular failure mode changes the criticality, in comparison to the FMEA, check the box provided in the summary section of the checklist.

i. Question 7. If crew action is not required to respond to the failure, check the "N/A" block. Cues which provide inputs to the crew include but are not limited to cathode-ray tube annunciation, caution and warning, visual cues, audible cues, callup and dedicated displays, subsystem status data, panel meters, etc.

j. Question 8.A and 8.B. Answer these questions only if either question 1 or 3 is "yes."

(1) Question 8.A. Consider that the failure occurs while the vehicle is being flown using the primary system. What will happen if the BFS must be engaged subsequent to the failure? Will the fact that the failure has occurred prevent the BFS from operating properly, under any conditions? A "no" answer is a potential issue (requiring explanation) only if the BFS can normally tolerate the failure (when it occurs during BFS operation).

(2) Question 8.B. Consider that the failure occurs while the vehicle is under BFS control. A "no" answer is an issue (requiring explanation) only if the BFS response differs from that for the primary system.

4.2.2 Change/Retention Rationale Summary. Each failure is assigned to one of six possible groups, based upon the answers obtained in the checklist body. Boxes are provided to indicate the category assigned. Figure 4-2 presents the criteria for group assignment.

A box is also provided to indicate that changes are required to the FMEA. The FMEA evaluation of in-flight detectability is sometimes inaccurate and requires change. In addition, other errors (e.g., incorrect criticality assignment or incorrect evaluation of redundancy screens) are occasionally noted during the analysis and are documented here.

A space is provided to detail acceptance rationale, change recommendations, or suggested FMEA changes. This space may also be used to provide a short general comment to expand the retention rationale grouping.

4.2.3 Explanation/Comments. Each question answered by checking a box identified with an asterisk is discussed in this section. The circumstances for checking a box not identified with an asterisk are discussed, and the rationale for not making such a change is presented, if applicable. This section may also be used to explain, expand, or qualify answers. Each discussion is identified with the corresponding question number.

4.3 ANALYSIS SUMMARY. The analysis results are summarized on the basis of retention rationale grouping and recommended changes/retention rationale. Figure 4-3 depicts the form utilized for this purpose. A particular retention rationale definition, acceptance rationale statement, or recommended change is listed in the left column, with the applicable failure modes listed on the right. The issue/risk is briefly described with acceptance rationale or software requirements change recommendation. The summary provides a basic overview of the total analysis results.

5.0 ANALYSIS SUMMARY SHEETS. The analysis results are summarized on the following sheets. The failure modes have been grouped by issue/retention rationale (or change), affording an overview of the results for the entire subsystem.

CHANGE/RETENTION RATIONALE

1. NO * CHECKED - NO HARDWARE/SOFTWARE ISSUES ARE APPARENT FROM THE ANALYSIS. SYSTEM IS FAIL OPERATIONAL/FAIL SAFE WITH RESPECT TO THIS FAILURE MODE UNDER CURRENT DESIGN.
2. ONLY * CHECKED ON QUESTION 6 - NO HARDWARE/SOFTWARE ISSUES ARE APPARENT FROM THE ANALYSIS. RISK HAS BEEN ACCEPTED VIA HARDWARE CIL.
3. ONLY * (YES) CHECKED ON QUESTION 1a - NO SOFTWARE DETECTION IS PROVIDED. FAILURE EFFECT IS NOT TIME CRITICAL. FAILURE MAY BE DETECTED BY OTHER MEANS OR FUNCTION IS NOT MISSION/SAFETY CRITICAL.
4. * CHECKED ON QUESTION 3a - * ON 1a MAY OR MAY NOT BE CHECKED - SOFTWARE DOES NOT TAKE CORRECTIVE ACTION FOR FAILURE. FAILURE EFFECT IS NOT TIME CRITICAL. CORRECTIVE ACTION MAY BE INITIATED BY CREW. PLANNED CHECKOUT ACTIVITIES WILL DETECT FAILURE. SYSTEM IS FAIL OPERATIONAL/FAIL SAFE WITHOUT SOFTWARE DETECTION AND CORRECTION.
5. STANDARD RETENTION RATIONALE DOES NOT APPLY. SPECIFIC RETENTION RATIONALE IS SUMMARIZED FOR THIS FAILURE.
6. ISSUES IDENTIFIED AND CHANGES ARE DESIRABLE. SPECIFIC CHANGES ARE SUMMARIZED.

NOTE: DO NOT CONSIDER ANSWER TO QUESTION 2 IN DETERMINATION OF CHANGE/RETENTION RATIONALE SUMMARY CODE. CONSIDER RESPONSES TO BOTH QUESTION 2 AND 6 IN DETERMINING WHETHER AN FMEA CHANGE IS REQUIRED.

Figure 4-2. Change/Retention Rationale

HARDWARE/SOFTWARE ANALYSIS SUMMARY

SUBSYSTEM _____

FMEA _____

ANALYSIS RESULT

ITEM/FAILURE MODE

Figure 4-3. Hardware/Software Analysis Summary

HARDWARE/SOFTWARE ANALYSIS SUMMARY

SUBSYSTEM Forward Reaction Control

FMEA SD75-SH-0016A

ANALYSIS RESULT	ITEM/FAILURE MODE
HARDWARE ACCEPTS RISK	<p>Helium Storage Tank - Rupture (03-2F-101010-1)</p> <p>Helium Feedline - External Leakage (03-2F-101013-1)</p> <p>Quick Fill Disconnect, He - Fails Open, Cap Leaks (03-2F-101070-1)</p> <p>Test Quick Disconnect, Propellant - Ext. Leakage/Flight (03-2F-101090-1)</p> <p>Propellant Line Flex Assy. - External Leakage (03-2F-102106-1)</p> <p>Feedline and Fittings - External Leakage (03-2F-102108-1)</p> <p>AC Motor Operated Valve (Tank) - Fails Closed (03-2F-102120-1)</p> <p>Quick Disconnect - External Leakage (03-2F-102150-1)</p> <p>DC Solenoid Operated Valve - Fails Closed - Premature Operation (03-2F-102170-1)</p> <p>Tank Assembly and Propellant Acquisition Device - Small Crack - External Leakage (03-2F-111110-2)</p> <p>Tank Assembly and Propellant Acquisition Device - Restricted Flow (03-2F-111110-3)</p> <p>Tank Assembly and Propellant Acquisition Device - Loss of Gas in Propellant Acquisition Device (03-2F-111110-4)</p> <p>Flex Line and Fittings - External Leakage (03-2F-121308-1)</p> <p>Thrust Chamber - Burn Through (03-2F-121312-1)</p> <p>Nozzle Extension - Burn-Through (03-2F-121313-1)</p> <p>Vernier Thruster - Erratic Operation (03-2F-131310-3)</p> <p>Vernier Thruster - Burn-Through (03-2F-131310-4)</p> <p>Helium Pressure Regulator - Fails Closed (03-2F-101030-2)</p> <p>Tank Assembly and Propellant Acquisition Device - Large Rupture (03-2F-111110-1)</p> <p>Purge Quick Disconnect, Propellant - External Leakage During Flight (03-2F-101080-1)</p> <p>Helium Quad Check Valve - Fails Closed (03-2F-101095-2)</p> <p>Vernier Thruster - Loss of Output (03-2F-131310-1)</p>

HARDWARE/SOFTWARE ANALYSIS SUMMARY

SUBSYSTEM Forward Reaction Control

FMEA SD75-SH-0016A

ANALYSIS RESULT	ITEM/FAILURE MODE
NO HARDWARE/SOFTWARE ISSUES	<p>D.C. Solenoid Valve - Fails to Close (03-2F-101020-3)</p> <p>D.C. Solenoid Valve - Fails Closed (03-2F-101020-4)</p> <p>Helium Pressure Regulator - Fails Open (03-2F-101030-1)</p> <p>Relief Valve - External Leakage Overboard (03-2F-101060-1)</p> <p>Relief Valve - Burst Disc Ruptures (03-2F-101060-2)</p> <p>Relief Valve - Fails to Burst (03-2F-101060-3)</p> <p>Relief Valve - Opens Low (03-2F-101060-4)</p> <p>Relief Valve - Fails to Open (03-2F-101060-5)</p> <p>Helium Quad Check Valve - Fails Open (03-2F-101095-1)</p> <p>Injector Plate - Mixture (03-2F-121311-1)</p>

HARDWARE/SOFTWARE ANALYSIS SUMMARY

SUBSYSTEM Forward Reaction Control

FMEA SD75-SH-0016A

ANALYSIS RESULT	ITEM/FAILURE MODE
OUT OF SCOPE - GROUND ONLY	<p>Manual Valve - Fails Closed or Open (03-2F-101050-1)</p> <p>Manual Valve - Internal Leakage (03-2F-101050-2)</p> <p>Quick Fill Disconnect, He. - Fails Closed/Ground OPS (03-2F-101070-2)</p> <p>Purge Quick Disconnect, Propellant - Fails Closed/Ground OPS. (03-2F-101080-2)</p> <p>Test Quick Disconnect, Propellant - Fails Closed/Ground Ops (03-2F-101090-2)</p> <p>Quick Disconnect - Fails Closed/Ground Ops. (03-2F-102150-2)</p>

6.0 ANALYSIS CHECKLIST SHEETS

Following are the analysis checklist sheets for each failure mode evaluated.

. HARDWARE/SOFTWARE ANALYSIS CHECKLIST 03-2F-101010-1

SUBSYSTEM Fwd Reaction Control

FMEA NUMBER SD75-SH-0016A

ITEM Helium Storage Tank

FAILURE MODE Rupture

1. DOES THE FLIGHT SOFTWARE DETECT THIS FAILURE MODE (i.e., AUTOMATICALLY ANNUNCIATE OR TAKE ACTION IN RESPONSE)? YES ☒ NO ☐
- 1a. IF NOT, DOES THE HARDWARE PROVIDE INFORMATION THAT THE FLIGHT SOFTWARE COULD USE TO DETECT THE FAILURE? *YES ☐ NO ☐
2. ARE THE ANSWERS TO QUESTIONS 1 AND 1a CONSISTENT WITH THE FMEA EVALUATION OF IN-FLIGHT DETECTABILITY? YES ☒ *NO ☐
3. DOES THE FLIGHT SOFTWARE TAKE ACTION TO NEGATE THE EFFECTS OF THE FAILURE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? YES ☐ NO ☒
- 3a. IF NOT, DOES THE CAPABILITY EXIST FOR THE SOFTWARE TO COMPENSATE FOR THIS FAILURE MODE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? *YES ☐ NO ☒
4. AS A RESULT OF THIS FAILURE MODE, CAN THE SOFTWARE OVERSTRESS THE HARDWARE OR INDUCE ANOTHER FAILURE? *YES ☐ NO ☒
5. CAN THIS FAILURE MODE, IN COMBINATION WITH SOFTWARE LOGIC, ADVERSELY AFFECT OTHER FUNCTIONS? *YES ☐ NO ☒
6. HOW MANY OF THESE HARDWARE FAILURES CAN THE SHUTTLE TOLERATE (CONSIDER CREW ACTION AND HARDWARE/SOFTWARE OPERATION)? NOTE CHANGE TO FMEA CRITICALITY. *0 ☒ *1 ☐ 2 ☐
7. IF CREW ACTION IS REQUIRED TO RESPOND TO THIS FAILURE MODE, ARE CUES PROVIDED TO SIGNAL THE NEED FOR INTERVENTION AND THE REQUIRED CORRECTIVE ACTION? N/A ☐ YES ☒ NO ☐
8. IF THE ANSWER TO EITHER 1 OR 3 IS YES:
 - A. CAN THE BFS BE ENGAGED AFTER OCCURRENCE? YES ☐ *NO ☐
 - B. WILL BFS TOLERATE FAILURE WITHOUT LOSS OF CREW/VEHICLE? YES ☐ *NO ☐

*EXPLANATION REQUIRED (SEE BELOW)

CHANGE/RETENTION RATIONALE SUMMARY

- | | | |
|--|---|--|
| 1. <input type="checkbox"/> NO H/S ISSUES | 3. <input type="checkbox"/> NO SOFTWARE DETECTION | 5. <input type="checkbox"/> ACCEPTANCE RATIONALE BELOW |
| 2. <input checked="" type="checkbox"/> HARDWARE ACCEPTS RISK | 4. <input type="checkbox"/> DETECTION DURING CHECKOUT | 6. <input type="checkbox"/> RECOMMENDED CHANGES BELOW |

☐ FMEA CHANGE RECOMMENDED

EXPLANATION/COMMENTS:

1. GAX will give a class 2 alert upon sensing an out-of-tolerance condition. (<500 psi) Gross leak detection will give a class 2 alert.

8. Backup flight system same as primary.

SHUTTLE FAILURE MODE AND EFFECTS ANALYSIS - ORBITER 102

SUBSYSTEM : FWD - REACTION CONTROL FMEA NO 03-2F -101010-1 REV: 12/18/7
 .ASSEMBLY : PRESSURIZATION ABORT: CRIT. FUNC: 1
 .P/N RI : MC292-0082-0031/-0032 CRIT. HWD: 1
 .P/N VENDOR: BLD-999040 MISSIONS: HF VF X FF UF SM
 .QUANTITY : 2 PHASE(S): PL X LO X GO X DO X LS
 . : ONE REQ'D PER EACH NUMBER OF SUCCESS PATHS REMAINING
 . : PROPELLANT TANK AFTER FIRST FAILURE: C
 . REDUNDANCY SCREEN: A-N/A B-N/A C-N/A
 .FAILURE DETECTABLE IN FLIGHT? YES TIME TO EFFECT:
 .PRESSURE INDICATION V42P-1110C IMMEDIATE/SECONDS
 .1113C REFERENCE DOCUMENTS:
 . MJ070-C001-018
 .GROUND TURNAROUND?.....YES S072-SH-0103-2
 .SAME AS FLIGHT VS70-421001
 .
 .
 .
 .

PREPARED BY:

DES

REL

J TAGGART

R DIEHL

APPROVED BY:

DES

REL

.ITEM: TANK
 . HELIUM STORAGE, FILAMENT WOUND.
 .FUNCTION:
 . TO STORE HELIUM AT A MAX WORKING PRESSURE OF 4000 PSI FOR
 PRESSURIZATION OF THE FWD RCS MODULE PROPELLANT SUPPLY SYSTEM. TANK
 CONSISTS OF A DOUBLE MELT T1 LINER WITH DUPONT 49 FIBER AND EPOXY RESIN
 BONDING OVER WRAP.
 .FAILURE MODE: RUPTURE, EXTERNAL LEAK (S)
 . RUPTURE - LARGE CRACK WHICH PROPAGATES AROUND TANK IMMEDIATELY.
 LEAKAGE - FRACTURE WHICH DOES NOT PROPAGATE TO RUPTURE.
 .CAUSE(S):
 . VIBRATION, STRESS CORROSION, TEMP. RISE, FATIGUE, INADVERTENT
 OVER-PRESSURIZATION (GROUND OPS).
 .EFFECT(S): ON (A)SUBSYSTEM (B)INTERFACES (C)MISSION (D)CREW/VEHICLE:
 . (A) LOSS OF PRESSURIZATION TO FUEL OR OXIDIZER. (B) EXPLOSIVE
 . EXPANSION OF HELIUM WITHIN RCS MODULE. (C) POTENTIAL LOSS OF
 MISSION-ABORT DECISION DEPENDANT ON EXTENT OF DAMAGE. (D) POTENTIAL
 LOSS OF CREW/VEHICLE.
 .CORRECTING ACTION:
 . NONE AVAILABLE EXCEPT POSSIBLE RESCUE IF VEHICLE STILL INTACT.
 .REMARKS/HAZARDS:
 . HAZARD OF SHRAPNEL PROPAGATION, HOWEVER, UTILIZATION OF FILAMENT WOUND
 TANK MINIMIZES OR ELIMINATES THIS HAZARD. ADDITIONAL HAZARD OF MODULE
 OVER PRESSURIZATION STILL EXISTS. NO REDUNDANCY PROVIDED FOR THIS ITEM
 - REFERENCE HAZARD IYXX-0302-02.

ORIGINAL PAGE IS
 OF POOR QUALITY

SHUTTLE CRITICAL ITEMS LIST - ORBITER 102

SUBSYSTEM : FWD - REACTION CONTROL FMEA NO 03-2F -101010-1 REV:11/09/79
 .ASSEMBLY : PRESSURIZATION ABORT: CRIT. FUNC: 1
 .P/N RI : 4C282-0082-0031/-0032 CRIT. HDW: 1
 .P/N VENDOR: BLD-999040 MISSIONS: HF VF X FF OF SM
 .QUANTITY : 2 PHASE(S): PL X LO X OO X DO X LS
 . : ONE REQ'D PER EACH
 . : PROPELLANT TANK

REDUNDANCY SCREEN: A-N/A S-N/A C-N/A

PREPARED BY:
 .DES J TAGGART
 .REL R DIEHL

APPROVED BY:
 DES *[Signature]*
 REL *[Signature]* 11/15/78

APPROVED BY: NASA
 SSM *[Signature]*
 REL *[Signature]*

ITEM: TANK

. HELIUM STORAGE, FILAMENT WOUND.

FUNCTION:

. TO STORE HELIUM AT A MAX WORKING PRESSURE OF 4000 PSI FOR PRESSURIZATION OF THE FWD RCS MODULE PROPELLANT SUPPLY SYSTEM. TANK CONSISTS OF A DOUBLE MELT TI LINER WITH DUPONT 49 FIBER AND EPOXY RESIN BONDING OVER WRAP.

.FAILURE MODE: RUPTURE, EXTERNAL LEAK (S)

. RUPTURE - LARGE CRACK WHICH PROPOGATES AROUND TANK IMMEDIATELY. LEAKAGE - FRACTURE WHICH DOES NOT PROPOGATE TO RUPTURE.

CAUSE(S):

. VIBRATION, STRESS CORROSION, TEMP. RISE, FATIGUE, INADVERTENT OVER-PRESSURIZATION (GROUND OPS).

.EFFECT(S): ON (A)SUBSYSTEM (B)INTERFACES (C)MISSION (D)CREW/VEHICLE:

. (A) LOSS OF PRESSURIZATION TO FUEL OR OXIDIZER. (B) EXPLOSIVE EXPANSION OF HELIUM WITHIN RCS MODULE. (C) POTENTIAL LOSS OF MISSION-ABORT DECISION DEPENDANT ON EXTENT OF DAMAGE. (D) POTENTIAL LOSS OF CREW/VEHICLE.

.DISPOSITION & RATIONALE (A)DESIGN (B)TEST (C)INSPECTION (D)FAILURE HISTORY:

. (A) FILAMENT WOUND TANKS ARE DESIGNED TO LEAK BEFORE RUPTURE WHICH LIMITS FAILURE PROPAGATION DUE TO SCHRAPNEL. INCREASED STRAIN CAPABILITY IS PROVIDED BY THE COMPRESSIVE LOAD ON AN UNPRESSURIZED LINER. THE FACTOR OF SAFETY IS 1.5 X MAX WORKING PRESSURE OF 4000 PSIG. DUAL SEALS ARE PROVIDED AT TANK FLANGE. (B) TANKS ARE SUBJECTED TO PROOF PRESSURE (1.1X WORKING PRESSURE) DURING ACCEPTANCE TESTING. QUAL TESTS INCLUDE 1000 PRESSURE CYCLES EQUAL TO 4 TIMES LIFE REQUIREMENT, 90 DAY CREEP TEST AT MAX WORKING PRESSURE PLUS RANDOM VIBRATION AT ANTICIPATED MISSION LEVELS FOR 48 MIN IN EACH AXIS. (C) IN PROCESS INSPECTION INCLUDES RADIO GRAPHIC INSPECTION OF WELDS & FLUORESCENT PENETRATION INSPECTION FOR SURFACE FLAWS. TURNAROUND CYCLE FOR EVIDENCE OF RUPTURE. AUDIT CONDUCTED 3/9/78 VERIFIED SUPPLIER RECEIVING INSPECTION CONTROLS RAW MATERIAL AND PURCHASED COMPONENTS AND IN-HOUSE INSPECTION CONTROLS CORROSION PROTECTIVE PROVISIONS, TEST HANDLING STORAGE ENVIRONMENTS, MEASUREMENT STANDARDS, TEST EQUIPMENT, NDE TESTING, PARTS PROTECTION, MFG PROCESSES AND FINISHES. CHEMICAL ETCHING, X-RAY AND PROOF TEST OF LINER AND MECHANICAL PROPERTIES AFTER HEAT TREAT ALSO VERIFIED BY INSPECTION. (D) NO HISTORY AVAILABLE. TANK IS BEING DEVELOPED FOR SHUTTLE PROGRAM.

. HARDWARE/SOFTWARE ANALYSIS CHECKLIST 03-2F-101013-1

SUBSYSTEM Fwd Reaction Control

FMEA NUMBER SD75-SH-0016A

ITEM Helium Feedline

FAILURE MODE External Leakage

1. DOES THE FLIGHT SOFTWARE DETECT THIS FAILURE MODE (i.e., AUTOMATICALLY ANNUNCIATE OR TAKE ACTION IN RESPONSE)? YES ☒ NO ☐
- 1a. IF NOT, DOES THE HARDWARE PROVIDE INFORMATION THAT THE FLIGHT SOFTWARE COULD USE TO DETECT THE FAILURE? *YES ☐ NO ☐
2. ARE THE ANSWERS TO QUESTIONS 1 AND 1a CONSISTENT WITH THE FMEA EVALUATION OF IN-FLIGHT DETECTABILITY? YES ☒ *NO ☐
3. DOES THE FLIGHT SOFTWARE TAKE ACTION TO NEGATE THE EFFECTS OF THE FAILURE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? YES ☐ NO ☒
- 3a. IF NOT, DOES THE CAPABILITY EXIST FOR THE SOFTWARE TO COMPENSATE FOR THIS FAILURE MODE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? *YES ☐ NO ☒
4. AS A RESULT OF THIS FAILURE MODE, CAN THE SOFTWARE OVERSTRESS THE HARDWARE OR INDUCE ANOTHER FAILURE? *YES ☐ NO ☒
5. CAN THIS FAILURE MODE, IN COMBINATION WITH SOFTWARE LOGIC, ADVERSELY AFFECT OTHER FUNCTIONS? *YES ☐ NO ☒
6. HOW MANY OF THESE HARDWARE FAILURES CAN THE SHUTTLE TOLERATE (CONSIDER CREW ACTION AND HARDWARE/SOFTWARE OPERATION)? NOTE CHANGE TO FMEA CRITICALITY. *0 ☒ *1 ☐ 2 ☐
7. IF CREW ACTION IS REQUIRED TO RESPOND TO THIS FAILURE MODE, ARE CUES PROVIDED TO SIGNAL THE NEED FOR INTERVENTION AND THE REQUIRED CORRECTIVE ACTION? N/A ☐ YES ☒ NO ☐
8. IF THE ANSWER TO EITHER 1 OR 3 IS YES:
 - A. CAN THE BFS BE ENGAGED AFTER OCCURRENCE? YES ☒ *NO ☐
 - B. WILL BFS TOLERATE FAILURE WITHOUT LOSS OF CREW/VEHICLE? YES ☒ *NO ☐

*EXPLANATION REQUIRED (SEE BELOW)

CHANGE/RETENTION RATIONALE SUMMARY

- | | | |
|--|---|--|
| 1. <input type="checkbox"/> NO H/S ISSUES | 3. <input type="checkbox"/> NO SOFTWARE DETECTION | 5. <input type="checkbox"/> ACCEPTANCE RATIONALE BELOW |
| 2. <input checked="" type="checkbox"/> HARDWARE ACCEPTS RISK | 4. <input type="checkbox"/> DETECTION DURING CHECKOUT | 6. <input type="checkbox"/> RECOMMENDED CHANGES BELOW |

☐ FMEA CHANGE RECOMMENDED

EXPLANATION/COMMENTS:

1. GAX will give a class 2 alert upon sensing an out-of-tolerance condition. (<500 psi)
Gross leak detection will give a class 2 alert.

8. Backup flight system same as primary.

SHUTTLE FAILURE MODE AND EFFECTS ANALYSIS - ORBITER 102

SUBSYSTEM : FWD - REACTION CONTROL FMEA NO C3-2F -101013-1 REV: 11/09/7.
 .ASSEMBLY : PRESSURIZATION HELIUM - ABORT: CRIT. FUNC: 1
 .P/N R1 : VC70-421701 CRIT. HND: 1
 .P/N VENDOP: MISSIONS: HF VF X FF CF SM
 .QUANTITY : 2 PHASE(S): PL X LG X GO X DO X LS X
 . : ONE SET PER PROPELLANT NUMBER OF SUCCESS PATHS REMAINING
 . : AFTER FIRST FAILURE: G
 . REDUNDANCY SCREEN: A-N/A B-N/A C-N/A
 .FAILURE DETECTABLE IN FLIGHT? . YES TIME TO EFFECT:
 .HELIUM TANK PRESSURE DRO P AT OFF-NOMINAL RATE; IMMEDIATE
 .V42P-1110C;1112C;1113C; 1114C REFERENCE DOCUMENTS:
 .GROUND TURNAROUND?.....YES MJ070-0001-01b
 .SAME AS FLIGHT INSTRUMENTATION SD72-SH-0103-2
 . VS70-421001
 .
 .
 .
 . PREPARED BY: APPROVED BY:
 . DES A SIEGELIN DES _____
 . REL R DIEHL REL _____
 .
 .
 .ITEM: HELIUM FEED LINE AND
 . FLUID FITTINGS.
 .FUNCTION:
 . TO PROVIDE FEED LINE FROM HELIUM TANKS TO HELIUM
 REGULATION/PRESSURATION SYSTEM AND TO PROPELLANT
 TANKS.
 .FAILURE MODE: EXTERNAL LEAKAGE (S)
 .
 .CAUSE(S):
 . MECHANICAL SHOCK, VIBRATION/FATIGUE, IMPROPER INSTALLATION (WELD).
 FLUID FITTING SEAL FAILURE.
 .EFFECT(S): ON (A)SUBSYSTEM (B)INTERFACES (C)MISSION (D)CREW/VEHICLE:
 . (A) LOSS OF HELIUM SUPPLY IF NOT ISOLATABLE. (IE. IF UPSTREAM OF
 . SOLENOID VALVE). (B) POTENTIAL OVERPRESSURIZATION OF FORWARD MODULE
 FROM GROSS LEAK. (C,D) POTENTIAL MODULE DAMAGE RESULTING IN LOSS OF
 . MISSION/CREW/VEHICLE IF GROSS LEAK OCCURS DURING CRITICAL MANEUVERS.
 .CORRECTING ACTION:
 . INITIATE ABORT. CHECK VALVES MAINTAIN PROPELLANT TANK RESIDUAL GAS
 PRESSURE TO ALLOW POTENTIAL PLGW DOWN MODE UTILIZATION.
 .REMARKS/HAZARDS:
 . NO REDUNDANCY PROVIDED FOR LINES. IF LEAK RATE IS EXCESSIVE PRESSURE
 BUILD-UP IN MODULE MAY RESULT IN HAZARD. SEE HAZARD IYXX-0302-02.

ORIGINAL PAGE IS
OF POOR QUALITY.

SHUTTLE CRITICAL ITEMS LIST - ORBITER 102

```

SUBSYSTEM : FWD - REACTION CONTROL      FMEA NO 03-2F - 101013-1      REV: 11/09/77
ASSEMBLY  : PRESSURIZATION HELIUM -     ABORT:                      CRIT. FUNC: 1
P/N RI    : V070-421701                 CRIT. HDW: 1
P/N VENDOR:                             MISSIONS:  HF    VF X  FF    CF    SM
QUANTITY  : 2                           PHASE(S):  PL X  LO X  CO X  DO X  LS X
: ONE SET PER PROPELLANT

```

REDUNDANCY SCREEN: A-N/A B-N/A C-N/A

PREPARED BY: DES A SIEGELIN
 REL R DIEHL

APPROVED BY: DES [Signature]
 REL C. E. [Signature] 12/5/76

APPROVED BY (NASA): [Signature]
 SSN [Signature]
 REL [Signature]

APPROVED WITH CHANGES
See Section 13.0

- ITEM: HELIUM FEED LINE AND
- FLUID FITTINGS.

• FUNCTION:

- TO PROVIDE FEED LINE FROM HELIUM TANKS TO HELIUM REGULATION/PRESSURATION SYSTEM AND TO PROPELLANT TANKS.

•FAILURE MODE: EXTERNAL LEAKAGE (S)

• CAUSE(S):

- MECHANICAL SHOCK, VIBRATION/FATIGUE, IMPROPER INSTALLATION (WELD).
FLUID FITTING SEAL FAILURE.

•EFFECT(S): ON (A)SUBSYSTEM (B)INTERFACES (C)MISSION (D)CREW/VEHICLE:

- (A) LOSS OF HELIUM SUPPLY IF NOT ISOLATABLE. (IE. IF UPSTREAM OF SOLENOID VALVE). (B) POTENTIAL OVERPRESSURIZATION OF FORWARD MODULE FROM GROSS LEAK. (C,D) POTENTIAL MODULE DAMAGE RESULTING IN LOSS OF MISSION/CREW/VEHICLE IF GROSS LEAK OCCURS DURING CRITICAL MANEUVERS.

•DISPOSITION & RATIONALE (A)DESIGN (B)TEST (C)INSPECTION (D)FAILURE HISTORY:

(A) FACTOR OF SAFETY OF 4.0 WILL MINIMIZE FAILURE POTENTIAL. FLUID FITTINGS HAVE DUAL SEALS. WELD CONSTRUCTION REDUCES JOINTS AND POSSIBLE LEAK PATHS. FASTENING CLAMPS AND TUBE BEND DESIGN ALLOWS DEGREE OF MOVEMENT WHICH HELPS PREVENTING LEAKS. (B) POST INSTALLATION TEST AND OPERATIONAL CHECKOUTS WILL VERIFY SYSTEM INTEGRITY. ALL LINES SUBJECTED TO 1.25 PROOF TEST. (C) IN PROCESS INSPECTION INCLUDES NDT & LEAK CHECKS DURING INSTALLATION. TURNAROUND INSPECTION INCLUDES MONITORING FUNCTIONAL TESTS DURING PRESSURIZATION CYCLE FOR EVIDENCE OF LEAKS. WHERE ACCESSABLE VISUALLY INSPECT FOR DAMAGE. HARDWARE INSPECTION IN ACCORDANCE WITH PLANNING RQMTS APPROVED BY NASA. (D) MINOR FAILURE HISTORY-CORROSION AND FAB PROBLEMS REPORTED DURING APOLLO PROGRAM AND CORRECTED.

WITH APPLICABLE TMO/TPC REQUIREMENT. HARDWARE INSPECTION IN ACCORDANCE WITH PLANNING RQMTS APPROVED BY NASA. (D) MINOR FAILURE HISTORY-CORROSION AND FAB PROBLEMS REPORTED DURING APOLLO PROGRAM AND CORRECTED.

. HARDWARE/SOFTWARE ANALYSIS CHECKLIST 03-2F-101020-3

SUBSYSTEM Fwd Reaction Control

FMEA NUMBER SD75-SH-0016A

ITEM D. C. Solenoid Valve - Helium

FAILURE MODE Fails to Close

1. DOES THE FLIGHT SOFTWARE DETECT THIS FAILURE MODE (i.e., AUTOMATICALLY ANNUNCIATE OR TAKE ACTION IN RESPONSE)? YES ☐ NO ☒
- 1a. IF NOT, DOES THE HARDWARE PROVIDE INFORMATION THAT THE FLIGHT SOFTWARE COULD USE TO DETECT THE FAILURE? *YES ☐ NO ☐
2. ARE THE ANSWERS TO QUESTIONS 1 AND 1a CONSISTENT WITH THE FMEA EVALUATION OF IN-FLIGHT DETECTABILITY? YES ☐ *NO ☒
3. DOES THE FLIGHT SOFTWARE TAKE ACTION TO NEGATE THE EFFECTS OF THE FAILURE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? YES ☐ NO ☒
- 3a. IF NOT, DOES THE CAPABILITY EXIST FOR THE SOFTWARE TO COMPENSATE FOR THIS FAILURE MODE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? *YES ☐ NO ☒
4. AS A RESULT OF THIS FAILURE MODE, CAN THE SOFTWARE OVERSTRESS THE HARDWARE OR INDUCE ANOTHER FAILURE? *YES ☐ NO ☒
5. CAN THIS FAILURE MODE, IN COMBINATION WITH SOFTWARE LOGIC, ADVERSELY AFFECT OTHER FUNCTIONS? *YES ☐ NO ☒
6. HOW MANY OF THESE HARDWARE FAILURES CAN THE SHUTTLE TOLERATE (CONSIDER CREW ACTION AND HARDWARE/SOFTWARE OPERATION)? NOTE CHANGE TO FMEA CRITICALITY. *0 ☐ *1 ☐ 2 ☒
7. IF CREW ACTION IS REQUIRED TO RESPOND TO THIS FAILURE MODE, ARE CUES PROVIDED TO SIGNAL THE NEED FOR INTERVENTION AND THE REQUIRED CORRECTIVE ACTION? N/A ☐ YES ☒ NO ☐
8. IF THE ANSWER TO EITHER 1 OR 3 IS YES:
 - A. CAN THE BFS BE ENGAGED AFTER OCCURRENCE? YES ☒ *NO ☐
 - B. WILL BFS TOLERATE FAILURE WITHOUT LOSS OF CREW/VEHICLE? YES ☒ *NO ☐

*EXPLANATION REQUIRED (SEE BELOW)

CHANGE/RETENTION RATIONALE SUMMARY

- | | | |
|--|---|--|
| 1. <input checked="" type="checkbox"/> NO H/S ISSUES | 3. <input type="checkbox"/> NO SOFTWARE DETECTION | 5. <input type="checkbox"/> ACCEPTANCE RATIONALE BELOW |
| 2. <input type="checkbox"/> HARDWARE ACCEPTS RISK | 4. <input type="checkbox"/> DETECTION DURING CHECKOUT | 6. <input type="checkbox"/> RECOMMENDED CHANGES BELOW |

In-Flight Detectability

☒ FMEA CHANGE RECOMMENDED

EXPLANATION/COMMENTS:

1. Switch scan will detect failure in OPS-2 only and only on demand.
May not be used on STS-1.

SHUTTLE FAILURE MODE AND EFFECTS ANALYSIS - ORBITER 102

SUBSYSTEM : FWD - REACTION CONTROL FMEA NO 03-2F -101020-3 REV:03/06/7.
 .ASSEMBLY : PRESSURIZATION ABORT: CRIT. FUNC:
 .P/N RI : MC284-C419-0011/-0012 CRIT. HWB: 3
 .P/N VENDOR: 75835 MISSIONS: HF VF X HF LF SM
 .QUANTITY : 4 PHASE(S): PL X LO X DO X DO X LS
 . : TWO REQ'D PER PRESSURANT NUMBER OF SUCCESS PATHS REMAINING
 . : FEED ASSEMBLY AFTER FIRST FAILURE: 2
 . REDUNDANCY SCREEN: A-PASS B-PASS C-PASS
 . FAILURE DETECTABLE IN FLIGHT? YES TIME TO EFFECT:
 . HELIUM TANK PRESS, V42P 1110,1112,1113,1114, SECONDS
 . AND PRESS LINE; V42P1115, 1116 AND POSITION IND. REFERENCE DOCUMENTS:
 . 1120X,1122X,1124X,1126X VL70-00249
 . GROUNDED TURNAROUND?.....YES MJ070-0001-016
 . SAME AS FLIGHT INSTR. SU72-SH-0103-2
 . VS70-421001

PREPARED BY:

DES
REL

R BURKHART
R DIEHL

APPROVED BY:

DES
REL

.ITEM: VALVE,D.C. SOLENOID

. OPERATED, HIGH PRESSURE. HE (2600-4000 PSIA) SOLENOID ACTUATED,
 51-STABLE, (1/2") (LV 101/102/103/104).

.FUNCTION:

. THESE VALVES ARE UTILIZED TO CONTROL HELIUM PRESSURIZATION OF THE RCS
 MODULE. IN THE OPEN POSITION A FLOW PATH IS PROVIDED FROM THE HELIUM
 SUPPLY TANK(S) TO THE REGULATOR(S). TWO PARALLEL PATHS ARE PROVIDED
 FOR FUEL AND OXIDIZER. ONE PATH IS NORMALLY OPEN PER TANK. THE VALVE
 IS CLOSED AND PARALLEL VALVE OPENED SUBSEQUENT TO A DOWN STREAM
 FAILURE.

.FAILURE MODE: FAILS TO CLOSE (F)

. WHEN COMMANDED TO ISOLATE DOWNSTREAM FAILURES

.CAUSE(S):

. CONTAMINATION, VIBRATION, LOSS OF ELECTRICAL INPUT, IMPROPER OPENING
 ACTUATION, PIECE PART FAILURE.

.EFFECT(S): ON (A)SUBSYSTEM (B)INTERFACES (C)MISSION (D)CREW/VEHICLE:

. (A,C,D) NO EFFECT, VALVE IS FUNCTIONED (CLOSED) ONLY SUBSEQUENT TO A
 . 2ND ORDER FAILURE. (B) NO EFFECT, DOES NOT INTERFACE WITH OTHER
 SUBSYSTEMS.

.CORRECTING ACTION:

. NONE -

.REMARKS/HAZARDS:

. NONE.

ORIGINAL PAGE IS
OF POOR QUALITY

. HARDWARE/SOFTWARE ANALYSIS CHECKLIST 03-2F-101020-4

SUBSYSTEM Fwd Reaction Control FMEA NUMBER SD75-SH-0016A

ITEM D. C. Solenoid Valve - Helium FAILURE MODE Fails Closed

1. DOES THE FLIGHT SOFTWARE DETECT THIS FAILURE MODE (i.e., AUTOMATICALLY ANNUNCIATE OR TAKE ACTION IN RESPONSE)? YES ☒ NO ☐
- 1a. IF NOT, DOES THE HARDWARE PROVIDE INFORMATION THAT THE FLIGHT SOFTWARE COULD USE TO DETECT THE FAILURE? *YES ☐ NO ☐
2. ARE THE ANSWERS TO QUESTIONS 1 AND 1a CONSISTENT WITH THE FMEA EVALUATION OF IN-FLIGHT DETECTABILITY? YES ☒ *NO ☐
3. DOES THE FLIGHT SOFTWARE TAKE ACTION TO NEGATE THE EFFECTS OF THE FAILURE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? YES ☐ NO ☒
- 3a. IF NOT, DOES THE CAPABILITY EXIST FOR THE SOFTWARE TO COMPENSATE FOR THIS FAILURE MODE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? *YES ☐ NO ☒
4. AS A RESULT OF THIS FAILURE MODE, CAN THE SOFTWARE OVERSTRESS THE HARDWARE OR INDUCE ANOTHER FAILURE? *YES ☐ NO ☒
5. CAN THIS FAILURE MODE, IN COMBINATION WITH SOFTWARE LOGIC, ADVERSELY AFFECT OTHER FUNCTIONS? *YES ☐ NO ☒
6. HOW MANY OF THESE HARDWARE FAILURES CAN THE SHUTTLE TOLERATE (CONSIDER CREW ACTION AND HARDWARE/SOFTWARE OPERATION)? NOTE CHANGE TO FMEA CRITICALITY. *0 ☐ *1 ☐ 2 ☒
7. IF CREW ACTION IS REQUIRED TO RESPOND TO THIS FAILURE MODE, ARE CUES PROVIDED TO SIGNAL THE NEED FOR INTERVENTION AND THE REQUIRED CORRECTIVE ACTION? N/A ☐ YES ☒ NO ☐
8. IF THE ANSWER TO EITHER 1 OR 3 IS YES:
 - A. CAN THE BFS BE ENGAGED AFTER OCCURRENCE? YES ☒ *NO ☐
 - B. WILL BFS TOLERATE FAILURE WITHOUT LOSS OF CREW/VEHICLE? YES ☒ *NO ☐

*EXPLANATION REQUIRED (SEE BELOW)

CHANGE/RETENTION RATIONALE SUMMARY

- | | | |
|--|---|--|
| 1. <input type="checkbox"/> NO H/S ISSUES | 3. <input type="checkbox"/> NO SOFTWARE DETECTION | 5. <input type="checkbox"/> ACCEPTANCE RATIONALE BELOW |
| 2. <input checked="" type="checkbox"/> HARDWARE ACCEPTS RISK | 4. <input type="checkbox"/> DETECTION DURING CHECKOUT | 6. <input type="checkbox"/> RECOMMENDED CHANGES BELOW |

☐ FMEA CHANGE RECOMMENDED

EXPLANATION/COMMENTS:

1. Switch scan will detect failure in OPS-2 only and only on demand.
May not be used on STS-1.

SHUTTLE FAILURE MODE AND EFFECTS ANALYSIS - ORBITER 102

SUBSYSTEM : FWD - REACTION CONTROL FMEA NO 03-2F -101020-4 REV:12/08/71
 .ASSEMBLY : PRESSURIZATION ABORT: CRIT. FUNC: 1R
 .P/N RI : MC284-0419-0011/-0012 CRIT. HWD: 2
 .P/N VENDOR: 73835 MISSIONS: HF VF X HF GF SM
 .QUANTITY : 4 PHASE(S): PL X LC X CG X DD X LS
 . : TWO REQ'D PER PRESSURANT NUMBER OF SUCCESS PATHS REMAINING
 . : FEED ASSEMBLY AFTER FIRST FAILURE: 1
 . REDUNDANCY SCREEN: A-PASS B-PASS C-FAIL
 .FAILURE DETECTABLE IN FLIGHT? YES TIME TO EFFECT:
 .MONITOR TANK PRESSURE AND POSITION INDICATION MINUTES
 .V42X-1120X,1122X,1124X, 1126X REFERENCE DOCUMENTS:
 . VLT0-008249
 .GROUND TURNAROUND?.....YES MJ070-0001-018
 .SAME AS FLIGHT INSTR. SD72-SH-0103-2
 . VS70-421001

PREPARED BY:

DES
REL

R BURKHART
R DIEHL

APPROVED BY:

DES
REL

.ITEM: VALVE, D.C. SOLENOID (Helium - PRESSURIZATION SYSTEM)

. OPERATED, HIGH PRESSURE. HE (3600-4000 PSIA) SOLENOID ACTUATED, BI-STABLE, (1/2") (LV 101/102/103/104).

.FUNCTION:

. THESE VALVES ARE UTILIZED TO CONTROL HELIUM PRESSURIZATION OF THE RCS MODULE. IN THE OPEN POSITION A FLOW PATH IS PROVIDED FROM THE HELIUM SUPPLY TANK(S) TO THE REGULATOR(S). TWO PARALLEL PATHS ARE PROVIDED FOR FUEL AND OXIDIZER. ONE PATH IS NORMALLY OPEN PER TANK. THE VALVE IS CLOSED AND PARALLEL VALVE OPENED SUBSEQUENT TO A DOWN STREAM FAILURE.

.FAILURE MODE: FAILS CLOSED (F)

.CAUSE(S):

. VIBRATION, CONTAMINATION CONTINUOUS INADVERTENT CLOSING SIGNAL DUE TO SHORT CIRCUIT, PIECE PART FAILURE.

.EFFECT(S): UN (A)SUBSYSTEM (B)INTERFACES (C)MISSION (D)CREW/VEHICLE:

. (A) LOSS OF REDUNDANT PRESSURIZATION PATH. (B,D) NO EFFECT. (C)

. ABORT DECISION DEPENDENT ON MISSION PHASE AND BLOWDOWN CAPABILITY.

.CORRECTING ACTION:

. IF CAUSED BY VIBRATION, THE VALVE MAY BE CAPABLE OF OPENING WITH A NEW COMMAND OR, SWITCH TO PARALLEL REGULATION PATH - COMMAND PARALLEL ISOLATION VALVE OPEN.

.REMARKS/HAZARDS:

. POTENTIAL HAZARD IN ABORT SITUATION. SEE CONSOLIDATED CONTROLS FMEA NUMBER 73835 FMEA 1.

ORIGINAL PAGE IS
OF POOR QUALITY

SHUTTLE CRITICAL ITEMS LIST - ORBITER 102

SUBSYSTEM : FWD - REACTION CONTROL FMEA NO 03-2F -101020-4 REV:12/08/
 .ASSEMBLY : PRESSURIZATION ABORT: CRIT. FUNC: 1R
 .P/N RI : MC284-0419-0011/-0012 CRIT. HDW: 2
 .P/N VENDOR: 73835 MISSIONS: HF VF X FF OF SM
 .QUANTITY : 4 PHASE(S): PL X LO X CO X DO X LS
 . : TWO REQ'D PER PRESSURANT
 . : FEED ASSEMBLY

REDUNDANCY SCREEN: A-PASS B-PASS C-FA

PREPARED BY: APPROVED BY: APPROVED BY (NASA):
 .DES R BURKHART DES *M. L. Fisher* SSM *R. E. Tassner*
 .REL R DIEHL REL *C. E. Tassner* 12/15/77 REL *191 Tank Smith*

APPROVED WITH CHANGES
 See Section 13.0

- .ITEM: VALVE, D.C. SOLENOID
- .OPERATED, HIGH PRESSURE. HE (3600-4000 PSIA) SOLENOID ACTUATED, BI-STABLE, (1/2") (LV 101/102/103/104).
- .FUNCTION:
 - .THESE VALVES ARE UTILIZED TO CONTROL HELIUM PRESSURIZATION OF THE RCS MODULE. IN THE OPEN POSITION A FLOW PATH IS PROVIDED FROM THE HELIUM SUPPLY TANK(S) TO THE REGULATOR(S). TWO PARALLEL PATHS ARE PROVIDED FOR FUEL AND OXIDIZER. ONE PATH IS NORMALLY OPEN PER TANK. THE VALVE IS CLOSED AND PARALLEL VALVE OPENED SUBSEQUENT TO A DOWN STREAM FAILURE.
- .FAILURE MODE: FAILS CLOSED (F)
- .CAUSE(S):
 - .VIBRATION, CONTAMINATION CONTINUOUS INADVERTENT CLOSING SIGNAL DUE TO SHORT CIRCUIT, PIECE PART FAILURE.
- .EFFECT(S): ON (A)SUBSYSTEM (B)INTERFACES (C)MISSION (D)CREW/VEHICLE:
 - .(A) LOSS OF REDUNDANT PRESSURIZATION PATH. (B,D) NO EFFECT. (C) ABORT DECISION DEPENDENT ON MISSION PHASE AND BLOWDOWN CAPABILITY.
- .DISPOSITION & RATIONALE (A)DESIGN (B)TEST (C)INSPECTION (D)FAILURE HISTORY:
 - .(A) SERIES CONTROL CIRCUITRY PROVIDED TO MINIMIZE FAILURE MODE, 100 MICRON FILTER IS PROVIDED. MEDIA HAS BEEN FILTERED TO 25 MICRON PRIOR TO ENTERING TANK. SPECIAL EMPHASAS PLACED ON THE DESIGN AND LAYOUT OF SOLENOID WIRING TO PRECLUDE SHORTS. (B) QUAL TEST INCLUDES 48 MINUTES PER AXIS OF RANDOM VIBRATION AT ANTICIPATED MISSION LEVELS AND LIFE TESTING CONSISTING OF 2200 OPERATING CYCLES. ITEM IS USED DURING SYSTEM EVALUATION AT WHITE SANDS TESTING. (C) TURNAROUND INSPECTION INCLUDES MONITORING TESTS TO VERIFY ELECTRICAL POWER TO SOLENOID VALVE FOR EVIDENCE OF SHORT CIRCUIT, SUPPLIER AUDIT CONDUCTED 8-31-77 VERIFIED SUPPLIER INSPECTION EXERCISED CONTROL OF PARTS ID, PARTS PROTECTION, MFG PROCESSES, CONTAMINATION CONTROL, AND CORROSION PROTECTION VERIFICATION. (D) THERE IS NO FAILURE HISTORY FOR THIS SPECIFIC DESIGN.

HARDWARE/SOFTWARE ANALYSIS CHECKLIST 03-2F-101030-1

SUBSYSTEM Fwd. Reaction Control

FMEA NUMBER

SD75-SH-0016A

ITEM Helium Pressure Regulator

FAILURE MODE Fails Open

1. DOES THE FLIGHT SOFTWARE DETECT THIS FAILURE MODE (i.e., AUTOMATICALLY ANNUNCIATE OR TAKE ACTION IN RESPONSE)? YES ☐ NO ☒
- 1a. IF NOT, DOES THE HARDWARE PROVIDE INFORMATION THAT THE FLIGHT SOFTWARE COULD USE TO DETECT THE FAILURE? *YES ☐ NO ☒
2. ARE THE ANSWERS TO QUESTIONS 1 AND 1a CONSISTENT WITH THE FMEA EVALUATION OF IN-FLIGHT DETECTABILITY? YES ☒ *NO ☐
3. DOES THE FLIGHT SOFTWARE TAKE ACTION TO NEGATE THE EFFECTS OF THE FAILURE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? YES ☐ NO ☒
- 3a. IF NOT, DOES THE CAPABILITY EXIST FOR THE SOFTWARE TO COMPENSATE FOR THIS FAILURE MODE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? *YES ☐ NO ☒
4. AS A RESULT OF THIS FAILURE MODE, CAN THE SOFTWARE OVERSTRESS THE HARDWARE OR INDUCE ANOTHER FAILURE? *YES ☐ NO ☒
5. CAN THIS FAILURE MODE, IN COMBINATION WITH SOFTWARE LOGIC, ADVERSELY AFFECT OTHER FUNCTIONS? *YES ☐ NO ☒
6. HOW MANY OF THESE HARDWARE FAILURES CAN THE SHUTTLE TOLERATE (CONSIDER CREW ACTION AND HARDWARE/SOFTWARE OPERATION)? NOTE CHANGE TO FMEA CRITICALITY. *0 ☐ *1 ☐ 2 ☒
7. IF CREW ACTION IS REQUIRED TO RESPOND TO THIS FAILURE MODE, ARE CUES PROVIDED TO SIGNAL THE NEED FOR INTERVENTION AND THE REQUIRED CORRECTIVE ACTION? N/A ☒ YES ☐ NO ☐
8. IF THE ANSWER TO EITHER 1 OR 3 IS YES:
 - A. CAN THE BFS BE ENGAGED AFTER OCCURRENCE? YES ☐ *NO ☐
 - B. WILL BFS TOLERATE FAILURE WITHOUT LOSS OF CREW/VEHICLE? YES ☐ *NO ☐

*EXPLANATION REQUIRED (SEE BELOW)

CHANGE/RETENTION RATIONALE SUMMARY

- | | | |
|--|---|--|
| 1. <input checked="" type="checkbox"/> NO H/S ISSUES | 3. <input type="checkbox"/> NO SOFTWARE DETECTION | 5. <input type="checkbox"/> ACCEPTANCE RATIONALE BELOW |
| 2. <input type="checkbox"/> HARDWARE ACCEPTS RISK | 4. <input type="checkbox"/> DETECTION DURING CHECKOUT | 6. <input type="checkbox"/> RECOMMENDED CHANGES BELOW |

☐ FMEA CHANGE RECOMMENDED

EXPLANATION/COMMENTS:

1. Detection of this failure mode is not desired as these are redundant series regulators.

SHUTTLE FAILURE MODE AND EFFECTS ANALYSIS - ORBITER 102

1/12/77
22

SUBSYSTEM : FWD - REACTION CONTROL FMEA NO 03-2F -101030-1 REV: 06/12/77.
 .ASSEMBLY : PRESSURIZATION ABORT: CRIT. FUNC:
 .P/N RI : MC284-C418 CRIT. HWO: 3
 .P/N VENDOR: 743390C1 MISSIONS: HF VF X FF GF SM
 .QUANTITY : 4 PHASE(S): PL LO X OO X DU X LS
 . : TWO REQUIRED PER NUMBER OF SUCCESS PATHS REMAINING
 . : PRESSURANT PATH AFTER FIRST FAILURE: 1
 . REDUNDANCY SCREEN: A-PASS B-N/A C-PAS:
 .FAILURE DETECTABLE IN FLIGHT?. N/A TIME TO EFFECT:
 .STANDBY UNIT SECONDS
 . REFERENCE DOCUMENTS:
 . VS70-421001
 . GROUND TURNAROUND?.....YES MJ070-C001-01E
 . GROUND CHECKOUT TEST PORTS SD72-SH-0103-2

PREPARED BY: APPROVED BY:
 DES J. TAGGART DES _____
 REL R DIEHL REL _____

.ITEM: REGULATOR, PRESS, HE,
 . SERIES REDUNDANT. SET AT UNEQUAL OUTLET PRESSURES - PRIMARY SET LOWER
 THAN SECONDARY (PR 101/102/103/104).
 .FUNCTION:
 . TO REGULATE STORED HELIUM PRESSURE FROM 4000 PSIG MAX TO ULLAGE
 PRESSURE OF 245 (+ OR -3) PSIG FOR PURPOSE OF PROPELLANT FLOW TO
 THRUSTERS. TWO PARALLEL PATHS WITH TWO SERIES REGS ARE PROVIDED FOR
 EACH PROPELLANT TANK.
 .FAILURE MODE: FAILS OPEN (F)
 . OR LEAKS INTERNALLY.
 .CAUSE(S):
 . CONTAMINATION, VIBRATION, PIECE PART STRUCTURAL FAILURE-FLEXURES,
 BELLOWS, POPPET ASSY.
 .EFFECT(S): ON (A)SUBSYSTEM (B)INTERFACES (C)MISSION (D)CREW/VEHICLE:
 . (A) LOSS OF ONE REGULATOR ELEMENT IN ONE PATH (PRIMARY) AND RISE IN
 . PROPELLANT FEED PRESSURE TO SECONDARY REGULATOR ELEMENT PRESSURE
 SETTING. (S,C,D) NONE.
 .CORRECTING ACTION:
 . NONE REQUIRED - SERIES REGULATOR ELEMENT WILL AUTOMATICALLY TAKE OVER
 FUNCTION.
 .REMARKS/HAZARDS:
 . SEE FAIRCHILD FMEA # RR74339-12.

ORIGINAL PAGE IS
OF POOR QUALITY

. HARDWARE/SOFTWARE ANALYSIS CHECKLIST 03-2F-101030-2

SUBSYSTEM Fwd Reaction Control

FMEA NUMBER SD75-SH-0016A

ITEM Helium Pressure Regulator

FAILURE MODE Fails Closed

1. DOES THE FLIGHT SOFTWARE DETECT THIS FAILURE MODE (i.e., AUTOMATICALLY ANNUNCIATE OR TAKE ACTION IN RESPONSE)? YES ☒ NO ☐
- 1a. IF NOT, DOES THE HARDWARE PROVIDE INFORMATION THAT THE FLIGHT SOFTWARE COULD USE TO DETECT THE FAILURE? *YES ☐ NO ☐
2. ARE THE ANSWERS TO QUESTIONS 1 AND 1a CONSISTENT WITH THE FMEA EVALUATION OF IN-FLIGHT DETECTABILITY? YES ☐ *NO ☒
3. DOES THE FLIGHT SOFTWARE TAKE ACTION TO NEGATE THE EFFECTS OF THE FAILURE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? YES ☐ NO ☒
- 3a. IF NOT, DOES THE CAPABILITY EXIST FOR THE SOFTWARE TO COMPENSATE FOR THIS FAILURE MODE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? *YES ☐ NO ☒
4. AS A RESULT OF THIS FAILURE MODE, CAN THE SOFTWARE OVERSTRESS THE HARDWARE OR INDUCE ANOTHER FAILURE? *YES ☐ NO ☒
5. CAN THIS FAILURE MODE, IN COMBINATION WITH SOFTWARE LOGIC, ADVERSELY AFFECT OTHER FUNCTIONS? *YES ☐ NO ☒
6. HOW MANY OF THESE HARDWARE FAILURES CAN THE SHUTTLE TOLERATE (CONSIDER CREW ACTION AND HARDWARE/SOFTWARE OPERATION)? NOTE CHANGE TO FMEA CRITICALITY. *0 ☐ *1 ☒ 2 ☐
7. IF CREW ACTION IS REQUIRED TO RESPOND TO THIS FAILURE MODE, ARE CUES PROVIDED TO SIGNAL THE NEED FOR INTERVENTION AND THE REQUIRED CORRECTIVE ACTION? N/A ☐ YES ☒ NO ☐
8. IF THE ANSWER TO EITHER 1 OR 3 IS YES:
 - A. CAN THE BFS BE ENGAGED AFTER OCCURRENCE? YES ☒ *NO ☐
 - B. WILL BFS TOLERATE FAILURE WITHOUT LOSS OF CREW/VEHICLE? YES ☒ *NO ☐

*EXPLANATION REQUIRED (SEE BELOW)

CHANGE/RETENTION RATIONALE SUMMARY

- | | | |
|--|---|--|
| 1. <input type="checkbox"/> NO H/S ISSUES | 3. <input type="checkbox"/> NO SOFTWARE DETECTION | 5. <input type="checkbox"/> ACCEPTANCE RATIONALE BELOW |
| 2. <input checked="" type="checkbox"/> HARDWARE ACCEPTS RISK | 4. <input type="checkbox"/> DETECTION DURING CHECKOUT | 6. <input type="checkbox"/> RECOMMENDED CHANGES BELOW |

FMEA should be changed from "NA" to "yes" for in-flight detectability via V42P1115C and 1116C.

☒ FMEA CHANGE RECOMMENDED

EXPLANATION/COMMENTS:

1. V42P1115C, 1116C, will sense the pressure drop initiating a class 2 alarm from GAX.
2. Failure is "hardware detectable" by V42P1115C and V42P1116C pressure drop.
6. Upon regulator failure the redundant parallel "leg" can be utilized.

SHUTTLE FAILURE MODE AND EFFECTS ANALYSIS - ORBITER 102

SUBSYSTEM : FWD - REACTION CONTROL	FMEA NO 03-2F -101030-2	REV: 11/13/70
ASSEMBLY : PRESSURIZATION	ABORT:	CRIT. FUNC: 1R
P/N R1 : MC284-0419		CRIT. FWD: 2
P/N VENDOR: 74335001	MISSIONS: HF VF X FF UF SM	
QUANTITY : 4	PHASE(S): PL LO X GO X DO X LS	
: TWO REQUIRED PER	NUMBER OF SUCCESS PATHS REMAINING	
: PRESSURANT PATH	AFTER FIRST FAILURE:	Y
	REDUNDANCY SCREEN: A-PASS E-PASS C-PASS	
FAILURE DETECTABLE IN FLIGHT? <u>NA</u>	TIME TO EFFECT:	
STANDBY REDUNDANCY	MINUTES	
	REFERENCE DOCUMENTS:	
	V570-421001	
GROUND TURNAROUND?.....YES	MJ070-0001-012	
GROUND CHECKOUT TEST PORTS	SD72-SH-0103-2	

PREPARED BY:	APPROVED BY:
DES J. TAGGART	DES _____
REL R DIEHL	REL _____

- . ITEM: REGULATOR, PRESS, HE,
- . SERIES REDUNDANT. SET AT UNEQUAL OUTLET PRESSURES - PRIMARY SET LOWER THAN SECONDARY (PR 101/102/103/104).
- . FUNCTION:
- . TO REGULATE STORED HELIUM PRESSURE FROM 4000 PSIG MAX TO ULLAGE PRESSURE OF 245 (+ OR -3) PSIG FOR PURPOSE OF PROPELLANT FEED TO THRUSTERS. TWO PARALLEL PATHS WITH TWO SERIES REGS ARE PROVIDED FOR EACH PROPELLANT TANK.
- . FAILURE MODE: FAILS CLOSED (F)
- . (LOW PRESSURE)
- . CAUSE(S):
- . CONTAMINATION (PARTIAL BLOCKAGE OF PILOT SCREEN) FROZEN MOISTURE PIECE PART FAILURE, VIBRATION.
- . EFFECT(S): ON (A) SUBSYSTEM (B) INTERFACES (C) MISSION (D) CREW/VEHICLE:
- . (A) LOSS OF ONE REGULATOR PATH. (B,C) POTENTIAL ABORT BECAUSE ONE
- . ADDITIONAL FAILURE MAY CAUSE LOSS OF PRESSURIZATION AND SUBSEQUENT VEHICLE LOSS. (D) NONE. (E) FUNCTIONAL CRITICALITY EFFECTS - IF FAILURE OCCUR BEFORE ET SEPARATION, LOSS OF HELIUM WOULD PREVENT ET SEPARATION AND LOSS OF CREW/VEHICLE WOULD RESULT.
- . CORRECTING ACTION:
- . CLOSE HIGH PRESSURE ISOLATION VALVE IN EFFECTED PATH AND OPEN HIGH PRESSURE ISOLATION VALVE IN PARALLEL PATH.
- . REMARKS/HAZARDS:
- . POTENTIAL ABORT BECAUSE ONE ADDITIONAL FAILURE (CLOSED) MAY CAUSE LOSS OF PRESSURIZATION AND SUBSEQUENT VEHICLE LOSS (REQUIRES 2ND ORDER FAILURE) DEPENDENT ON MISSION PHASE. SEE FAIRCHILD FMEA & RM 74335-12.

SHUTTLE CRITICAL ITEMS LIST - ORBITER 102

SUBSYSTEM : FWD - REACTION CONTROL FMEA NO 03-2F -101030-2 PEV:11/13/76
 .ASSEMBLY : PRESSURIZATION ABORT: CRIT. FUNC: 1R
 .P/N RI : MC284-0418 CRIT. HDW: 2
 .P/N VENDOR: 74339001 MISSIONS: HF VF X FF 3F SM
 .QUANTITY : 4 PHASE(S): PL LO X OO X DO X LS
 . : TWO REQUIRED PER
 . : PRESSURANT PATH

REDUNDANCY SCREEN: A-PASS B-PASS C-PASS

.PREPARED BY:
 .DES J. TAGGART
 .REL R DIEHL

APPROVED BY:
 DES *[Signature]*
 REL *[Signature]* 12/15/76

APPROVED BY (NASA):
 SSM *[Signature]*
 REL *[Signature]*

APPROVED WITH CHANGES
 See Section 13.0

.ITEM: REGULATOR, PRESS, HE,
 . SERIES REDUNDANT. SET AT UNEQUAL OUTLET PRESSURES - PRIMARY SET LOWER
 THAN SECONDARY (PR 101/102/103/104).

.FUNCTION:
 . TO REGULATE STORED HELIUM PRESSURE FROM 4000 PSIG MAX TO ULLAGE
 PRESSURE OF 245 (+ OR -3) PSIG FOR PURPOSE OF PROPELLANT FEED TO
 THRUSTERS. TWO PARALLEL PATHS WITH TWO SERIES PEGS ARE PROVIDED FOR
 EACH PROPELLANT TANK.

.FAILURE MODE: FAILS CLOSED (F)
 . (LOW PRESSURE).

.CAUSE(S):
 . CONTAMINATION (PARTIAL BLOCKAGE OF PILOT SCREEN) FROZEN MOISTURE PIECE
 PART FAILURE, VIBRATION.
 .EFFECT(S): ON (A)SUBSYSTEM (B)INTERFACES (C)MISSION (D)CREW/VEHICLE:
 . (A) LOSS OF ONE REGULATOR PATH. (B,C) POTENTIAL ABORT BECAUSE ONE
 ADDITIONAL FAILURE MAY CAUSE LOSS OF PRESSURIZATION AND SUBSEQUENT
 VEHICLE LOSS. (D) NONE.

.DISPOSITION & RATIONALE (A)DESIGN (B)TEST (C)INSPECTION (D)FAILURE HISTORY:
 . (A) EXPERIENCE FROM PREVIOUS REGULATOR DESIGN TO BE APPLIED TO PRECLUDE
 PIECE PART FAILURE AND SELF GENERATED CONTAMINATION. ALSO, 25 MICRON
 INTREGAL INLET FILTER PROVIDED TO MINIMIZE CONTAMINANTS. (B) QUAL
 TESTING INCLUDES 28 HOUR SAND AND DUST TEST, 48 MINUTES PER AXIS OF
 RANDOM VIBRATION AT ANTICIPATED MISSION LEVELS AND LIFE CYCLE TESTS OF
 50,000 CYCLES FOR THE MAIN STAGE AND 100,000 CYCLES FOR PILOT STAGE.
 (C) TURNAROUND INSPECTION INCLUDES MONITORING TESTS TO VERIFY FUNCTIONAL
 OPERATION IS WITHIN SPECIFIED LIMITS. SUPPLIER AUDIT CONDUCTED VERIFIES
 WITHIN SPECIFIED LIMITS. SUPPLIER AUDIT CONDUCTED VERIFIES SUPPLIER
 CONTAMINATION CONTROL, AND STORAGE ENVIRONMENT. (D) NEW DESIGN FOR
 SHUTTLE APPLICATION. NO FAILURE HISTORY DATA AVAILABLE FOR THIS DESIGN.

HARDWARE/SOFTWARE ANALYSIS CHECKLIST

03-2F-101050-1

SUBSYSTEM Fwd. Reaction Control

FMEA NUMBER

SD75-SH-0016A

ITEM Manual Valve

FAILURE MODE Fails Closed or Open

1. DOES THE FLIGHT SOFTWARE DETECT THIS FAILURE MODE (i.e., AUTOMATICALLY ANNUNCIATE OR TAKE ACTION IN RESPONSE)? YES ☒ NO ☐
- 1a. IF NOT, DOES THE HARDWARE PROVIDE INFORMATION THAT THE FLIGHT SOFTWARE COULD USE TO DETECT THE FAILURE? *YES ☐ NO ☐
2. ARE THE ANSWERS TO QUESTIONS 1 AND 1a CONSISTENT WITH THE FMEA EVALUATION OF IN-FLIGHT DETECTABILITY? YES ☒ *NO ☐
3. DOES THE FLIGHT SOFTWARE TAKE ACTION TO NEGATE THE EFFECTS OF THE FAILURE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? YES ☐ NO ☒
- 3a. IF NOT, DOES THE CAPABILITY EXIST FOR THE SOFTWARE TO COMPENSATE FOR THIS FAILURE MODE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? *YES ☐ NO ☒
4. AS A RESULT OF THIS FAILURE MODE, CAN THE SOFTWARE OVERSTRESS THE HARDWARE OR INDUCE ANOTHER FAILURE? *YES ☐ NO ☒
5. CAN THIS FAILURE MODE, IN COMBINATION WITH SOFTWARE LOGIC, ADVERSELY AFFECT OTHER FUNCTIONS? *YES ☐ NO ☒
6. HOW MANY OF THESE HARDWARE FAILURES CAN THE SHUTTLE TOLERATE (CONSIDER CREW ACTION AND HARDWARE/SOFTWARE OPERATION)? NOTE CHANGE TO FMEA CRITICALITY. *0 ☒ *1 ☐ 2 ☐
7. IF CREW ACTION IS REQUIRED TO RESPOND TO THIS FAILURE MODE, ARE CUES PROVIDED TO SIGNAL THE NEED FOR INTERVENTION AND THE REQUIRED CORRECTIVE ACTION? N/A ☐ YES ☒ NO ☐
8. IF THE ANSWER TO EITHER 1 OR 3 IS YES:
 - A. CAN THE BFS BE ENGAGED AFTER OCCURRENCE? YES ☒ *NO ☐
 - B. WILL BFS TOLERATE FAILURE WITHOUT LOSS OF CREW/VEHICLE? YES ☒ *NO ☐

*EXPLANATION REQUIRED (SEE BELOW)

CHANGE/RETENTION RATIONALE SUMMARY

- | | | |
|--|---|--|
| 1. <input type="checkbox"/> NO H/S ISSUES | 3. <input type="checkbox"/> NO SOFTWARE DETECTION | 5. <input type="checkbox"/> ACCEPTANCE RATIONALE BELOW |
| 2. <input checked="" type="checkbox"/> HARDWARE ACCEPTS RISK | 4. <input type="checkbox"/> DETECTION DURING CHECKOUT | 6. <input type="checkbox"/> RECOMMENDED CHANGES BELOW |

☐ FMEA CHANGE RECOMMENDED

EXPLANATION/COMMENTS:

1. If valve is cracked open V42P1115A, 1116A would alarm.
6. There are no success paths remaining after first failure.

SHUTTLE FAILURE MODE AND EFFECTS ANALYSIS - ORBITER 102

SUBSYSTEM : FWD - REACTION CONTROL FMEA NO 03-2F -101050-1 REV: C1/C4/70
 .ASSEMBLY : PRESSURIZATION ABORT: CRIT. FUNC:
 .P/N RI : MC284-0460-0001/-0002 CRIT. FWD: 3
 .P/N VENDOR: 5760015, 5760016 MISSIONS: HF VF X FF OF SM
 .QUANTITY : 2 PHASE(S): PL LO X GO X DO X LS
 . : ONE REQ'D PER TANK NUMBER OF SUCCESS PATHS REMAINING
 . : AFTER FIRST FAILURE: C
 . REDUNDANCY SCREEN: A-PASS B-N/A C-PASS
 .FAILURE DETECTABLE IN FLIGHT? YES TIME TO EFFECT:
 .PROPELLANT TANK PRESSURE V42P-1210,1115,1116,1310 SECONDS TO MINUTES
 . REFERENCE DOCUMENTS:
 . MJC70-0001-01B
 . GROUND TURNAROUND?.....YES SD72-SH-0103-2
 . SAME AS FLIGHT VS70-421001
 .
 .
 .
 . PREPARED BY: APPROVED BY:
 . DES R. GONZALEZ DES _____
 . REL R DIEHL REL _____
 .
 .
 . ITEM: VALVE, MANUAL-OPERATED.
 . TWO POSITION SELECTOR VALVE (WITH STRUCTURAL INTERLOCK) (MV 101/102).
 . FUNCTION:
 . TO PROVIDE ISOLATION OF PROPELLANT TANK(S) FROM PRESSURE CYCLES WHILE
 . PERFORMING GROUND C/O AND/OR SERVICING OF PRESSURIZATION SYSTEM.
 . FAILURE MODE: FAILS CLOSED OR OPEN ()
 . STRUCTURAL FAILURE.
 . CAUSE(S):
 . SEVERE MECHANICAL SHOCK OR VIBRATION CAUSING DETENT MOVEMENT ON A
 . DEFICIENT VALVE LOSS OF INTERLOCK BY FRACTURE OF DRIVE FINGER OR
 . RUCKER, CORROSION, CONTAMINATION, IMPROPER USE.
 . EFFECT(S): ON (A) SUBSYSTEM (B) INTERFACES (C) MISSION (D) CREW/VEHICLE:
 . (A)(B) LOSS OF FUNCTION (IN ABILITY TO PERFORM SYS C/O. (C) LAUNCH
 . DELAY. (D) NO EFFECT.
 . CORRECTING ACTION:
 . NONE AVAILABLE.
 . REMARKS/HAZARDS:
 . NO HAZARDS IDENTIFIED.

ORIGINAL PAGE IS
 OF POOR QUALITY

. HARDWARE/SOFTWARE ANALYSIS CHECKLIST

03-2F-101050-2

SUBSYSTEM Fwd. Reaction Control

FMEA NUMBER

SD75-SH-0016A

ITEM Manual Valve

FAILURE MODE Internal Leakage

1. DOES THE FLIGHT SOFTWARE DETECT THIS FAILURE MODE (i.e., AUTOMATICALLY ANNUNCIATE OR TAKE ACTION IN RESPONSE)? YES ☒ NO ☐
- 1a. IF NOT, DOES THE HARDWARE PROVIDE INFORMATION THAT THE FLIGHT SOFTWARE COULD USE TO DETECT THE FAILURE? *YES ☐ NO ☐
2. ARE THE ANSWERS TO QUESTIONS 1 AND 1a CONSISTENT WITH THE FMEA EVALUATION OF IN-FLIGHT DETECTABILITY? YES ☒ *NO ☐
3. DOES THE FLIGHT SOFTWARE TAKE ACTION TO NEGATE THE EFFECTS OF THE FAILURE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? YES ☐ NO ☒
- 3a. IF NOT, DOES THE CAPABILITY EXIST FOR THE SOFTWARE TO COMPENSATE FOR THIS FAILURE MODE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? *YES ☐ NO ☒
4. AS A RESULT OF THIS FAILURE MODE, CAN THE SOFTWARE OVERSTRESS THE HARDWARE OR INDUCE ANOTHER FAILURE? *YES ☐ NO ☒
5. CAN THIS FAILURE MODE, IN COMBINATION WITH SOFTWARE LOGIC, ADVERSELY AFFECT OTHER FUNCTIONS? *YES ☐ NO ☒
6. HOW MANY OF THESE HARDWARE FAILURES CAN THE SHUTTLE TOLERATE (CONSIDER CREW ACTION AND HARDWARE/SOFTWARE OPERATION)? NOTE CHANGE TO FMEA CRITICALITY. *0 ☒ *1 ☐ 2 ☐
7. IF CREW ACTION IS REQUIRED TO RESPOND TO THIS FAILURE MODE, ARE CUES PROVIDED TO SIGNAL THE NEED FOR INTERVENTION AND THE REQUIRED CORRECTIVE ACTION? N/A ☐ YES ☒ NO ☐
8. IF THE ANSWER TO EITHER 1 OR 3 IS YES:
 - A. CAN THE BFS BE ENGAGED AFTER OCCURRENCE? YES ☒ *NO ☐
 - B. WILL BFS TOLERATE FAILURE WITHOUT LOSS OF CREW/VEHICLE? YES ☒ *NO ☐

*EXPLANATION REQUIRED (SEE BELOW)

CHANGE/RETENTION RATIONALE SUMMARY

- | | | |
|--|---|--|
| 1. <input type="checkbox"/> NO H/S ISSUES | 3. <input type="checkbox"/> NO SOFTWARE DETECTION | 5. <input type="checkbox"/> ACCEPTANCE RATIONALE BELOW |
| 2. <input checked="" type="checkbox"/> HARDWARE ACCEPTS RISK | 4. <input type="checkbox"/> DETECTION DURING CHECKOUT | 6. <input type="checkbox"/> RECOMMENDED CHANGES BELOW |

☐ FMEA CHANGE RECOMMENDED

EXPLANATION/COMMENTS:

1. If valve is cracked open V42P1115A, 1116A would alarm.
6. There are no success paths remaining after first failure.

SHUTTLE FAILURE MODE AND EFFECTS ANALYSIS - ORBITER 102

SUBSYSTEM : FWD - REACTION CONTROL FMEA NO 03-2F -101050-2 REV:01/04/7.
 .ASSEMBLY : PRESSURIZATION ASORT: CRIT. FUNC:
 .P/N RI : MC284-0480-0001/-0002 CRIF. FWD: 3
 .P/N VENDOR: 5760015, 5760016 MISSIONS: HF VF X FF OF SM
 .QUANTITY : 2 PHASE(S): PL LG X GG X DG X LS
 . : ONE REQ'D PER TANK NUMBER OF SUCCESS PATHS REMAINING
 . : AFTER FIRST FAILURE: 0
 . REDUNDANCY SCREEN: A-PASS B-N/A C-PAS:
 .FAILURE DETECTABLE IN FLIGHT?. YES TIME TO EFFECT:
 .PROPELLANT TANK PRESSURE V42P-1210,1115,1116,1310 SECONDS TO MINUTES
 . REFERENCE DOCUMENTS:
 . MJ070-C001-G18
 . GROUND TURNAROUND?.....YES SD72-SH-0103-2
 . SAME AS FLIGHT VS70-421001

PREPARED BY:

DES

REL

R. GONZALEZ

R DIEHL

APPROVED BY:

DES

REL

.ITEM: VALVE, MANUAL-OPERATED.

. TWO POSITION SELECTOR VALVE (WITH STRUCTURAL INTERLOCK) (XV 101/102).

.FUNCTION:

. TO PROVIDE ISOLATION OF PROPELLANT TANK(S) FROM PRESSURE CYCLES WHILE PERFORMING GROUND C/O AND/OR SERVICING OF PRESSURIZATION SYSTEM.

.FAILURE MODE: EXCESSIVE INTERNAL ()

. LEAKAGE.

.CAUSE(S):

. SEVERE MECHANICAL SHOCK OR VIBRATION CAUSING DETENT MOVEMENT ON A DEFICIENT VALVE LOSS OF INTERLOCK BY FRACTURE OF DRIVE FINGER OR ROCKER, CORROSION, CONTAMINATION, IMPROPER USE.

.EFFECT(S): ON (A) SUBSYSTEM (B) INTERFACES (C) MISSION (D) CREW/VEHICLE:

. (A,B) LOSS OF FUNCTION (IN ABILITY TO PERFORM SYS C/O). (C) LAUNCH

. DELAY. (D) NO EFFECT.

.CORRECTING ACTION:

. NONE AVAILABLE.

.REMARKS/HAZARDS:

. NO HAZARDS IDENTIFIED.

. HARDWARE/SOFTWARE ANALYSIS CHECKLIST 03-2F-101060-1

SUBSYSTEM Fwd Reaction Control

FMEA NUMBER SD75-SH-0016A

ITEM Relief Valve

FAILURE MODE External Leakage Overboard

1. DOES THE FLIGHT SOFTWARE DETECT THIS FAILURE MODE (i.e., AUTOMATICALLY ANNUNCIATE OR TAKE ACTION IN RESPONSE)? YES ☒ NO ☐
- 1a. IF NOT, DOES THE HARDWARE PROVIDE INFORMATION THAT THE FLIGHT SOFTWARE COULD USE TO DETECT THE FAILURE? *YES ☐ NO ☐
2. ARE THE ANSWERS TO QUESTIONS 1 AND 1a CONSISTENT WITH THE FMEA EVALUATION OF IN-FLIGHT DETECTABILITY? YES ☒ *NO ☐
3. DOES THE FLIGHT SOFTWARE TAKE ACTION TO NEGATE THE EFFECTS OF THE FAILURE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? YES ☐ NO ☒
- 3a. IF NOT, DOES THE CAPABILITY EXIST FOR THE SOFTWARE TO COMPENSATE FOR THIS FAILURE MODE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? *YES ☐ NO ☒
4. AS A RESULT OF THIS FAILURE MODE, CAN THE SOFTWARE OVERSTRESS THE HARDWARE OR INDUCE ANOTHER FAILURE? *YES ☐ NO ☒
5. CAN THIS FAILURE MODE, IN COMBINATION WITH SOFTWARE LOGIC, ADVERSELY AFFECT OTHER FUNCTIONS? *YES ☐ NO ☒
6. HOW MANY OF THESE HARDWARE FAILURES CAN THE SHUTTLE TOLERATE (CONSIDER CREW ACTION AND HARDWARE/SOFTWARE OPERATION)? NOTE CHANGE TO FMEA CRITICALITY. *0 ☐ *1 ☐ 2 ☒
7. IF CREW ACTION IS REQUIRED TO RESPOND TO THIS FAILURE MODE, ARE CUES PROVIDED TO SIGNAL THE NEED FOR INTERVENTION AND THE REQUIRED CORRECTIVE ACTION? N/A ☐ YES ☒ NO ☐
8. IF THE ANSWER TO EITHER 1 OR 3 IS YES:
 - A. CAN THE BFS BE ENGAGED AFTER OCCURRENCE? YES ☒ *NO ☐
 - B. WILL BFS TOLERATE FAILURE WITHOUT LOSS OF CREW/VEHICLE? YES ☒ *NO ☐

*EXPLANATION REQUIRED (SEE BELOW)

CHANGE/RETENTION RATIONALE SUMMARY

- | | | |
|--|---|--|
| 1. <input type="checkbox"/> NO H/S ISSUES | 3. <input type="checkbox"/> NO SOFTWARE DETECTION | 5. <input type="checkbox"/> ACCEPTANCE RATIONALE BELOW |
| 2. <input checked="" type="checkbox"/> HARDWARE ACCEPTS RISK | 4. <input type="checkbox"/> DETECTION DURING CHECKOUT | 6. <input type="checkbox"/> RECOMMENDED CHANGES BELOW |

☐ FMEA CHANGE RECOMMENDED

EXPLANATION/COMMENTS:

1. Leakage of helium will cause a class 2 alarm.
Gross leak detection should occur first.

SHUTTLE FAILURE MODE AND EFFECTS ANALYSIS - ORBITER 102

SUBSYSTEM : FWD - REACTION CONTROL FMEA NO 03-2F -101060-1 REV:01/04/71
 .ASSEMBLY : PRESSURIZATION ABORT: CRIT. FUNC:
 .P/N RI : MC284-0421-0001/-0002 CRIT. HWD: 5
 .P/N VENDOR: 5760009-101, 5760010-102 MISSIONS: HF VF X FF GF SM
 .QUANTITY : 2 PHASE(S): PL LG X OD X OD X LS
 . : ONE REQ'D PER TANK NUMBER OF SUCCESS PATHS REMAINING
 . : AFTER FIRST FAILURE: 2
 . : REDUNDANCY SCREEN: A-N/A B-N/A C-N/A
 .FAILURE DETECTABLE IN FLIGHT? YES TIME TO EFFECT:
 .PRESSURE DECAY IN PRESS- SYSTEM V42P-1115C AND HOURS
 .1116C (TANK ULLAGE) REFERENCE DOCUMENTS:
 . : MJG70-0001-01F
 .GROUND TURNAROUND?.....YES SG72-SH-0103-2
 .TEST PORT FOR GROUND CHECKOUT AND BACK CHECK VS70-421001
 .
 .
 .
 . PREPARED BY: APPROVED BY:
 . DES R GONZALEZ DES _____
 . REL R DIEHL REL _____
 .
 .
 .ITEM: VALVE, PRESS. RELIEF -
 . CRCKNG PRESS 315 PSIG, FULL OPEN 340 PSIG, RESEAT 310 PSIG (RV
 101/102).
 .FUNCTION:
 . RELIEF VALVE PROVIDED TO PREVENT RISE OF TANK AND LINE PRESSURES TO
 LEVELS WHICH COULD BE DETRIMENTAL TO SUBSYSTEM.
 .FAILURE MODE: EXTERNAL LEAK ()
 . LEAKS OVERBOARD THRU BELLOWS & ORIFICE.
 .CAUSE(S):
 . GALVANIC CORROSION, IMPROPER INSTALLATION/HANDLING, FATIGUE OR
 STRUCTURAL FAILURE.
 .EFFECT(S): ON (A)SUBSYSTEM (B)INTERFACES (C)MISSION (D)CREW/VEHICLE:
 . (A&B) SUBSYSTEM DEGRADATION - HELIUM LEAKS OVERBOARD AT RATE CONTROLLED
 BY ORIFICE. (C&D) NO EFFECT UNLESS LEAK IS EXCESSIVE.
 .CORRECTING ACTION:
 . MONITOR SYSTEM FOR HELIUM LOSS.
 .REMARKS/HAZARDS:
 . NO HAZARD IDENTIFIED.

1. DOES THE FLIGHT SOFTWARE DETECT THIS FAILURE MODE (i.e., AUTOMATICALLY ANNUNCIATE OR TAKE ACTION IN RESPONSE)? YES ☒ NO ☐
- 1a. IF NOT, DOES THE HARDWARE PROVIDE INFORMATION THAT THE FLIGHT SOFTWARE COULD USE TO DETECT THE FAILURE? *YES ☐ NO ☐
2. ARE THE ANSWERS TO QUESTIONS 1 AND 1a CONSISTENT WITH THE FMEA EVALUATION OF IN-FLIGHT DETECTABILITY? YES ☐ *NO ☒
3. DOES THE FLIGHT SOFTWARE TAKE ACTION TO NEGATE THE EFFECTS OF THE FAILURE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? YES ☐ NO ☒
- 3a. IF NOT, DOES THE CAPABILITY EXIST FOR THE SOFTWARE TO COMPENSATE FOR THIS FAILURE MODE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? *YES ☐ NO ☒
4. AS A RESULT OF THIS FAILURE MODE, CAN THE SOFTWARE OVERSTRESS THE HARDWARE OR INDUCE ANOTHER FAILURE? *YES ☐ NO ☒
5. CAN THIS FAILURE MODE, IN COMBINATION WITH SOFTWARE LOGIC, ADVERSELY AFFECT OTHER FUNCTIONS? *YES ☐ NO ☒
6. HOW MANY OF THESE HARDWARE FAILURES CAN THE SHUTTLE TOLERATE (CONSIDER CREW ACTION AND HARDWARE/SOFTWARE OPERATION)? NOTE CHANGE TO FMEA CRITICALITY. *0 ☐ *1 ☐ 2 ☒
7. IF CREW ACTION IS REQUIRED TO RESPOND TO THIS FAILURE MODE, ARE CUES PROVIDED TO SIGNAL THE NEED FOR INTERVENTION AND THE REQUIRED CORRECTIVE ACTION? N/A ☒ YES ☐ NO ☐
8. IF THE ANSWER TO EITHER 1 OR 3 IS YES:
 - A. CAN THE BFS BE ENGAGED AFTER OCCURRENCE? YES ☒ *NO ☐
 - B. WILL BFS TOLERATE FAILURE WITHOUT LOSS OF CREW/VEHICLE? YES ☒ *NO ☐

*EXPLANATION REQUIRED (SEE BELOW)

CHANGE/RETENTION RATIONALE SUMMARY

- | | | |
|--|---|--|
| 1. <input type="checkbox"/> NO H/S ISSUES | 3. <input type="checkbox"/> NO SOFTWARE DETECTION | 5. <input type="checkbox"/> ACCEPTANCE RATIONALE BELOW |
| 2. <input checked="" type="checkbox"/> HARDWARE ACCEPTS RISK | 4. <input type="checkbox"/> DETECTION DURING CHECKOUT | 6. <input type="checkbox"/> RECOMMENDED CHANGES BELOW |

In-Flight Detectability
☒ FMEA CHANGE RECOMMENDED

EXPLANATION/COMMENTS:

1. May see discrete drop in RCS quantity. V42P1115C, 1116C will give class 2 caution and warning alarm.

SHUTTLE FAILURE MODE AND EFFECTS ANALYSIS - ORBITER 102

SUBSYSTEM : FWD - REACTION CONTROL FMEA NO C3-2F -101060-2 REV:01/04/76
 .ASSEMBLY : PRESSURIZATION ABORT: CRIT. FUNC:
 .P/N RI : MC284-0421-0001/-0002 CRIT. FWD: 3
 .P/N VENDOR: 5760C09-101,5760C10-102 MISSIONS: HF VF X HF LF SM
 .QUANTITY : 2 PHASE(S): PL X LO X CU X DO X LS
 . : ONE REQ'D PER TANK NUMBER OF SUCCESS PATHS REMAINING
 . : AFTER FIRST FAILURE: 2
 . REDUNDANCY SCREEN: A-PASS B-PASS C-PASS
 .FAILURE DETECTABLE IN FLIGHT?. NO TIME TO EFFECT:
 . IMMEDIATE
 . REFERENCE DOCUMENTS:
 . MJ070-0001-01E
 . GROUND TURNAROUND?.....NO SD72-SH-0103-2
 . VS70-421001

PREPARED BY: APPROVED BY:
 . DES R GONZALEZ DES _____
 . REL R DIEHL REL _____

.ITEM: VALVE, PRESS. RELIEF -
 . CRCKNG PRESS 315 PSIG, FULL OPEN 340 PSIG, RESEAT 310 PSIG (RV
 101/102).
 .FUNCTION:
 . RELIEF VALVE PROVIDED TO PREVENT RISE OF TANK AND LINE PRESSURES TO
 LEVELS WHICH COULD BE DETRIMENTAL TO SUBSYSTEM.
 .FAILURE MODE: FAILS OPEN ()
 . BURST DISC RUPTURES.
 .CAUSE(S):
 . REGULATOR PRESSURE SURGE, INCORRECT PRESSURE SETTING, FATIGUE. EXCESS
 PRESSURE CYCLING, VIB, MAT'L DEFECT PROP TEMP RISES.
 .EFFECT(S): ON (A)SUBSYSTEM (B)INTERFACES (C)MISSION (D)CREW/VEHICLE:
 . (A,B) LOSS OF REDUNDANCY (LEAKAGE OR OPEN MODE)(MAIN POPPET PROVIDES
 REDUNDANCY). (C,D) NO EFFECT.
 .CORRECTING ACTION:
 . MONITOR SYSTEM FOR POTENTIAL HELIUM LOSS OR PROP, TANK PRESSURE
 DECREASE. REPLACE VALVE AFTER LANDING.
 .REMARKS/HAZARDS:
 . NO HAZARDS IDENTIFIED.

. HARDWARE/SOFTWARE ANALYSIS CHECKLIST 03-2F-101060-3

SUBSYSTEM Fwd Reaction Control

FMEA NUMBER SD75-SH-0016A

ITEM Relief Valve

FAILURE MODE Fails to Burst

1. DOES THE FLIGHT SOFTWARE DETECT THIS FAILURE MODE (i.e., AUTOMATICALLY ANNUNCIATE OR TAKE ACTION IN RESPONSE)? YES ☒ NO ☐
- 1a. IF NOT, DOES THE HARDWARE PROVIDE INFORMATION THAT THE FLIGHT SOFTWARE COULD USE TO DETECT THE FAILURE? *YES ☐ NO ☐
2. ARE THE ANSWERS TO QUESTIONS 1 AND 1a CONSISTENT WITH THE FMEA EVALUATION OF IN-FLIGHT DETECTABILITY? YES ☒ *NO ☐
3. DOES THE FLIGHT SOFTWARE TAKE ACTION TO NEGATE THE EFFECTS OF THE FAILURE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? YES ☐ NO ☒
- 3a. IF NOT, DOES THE CAPABILITY EXIST FOR THE SOFTWARE TO COMPENSATE FOR THIS FAILURE MODE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? *YES ☐ NO ☒
4. AS A RESULT OF THIS FAILURE MODE, CAN THE SOFTWARE OVERSTRESS THE HARDWARE OR INDUCE ANOTHER FAILURE? *YES ☐ NO ☒
5. CAN THIS FAILURE MODE, IN COMBINATION WITH SOFTWARE LOGIC, ADVERSELY AFFECT OTHER FUNCTIONS? *YES ☐ NO ☒
6. HOW MANY OF THESE HARDWARE FAILURES CAN THE SHUTTLE TOLERATE (CONSIDER CREW ACTION AND HARDWARE/SOFTWARE OPERATION)? NOTE CHANGE TO FMEA CRITICALITY. *0 ☐ *1 ☐ 2 ☒
7. IF CREW ACTION IS REQUIRED TO RESPOND TO THIS FAILURE MODE, ARE CUES PROVIDED TO SIGNAL THE NEED FOR INTERVENTION AND THE REQUIRED CORRECTIVE ACTION? N/A ☒ YES ☐ NO ☐
8. IF THE ANSWER TO EITHER 1 OR 3 IS YES:
 - A. CAN THE BFS BE ENGAGED AFTER OCCURRENCE? YES ☒ *NO ☐
 - B. WILL BFS TOLERATE FAILURE WITHOUT LOSS OF CREW/VEHICLE? YES ☒ *NO ☐

*EXPLANATION REQUIRED (SEE BELOW)

CHANGE/RETENTION RATIONALE SUMMARY

- | | | |
|--|---|--|
| 1. <input type="checkbox"/> NO H/S ISSUES | 3. <input type="checkbox"/> NO SOFTWARE DETECTION | 5. <input type="checkbox"/> ACCEPTANCE RATIONALE BELOW |
| 2. <input checked="" type="checkbox"/> HARDWARE ACCEPTS RISK | 4. <input type="checkbox"/> DETECTION DURING CHECKOUT | 6. <input type="checkbox"/> RECOMMENDED CHANGES BELOW |

☐ FMEA CHANGE RECOMMENDED

EXPLANATION/COMMENTS:

1. Over pressurization will cause class 2 alarm; >312 psi. (GAX)
V42P1115C, 1116C.

SHUTTLE FAILURE MODE AND EFFECTS ANALYSIS - ORBITER 102

SUBSYSTEM : FWD - REACTION CONTROL FMEA NO G3-2F -101060-2 REV:01/04/70
 .ASSEMBLY : PRESSURIZATION ABORT: CRIT. FUNC:
 .P/N RI : MC284-0421-0001/-0002 CRIT. HWD: 3
 .P/N VENDOR: 5760009-101, 5760010-102 MISSIONS: HF VF X FF GF SM
 .QUANTITY : 2 PHASE(S): PL LG X DD X DD X LS
 . : : ONE REQ'D PER TANK NUMBER OF SUCCESS PATHS REMAINING
 . : : AFTER FIRST FAILURE: 2
 . : : REDUNDANCY SCREEN: A-N/A B-N/A C-N/A
 .FAILURE DETECTABLE IN FLIGHT? YES TIME TO EFFECT:
 .PRESSURE RISE IN HELIUM SYSTEM V42P-1115C AND SECONDS
 .1116C (TANK ULLAGE PRESSURE) REFERENCE DOCUMENTS:
 . : : MJ070-0001-01E
 .GROUND TURNAROUND?.....YES SD72-SH-0105-2
 .TURNAROUND TEST PORT PROVIDED VS70-421001

PREPARED BY:

DES

REL

R GONZALEZ

R DIEHL

APPROVED BY:

DES

REL

.ITEM: VALVE, PRESS. RELIEF -

. CRCKNG PRESS 315 PSIG, FULL OPEN 340 PSIG, RESEAT 310 PSIG (KV 101/102).

.FUNCTION:

. RELIEF VALVE PROVIDED TO PREVENT RISE OF TANK AND LINE PRESSURES TO LEVELS WHICH COULD BE DETRIMENTAL TO SUBSYSTEM.

.FAILURE MODE: FAILS TO BURST ()

. OR BURSTS AT A HIGHER THAN NOMINAL PRESSURE.

.CAUSE(S):

. IMPROPER INSTALLATION OR HANDLING DAMAGE THAT CAUSLS DISC TO STICK
 PIECE PART FAILURE, PRESSURE BUILD UP ON REVERSE SIDE.

.EFFECT(S): ON (A)SUBSYSTEM (B)INTERFACES (C)MISSION (D)CREW/VEHICLE:

. (A) NO EFFECT UNLESS MULTIPLE FAILURES OCCUR. (B) DEGRADATION OF

. INTERFACE SUBSYSTEM. PROP TANK ULLAGE PRESSURE MAY INCREASE ABOVE
 WORKING PRESSURE LIMITS. (C,D) NONE SEE (A) ABOVE.

.CORRECTING ACTION:

. CLOSE HELIUM ISOLATION VALVES, HOWEVER RELIEF COULD BE COMPLETED BY
 FIRING THRUSTERS.

.REMARKS/HAZARDS:

. NO HAZARDS, UNIT IS STANDBY - BACKUP FOR REGULATOR FAILURES. NO
 REDUNDANCY PROVIDED.

ORIGINAL PAGE IS
 OF POOR QUALITY

. **HARDWARE/SOFTWARE ANALYSIS CHECKLIST** 03-2F-101060-4

SUBSYSTEM Fwd Reaction Control FMEA NUMBER SD75-SH-0016A

ITEM Relief Valve FAILURE MODE Opens Low

1. DOES THE FLIGHT SOFTWARE DETECT THIS FAILURE MODE (i.e., AUTOMATICALLY ANNUNCIATE OR TAKE ACTION IN RESPONSE)? YES ☒ NO ☐
- 1a. IF NOT, DOES THE HARDWARE PROVIDE INFORMATION THAT THE FLIGHT SOFTWARE COULD USE TO DETECT THE FAILURE? *YES ☐ NO ☐
2. ARE THE ANSWERS TO QUESTIONS 1 AND 1a CONSISTENT WITH THE FMEA EVALUATION OF IN-FLIGHT DETECTABILITY? YES ☐ *NO ☒
3. DOES THE FLIGHT SOFTWARE TAKE ACTION TO NEGATE THE EFFECTS OF THE FAILURE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? YES ☐ NO ☒
- 3a. IF NOT, DOES THE CAPABILITY EXIST FOR THE SOFTWARE TO COMPENSATE FOR THIS FAILURE MODE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? *YES ☐ NO ☒
4. AS A RESULT OF THIS FAILURE MODE, CAN THE SOFTWARE OVERSTRESS THE HARDWARE OR INDUCE ANOTHER FAILURE? *YES ☐ NO ☒
5. CAN THIS FAILURE MODE, IN COMBINATION WITH SOFTWARE LOGIC, ADVERSELY AFFECT OTHER FUNCTIONS? *YES ☐ NO ☒
6. HOW MANY OF THESE HARDWARE FAILURES CAN THE SHUTTLE TOLERATE (CONSIDER CREW ACTION AND HARDWARE/SOFTWARE OPERATION)? NOTE CHANGE TO FMEA CRITICALITY. *0 ☐ *1 ☐ 2 ☒
7. IF CREW ACTION IS REQUIRED TO RESPOND TO THIS FAILURE MODE, ARE CUES PROVIDED TO SIGNAL THE NEED FOR INTERVENTION AND THE REQUIRED CORRECTIVE ACTION? N/A ☐ YES ☒ NO ☐
8. IF THE ANSWER TO EITHER 1 OR 3 IS YES:
 - A. CAN THE BFS BE ENGAGED AFTER OCCURRENCE? YES ☒ *NO ☐
 - B. WILL BFS TOLERATE FAILURE WITHOUT LOSS OF CREW/VEHICLE? YES ☒ *NO ☐

*EXPLANATION REQUIRED (SEE BELOW)

CHANGE/RETENTION RATIONALE SUMMARY

- | | | |
|--|---|--|
| 1. <input type="checkbox"/> NO H/S ISSUES | 3. <input type="checkbox"/> NO SOFTWARE DETECTION | 5. <input type="checkbox"/> ACCEPTANCE RATIONALE BELOW |
| 2. <input checked="" type="checkbox"/> HARDWARE ACCEPTS RISK | 4. <input type="checkbox"/> DETECTION DURING CHECKOUT | 6. <input type="checkbox"/> RECOMMENDED CHANGES BELOW |

In-Flight Detectability
☒ FMEA CHANGE RECOMMENDED

EXPLANATION/COMMENTS:

1. Leakage of helium will cause an oxidizer/fuel imbalance of 12.6 percent. May get a gross leak detection alarm.

SHUTTLE FAILURE MODE AND EFFECTS ANALYSIS - ORBITER 102

SUBSYSTEM : FWD - REACTION CONTROL	FMEA NO 03-2F -101060-4	REV: 01/04/78
ASSEMBLY : PRESSURIZATION	ABORT:	CRIT. FUNC:
P/N R1 : MC284-0421-0001/-0002		CRIT. HWU: 3
P/N VENDOR: 5760009-101, 5760010-102	MISSIONS: HF VF X FF. DE SM	
QUANTITY : 2	PHASE(S): PL LU X CO X DO X LS	
: ONE REQ'D PER TANK	NUMBER OF SUCCESS PATHS REMAINING	
:	AFTER FIRST FAILURE:	2
:	REDUNDANCY SCREEN: A- E- C-	
FAILURE DETECTABLE IN FLIGHT? NO	TIME TO EFFECT:	
UNLESS EXCESSIVE PRESSURE DROP IS EVIDENT IN	SECONDS TO DAYS	
TANKAGE	REFERENCE DOCUMENTS:	
:	MJ070-0001-018	
GROUND TURNAROUND?.....NO	SD72-SH-0103-2	
SAME AS FLIGHT	VS70-421001	

PREPARED BY:	APPROVED BY:
DES R GONZALEZ	DES _____
REL R DIEHL	REL _____

- . ITEM: VALVE, PRESS. RELIEF -
- . CRACKING PRESS 315 PSIG, FULL OPEN 340 PSIG, RESEAT 210 PSIG (RV 101/102).
- . FUNCTION:
- . RELIEF VALVE PROVIDED TO PREVENT RISE OF TANK AND LINE PRESSURES TO LEVELS WHICH COULD BE DETRIMENTAL TO SUBSYSTEM.
- . FAILURE MODE: PREMATURE/ERRATIC OPERATION (F)
- . TION, INTERNAL LEAKAGE, OPEN BELOW NOMINAL CRACKING PRESSURE.
- . CAUSE(S):
- . VIBRATION, MECHANICAL SHOCK, CONTAMINATION, PIECE PART STRUCTURAL FAILURE OF POPPET.
- . EFFECT(S): ON (A) SUBSYSTEM (B) INTERFACES (C) MISSION (D) CREW/VEHICLE:
- . (A) LOSS OF HELIUM OR PROPELLANT VAPORS OVERBOARD. (B) INABILITY TO PRESSURIZE PROPELLANT TANKS IF LEAK IS EXCESSIVE. (C) POTENTIAL ABORT IF EARLY IN MISSION, WOULD REQUIRE PRIOR FAILURE (BURST DISC OPEN). (D) NONE.
- . CORRECTING ACTION:
- . NONE.
- . REMARKS/HAZARDS:
- . WOULD REQUIRE BURST DISC FAILURE BEFORE LEAKS OVERBOARD. NO REDUNDANCY PROVIDED.

ORIGINAL PAGE IS
OF POOR QUALITY

HARDWARE/SOFTWARE ANALYSIS CHECKLIST 03-2F-101060-5

SUBSYSTEM Fwd Reaction Control

FMEA NUMBER SD75-SH-0016A

ITEM Relief Valve

FAILURE MODE Fails to Open

1. DOES THE FLIGHT SOFTWARE DETECT THIS FAILURE MODE (i.e., AUTOMATICALLY ANNUNCIATE OR TAKE ACTION IN RESPONSE)? YES ☒ NO ☐
- 1a. IF NOT, DOES THE HARDWARE PROVIDE INFORMATION THAT THE FLIGHT SOFTWARE COULD USE TO DETECT THE FAILURE? *YES ☐ NO ☐
2. ARE THE ANSWERS TO QUESTIONS 1 AND 1a CONSISTENT WITH THE FMEA EVALUATION OF IN-FLIGHT DETECTABILITY? YES ☒ *NO ☐
3. DOES THE FLIGHT SOFTWARE TAKE ACTION TO NEGATE THE EFFECTS OF THE FAILURE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? YES ☐ NO ☒
- 3a. IF NOT, DOES THE CAPABILITY EXIST FOR THE SOFTWARE TO COMPENSATE FOR THIS FAILURE MODE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? *YES ☐ NO ☒
4. AS A RESULT OF THIS FAILURE MODE, CAN THE SOFTWARE OVERSTRESS THE HARDWARE OR INDUCE ANOTHER FAILURE? *YES ☐ NO ☒
5. CAN THIS FAILURE MODE, IN COMBINATION WITH SOFTWARE LOGIC, ADVERSELY AFFECT OTHER FUNCTIONS? *YES ☐ NO ☒
6. HOW MANY OF THESE HARDWARE FAILURES CAN THE SHUTTLE TOLERATE (CONSIDER CREW ACTION AND HARDWARE/SOFTWARE OPERATION)? NOTE CHANGE TO FMEA CRITICALITY. *0 ☐ *1 ☐ 2 ☒
7. IF CREW ACTION IS REQUIRED TO RESPOND TO THIS FAILURE MODE, ARE CUES PROVIDED TO SIGNAL THE NEED FOR INTERVENTION AND THE REQUIRED CORRECTIVE ACTION? N/A ☐ YES ☒ NO ☐
8. IF THE ANSWER TO EITHER 1 OR 3 IS YES:
 - A. CAN THE BFS BE ENGAGED AFTER OCCURRENCE? YES ☒ *NO ☐
 - B. WILL BFS TOLERATE FAILURE WITHOUT LOSS OF CREW/VEHICLE? YES ☒ *NO ☐

*EXPLANATION REQUIRED (SEE BELOW)

CHANGE/RETENTION RATIONALE SUMMARY

- | | | |
|--|---|--|
| 1. <input type="checkbox"/> NO H/S ISSUES | 3. <input type="checkbox"/> NO SOFTWARE DETECTION | 5. <input type="checkbox"/> ACCEPTANCE RATIONALE BELOW |
| 2. <input checked="" type="checkbox"/> HARDWARE ACCEPTS RISK | 4. <input type="checkbox"/> DETECTION DURING CHECKOUT | 6. <input type="checkbox"/> RECOMMENDED CHANGES BELOW |

☐ FMEA CHANGE RECOMMENDED

EXPLANATION/COMMENTS:

1. Over pressurization will cause a class 2 alarm, V42P1115C, 1116C.

SHUTTLE FAILURE MODE AND EFFECTS ANALYSIS - ORBITER 102

SUBSYSTEM : FWD - REACTION CONTROL FMEA NO G3-2F -10106G-5 REV:01/04/78
 .ASSEMBLY : PRESSURIZATION ABORT: CRIT. FUNC:
 .P/N R1 : MC284-C421-0001/-0002 CRIT. HWD: .3
 .P/N VENDOR: 5760009-101,5760010-102 MISSIONS: HF VF X FF UF SM
 .QUANTITY : 2 PHASE(S): PL X LG X CG X CO X LS
 . : ONE REQ'D PER TANK NUMBER OF SUCCESS PATHS REMAINING
 . : AFTER FIRST FAILURE: 0
 . REDUNDANCY SCREEN: A- B- C-
 .FAILURE DETECTABLE IN FLIGHT?. YES TIME TO EFFECT:
 .TANK PRESSURE MONITOR V42P-1116C,1115C,1210C, SECONDS TO DAYS
 .1310C REFERENCE DOCUMENTS:
 . MJ070-C001-013
 . SPOUND TURNAROUND?.....YES SD72-SH-0103-2
 . SAME AS FLIGHT VS70-421001

PREPARED BY:

DES
REL

R GONZALEZ
R DIEHL

APPROVED BY:

DES
REL

.ITEM: VALVE, PRESS. RELIEF -

. CRCKNG PRESS 315 PSIG, FULL OPEN 340 PSIG, RESEAT 310 PSIG (RV 101/102).

.FUNCTION:

. RELIEF VALVE PROVIDED TO PREVENT RISE OF TANK AND LINE PRESSURES TO LEVELS WHICH COULD BE DETRIMENTAL TO SUBSYSTEM.

.FAILURE MODE: FAILS TO OPEN - (F)

. AT NOMINAL CRACKING PRESSURE .

.CAUSE(S):

. CONTAMINATION, PIECE PART STRUCTURAL FAILURE, PCPPET GALLING.

.EFFECT(S): ON (A)SUBSYSTEM (E)INTERFACES (C)MISSION (D)CREW/VEHICLE:

. (A) LOSS OF RELIEF PATH. (B,D) NONE. (C) POTENTIAL MISSION LOSS

. (ABORT DECISION) IF EARLY IN MISSION WOULD REQUIRE 2 PRIOR FAILURES.

.CORRECTING ACTION:

. FIRE ALL THRUSTERS NON-PROPULSIVELY.

.REMARKS/HAZARDS:

. POTENTIAL TANK RUPTURE ON 3RD ORDER FAILURE NO OTHER RELIEF PATH FOR SYSTEM.

ORIGINAL PAGE IS
OF POOR QUALITY

. HARDWARE/SOFTWARE ANALYSIS CHECKLIST 03-2F-101070-1

SUBSYSTEM Fwd Reaction Control

FMEA NUMBER SD75-SH-0016A

ITEM Fill Quick Disconnect, Helium

FAILURE MODE Fails Open, Cap Leaks

1. DOES THE FLIGHT SOFTWARE DETECT THIS FAILURE MODE (i.e., AUTOMATICALLY ANNUNCIATE OR TAKE ACTION IN RESPONSE)? YES ☒ NO ☐
- 1a. IF NOT, DOES THE HARDWARE PROVIDE INFORMATION THAT THE FLIGHT SOFTWARE COULD USE TO DETECT THE FAILURE? *YES ☐ NO ☐
2. ARE THE ANSWERS TO QUESTIONS 1 AND 1a CONSISTENT WITH THE FMEA EVALUATION OF IN-FLIGHT DETECTABILITY? YES ☐ *NO ☒
3. DOES THE FLIGHT SOFTWARE TAKE ACTION TO NEGATE THE EFFECTS OF THE FAILURE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? YES ☐ NO ☒
- 3a. IF NOT, DOES THE CAPABILITY EXIST FOR THE SOFTWARE TO COMPENSATE FOR THIS FAILURE MODE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? *YES ☐ NO ☒
4. AS A RESULT OF THIS FAILURE MODE, CAN THE SOFTWARE OVERSTRESS THE HARDWARE OR INDUCE ANOTHER FAILURE? *YES ☐ NO ☒
5. CAN THIS FAILURE MODE, IN COMBINATION WITH SOFTWARE LOGIC, ADVERSELY AFFECT OTHER FUNCTIONS? *YES ☐ NO ☒
6. HOW MANY OF THESE HARDWARE FAILURES CAN THE SHUTTLE TOLERATE (CONSIDER CREW ACTION AND HARDWARE/SOFTWARE OPERATION)? NOTE CHANGE TO FMEA CRITICALITY. *0 ☐ *1 ☒ 2 ☐
7. IF CREW ACTION IS REQUIRED TO RESPOND TO THIS FAILURE MODE, ARE CUES PROVIDED TO SIGNAL THE NEED FOR INTERVENTION AND THE REQUIRED CORRECTIVE ACTION? N/A ☐ YES ☒ NO ☐
8. IF THE ANSWER TO EITHER 1 OR 3 IS YES:
 - A. CAN THE BFS BE ENGAGED AFTER OCCURRENCE? YES ☒ *NO ☐
 - B. WILL BFS TOLERATE FAILURE WITHOUT LOSS OF CREW/VEHICLE? YES ☒ *NO ☐

*EXPLANATION REQUIRED (SEE BELOW)

CHANGE/RETENTION RATIONALE SUMMARY

- | | | |
|--|---|--|
| 1. <input type="checkbox"/> NO H/S ISSUES | 3. <input type="checkbox"/> NO SOFTWARE DETECTION | 5. <input type="checkbox"/> ACCEPTANCE RATIONALE BELOW |
| 2. <input checked="" type="checkbox"/> HARDWARE ACCEPTS RISK | 4. <input type="checkbox"/> DETECTION DURING CHECKOUT | 6. <input type="checkbox"/> RECOMMENDED CHANGES BELOW |

In-flight detectability

☒ FMEA CHANGE RECOMMENDED

EXPLANATION/COMMENTS:

1 & 2. V42P1110C, V42P1112C, V42P1113C and V42P1114C will detect the failure when the pressure drops to 500 psi and issue a class 3 caution and warning alert.

Gross leak indication should occur first. (12.6% Δ)

6. Capped quick disconnect provides one redundant success path.

SHUTTLE FAILURE MODE AND EFFECTS ANALYSIS - ORBITER 102

```

SUBSYSTEM : FWD - REACTION CONTROL          FMEA NO C3-2F -101070-1      REV:12/18/70
.ASSEMBLY : PRESSURIZATION                   ABORT:                     CRIT. FUNC:    1
.P/N RI    : MC276-0017-0402/0403           CRIT. HWD:    1
.P/N VENDOR: 75372000-0402/0403             MISSIONS:  HF   VF X FF   CF   SM
.QUANTITY  : 2                               PHASE(S):  PL X LO X GO X DO X LS X
.          : ONE REQ'D PER TANK              NUMBER OF SUCCESS PATHS REMAINING
.          :                               AFTER FIRST FAILURE:                1
.          :                               REDUNDANCY SCREEN:  A-N/A   B-N/A   C-N/A
.FAULTURE DETECTABLE IN FLIGHT?. NO          TIME TO EFFECT:
.                                              SECONDS TO DAYS
.                                              REFERENCE DOCUMENTS:
.                                              MJ070-0001-01E
.                                              SB72-SH-0103-2
.GROUND TURNAROUND?.....YES                VS70-421001
.VISUAL INSPECTION PRIOR TO LAUNCH

```

PREPARED BY:	APPROVED BY:
DES	DES
REL	REL

- .ITEM: DISCONNECT, QUICK FILL
- . HELIUM WITH SPRING LOADED POPPET AND STRUCTURAL END CAP (1/4"). (MD 105/106)
- .FUNCTION:
- . PROVIDES HELIUM TANK FILL POINT FOR GROUND OPERATIONS AND LOADING SERVICING.
- .FAILURE MODE: FAILS OPEN, CAP (S)
- . LEAKS IN EXCESS OF ACCEPTABLE RATE.
- .CAUSE(S):
- . VIBRATION, AND LOOSENING OF THE RETAINER NUT, IMPROPER HANDLING, MECHANICAL SHOCK.
- .EFFECT(S): ON (A)SUBSYSTEM (B)INTERFACES (C)MISSION (D)CREW/VEHICLE:
- . (A) LOSS OF REDUNDANCY. (B) NONE. (C) POTENTIAL LAUNCH DELAY
- . (MISSION LOSS) IF DETECTED. (D) POSSIBLE LOSS OF CREW/VEHICLE IF FAILURE OCCURS PRIOR TO ET SEPARATION.
- .CORRECTING ACTION:
- . REPLACE OR TIGHTEN END CAP ON GROUND. NONE AVAILABLE IN FLIGHT.
- .REMARKS/HAZARDS:
- . BECAUSE STRUCTURAL CAP IS LOADED OVER THE DISCONNECT, THIS FAILURE MODE IS VERY REMOTE IN FLIGHT.

SHUTTLE CRITICAL ITEMS LIST - ORBITER 102

SUBSYSTEM : FWD - REACTION CONTROL FMEA NO 03-2F -101070-1 REV:12/08/78
 . ASSEMBLY : PRESSURIZATION ABORT: CRIT. FUNC: 1
 . P/N RI : MC2 76-0C17-0402/0403 CRIT. HDW: 1
 . P/N VENDOR: 75372000-0402/0403 MISSIONS: HF VF X FF OF SM
 . QUANTITY : 2 PHASE(S): PL X LO X OO X DO X LS X
 . : ONE REQ'D PER TANK
 . :
 . :

REDUNDANCY SCREEN: A-N/A B-N/A C-N/A

. PREPARED BY: APPROVED BY: APPROVED BY (NASA):
 . DES C SCARLETT DES *C. Scarlett 12/13/8* SSM *W. K. K. K.*
 . REL R DIEHL REL *C. E. Garner 12/15/78* REL *W. K. K. K.*
 . :
 . :
 . : APPROVED WITH CHANGES
 . : See Section 13.0

- . ITEM: DISCONNECT, QUICK FILL
- . HELIUM WITH SPRING LOADED POPPET AND STRUCTURAL END CAP (1/4"). (MD 105/106)
- . FUNCTION:
 - . PROVIDES HELIUM TANK FILL POINT FOR GROUND OPERATIONS AND LOADING SERVICING.
- . FAILURE MODE: FAILS OPEN, CAP (S)
 - . LEAKS IN EXCESS OF ACCEPTABLE RATE.
- . CAUSE(S):
 - . VIBRATION, AND LOOSENING OF THE RETAINER NUT, IMPROPER HANDLING, MECHANICAL SHOCK.
- . EFFECT(S): ON (A) SUBSYSTEM (B) INTERFACES (C) MISSION (D) CREW/VEHICLE:
 - . (A) LOSS OF REDUNDANCY. (B) NONE. (C) POTENTIAL LAUNCH DELAY (MISSION LCSS) IF DETECTED. (D) POSSIBLE LOSS OF CREW/VEHICLE IF FAILURE OCCURS PRIOR TO ET SEPARATION.
- . DISPOSITION & RATIONALE (A) DESIGN (B) TEST (C) INSPECTION (D) FAILURE HISTORY:
 - . (A) CAP SEAL DESIGN DETERMINED TO BE ADEQUATE TO PRECLUDE LEAKAGE. DESIGN FACTOR OF SAFETY IS 2.0 X 4000 PSIG MAX WORKING PRESSURE. CAP PLUS COUPLING CONSTITUTES DUAL SEALING. ALL RETAINER NUTS ARE PROPERLY TORQUED TO PRECLUDE LOOSENING. (B) SEALS ARE EXPOSED TO OVER 600 CYCLES DURING DEVELOPMENT. COUPLINGS ARE SUBJECTED TO 600 OPERATIONAL CYCLES IN QUAL TEST. ALL CAPS AND COUPLING LEAK TESTED FOR 3 MIN. AT PRESSURES UP TO 1.25 MAX WORKING PRESSURE DURING ACCEPTANCE TEST. TURNAROUND LEAK CHECKS PERFORMED BEFORE EACH FLIGHT. RANDOM VIBRATION PERFORMED DURING QUAL PROGRAM. 68 MINUTES IN TWO AXES AT ANTICIPATED MISSION LEVELS. (C) TURNAROUND INSPECTION INCLUDES VISUAL INSPECTION ALL COUPLINGS THAT HAVE BEEN USED DURING TURNAROUND FOR DAMAGE PLUS INSPECTING FOR LEAKS DURING LEAK CHECKS. ALSO, PROPER BLEED SCREW TORQUE IS VERIFIED PRIOR TO REINSTALLATION OF ANY CAPS THAT HAVE BEEN REMOVED. SUPPLIER AUDIT CONDUCTED 4-5-77 VERIFIED THAT SUPPLIER INSPECTION CONTROLS RAW MATERIAL PARTS IDENTIFICATION, MFG PROCESSES, CONTAMINATION CONTROL, AND STORAGE ENVIRONMENTS. (D) NEW DESIGN FOR SHUTTLE APPLICATION. NO FLIGHT FAILURE HISTORY

HARDWARE/SOFTWARE ANALYSIS CHECKLIST

03-2F-101070-2

SUBSYSTEM Fwd. Reaction Control

FMEA NUMBER

SD75-SH-0016A

ITEM Quick Fill Disconnect, He.

FAILURE MODE Fails Closed/Ground OPS

1. DOES THE FLIGHT SOFTWARE DETECT THIS FAILURE MODE (i.e., AUTOMATICALLY ANNUNCIATE OR TAKE ACTION IN RESPONSE)? YES ☐ NO ☐
- 1a. IF NOT, DOES THE HARDWARE PROVIDE INFORMATION THAT THE FLIGHT SOFTWARE COULD USE TO DETECT THE FAILURE? *YES ☐ NO ☐
2. ARE THE ANSWERS TO QUESTIONS 1 AND 1a CONSISTENT WITH THE FMEA EVALUATION OF IN-FLIGHT DETECTABILITY? YES ☐ *NO ☐
3. DOES THE FLIGHT SOFTWARE TAKE ACTION TO NEGATE THE EFFECTS OF THE FAILURE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? YES ☐ NO ☐
- 3a. IF NOT, DOES THE CAPABILITY EXIST FOR THE SOFTWARE TO COMPENSATE FOR THIS FAILURE MODE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? *YES ☐ NO ☐
4. AS A RESULT OF THIS FAILURE MODE, CAN THE SOFTWARE OVERSTRESS THE HARDWARE OR INDUCE ANOTHER FAILURE? *YES ☐ NO ☐
5. CAN THIS FAILURE MODE, IN COMBINATION WITH SOFTWARE LOGIC, ADVERSELY AFFECT OTHER FUNCTIONS? *YES ☐ NO ☐
6. HOW MANY OF THESE HARDWARE FAILURES CAN THE SHUTTLE TOLERATE (CONSIDER CREW ACTION AND HARDWARE/SOFTWARE OPERATION)? NOTE CHANGE TO FMEA CRITICALITY. *0 ☐ *1 ☐ 2 ☐
7. IF CREW ACTION IS REQUIRED TO RESPOND TO THIS FAILURE MODE, ARE CUES PROVIDED TO SIGNAL THE NEED FOR INTERVENTION AND THE REQUIRED CORRECTIVE ACTION? N/A ☐ YES ☐ NO ☐
8. IF THE ANSWER TO EITHER 1 OR 3 IS YES:
 - A. CAN THE BFS BE ENGAGED AFTER OCCURRENCE? YES ☐ *NO ☐
 - B. WILL BFS TOLERATE FAILURE WITHOUT LOSS OF CREW/VEHICLE? YES ☐ *NO ☐

*EXPLANATION REQUIRED (SEE BELOW)

CHANGE/RETENTION RATIONALE SUMMARY

- | | | |
|---|---|--|
| 1. <input type="checkbox"/> NO H/S ISSUES | 3. <input type="checkbox"/> NO SOFTWARE DETECTION | 5. <input type="checkbox"/> ACCEPTANCE RATIONALE BELOW |
| 2. <input type="checkbox"/> HARDWARE ACCEPTS RISK | 4. <input type="checkbox"/> DETECTION DURING CHECKOUT | 6. <input type="checkbox"/> RECOMMENDED CHANGES BELOW |

☐ FMEA CHANGE RECOMMENDED

EXPLANATION/COMMENTS:

1. Out of Scope. Ground operations only.

SHUTTLE FAILURE MODE AND EFFECTS ANALYSIS - ORBITER 102

```

SUBSYSTEM : FWD - REACTION CONTROL          FMEA NO 03-2F -101070-2          REV: 01/04/71.
.ASSEMBLY  : PRESSURIZATION                  ABORT:                          CRIT. FUNC:
.P/N RI    : MC276-C017-0402/0403           CRIT. HWD:                      3
.P/N VENDOR: 75372000-0402/0403             MISSIONS:  HF      VF X FF      DF      SM
.QUANTITY  : 2                               PHASE(S):  PL X LG      BG      DG      LS
.          : ONE REQ'D PER TANK              NUMBER OF SUCCESS PATHS REMAINING
.          :                               AFTER FIRST FAILURE:                      0
.          :                               REDUNDANCY SCREEN:  A-N/A      B-N/A      C-N/A
.FAILURE DETECTABLE IN FLIGHT?. N/A          TIME TO EFFECT:
.          :                               IMMEDIATE
.          :                               REFERENCE DOCUMENTS:
.          :                               MJ07C-C001-01B
.          :                               SD72-SH-C103-2
.GROUND TURNAROUND?.....YES                VS70-421001
.GSE FILL RATE AND HELIUM PRESSURE

```

PREPARED BY:

DE S
REL

C SCARLETT
R DIEHL

APPROVED BY:

DES
REL

.ITEM: DISCONNECT, QUICK FILL

- HELIUM WITH SPRING LOADED POPPET AND STRUCTURAL END CAP (1/4"). (MD 105/106)

•FUNCTION:

- PROVIDES HELIUM TANK FILL POINT FOR GROUND OPERATIONS AND LOADING SERVICING.

FAILURE MODE: RESTRICTED FLOW - (F)

• FAILS CLOSED DURING GROUND FILL OPERATIONS

• CAUSE(S):

- VIBRATION/IMPROPER HANDLING WHICH CAUSES FILTER/POPPET DAMAGE IN DISCONNECT.

•EFFECT(S): UN (A)SUBSYSTEM (B)INTERFACES (C)MISSION (D)CREW/VEHICLE:

(A) LOSS OF OR REDUCED HELIUM FILL CAPABILITY. (B) NONE. (C) LAUNCH

• DELAY. (D) NONE.

• CORRECTING ACTION:

- REMOVE/REPLACE FILL VALVE OR ATTEMPT TO RECOUPLE.

REMARKS/HAZARDS:

• NONE. NO REDUNDANCY PROVIDED FOR THIS ITEM IN THIS MODE.

ORIGINAL PAGE IS
OF HIGH QUALITY

1. DOES THE FLIGHT SOFTWARE DETECT THIS FAILURE MODE (i.e., AUTOMATICALLY ANNUNCIATE OR TAKE ACTION IN RESPONSE)? YES ☒ NO ☐
- 1a. IF NOT, DOES THE HARDWARE PROVIDE INFORMATION THAT THE FLIGHT SOFTWARE COULD USE TO DETECT THE FAILURE? *YES ☐ NO ☐
2. ARE THE ANSWERS TO QUESTIONS 1 AND 1a CONSISTENT WITH THE FMEA EVALUATION OF IN-FLIGHT DETECTABILITY? YES ☐ *NO ☒
3. DOES THE FLIGHT SOFTWARE TAKE ACTION TO NEGATE THE EFFECTS OF THE FAILURE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? YES ☐ NO ☒
- 3a. IF NOT, DOES THE CAPABILITY EXIST FOR THE SOFTWARE TO COMPENSATE FOR THIS FAILURE MODE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? *YES ☐ NO ☒
4. AS A RESULT OF THIS FAILURE MODE, CAN THE SOFTWARE OVERSTRESS THE HARDWARE OR INDUCE ANOTHER FAILURE? *YES ☐ NO ☒
5. CAN THIS FAILURE MODE, IN COMBINATION WITH SOFTWARE LOGIC, ADVERSELY AFFECT OTHER FUNCTIONS? *YES ☐ NO ☒
6. HOW MANY OF THESE HARDWARE FAILURES CAN THE SHUTTLE TOLERATE (CONSIDER CREW ACTION AND HARDWARE/SOFTWARE OPERATION)? NOTE CHANGE TO FMEA CRITICALITY. *0 ☐ *1 ☒ 2 ☐
7. IF CREW ACTION IS REQUIRED TO RESPOND TO THIS FAILURE MODE, ARE CUES PROVIDED TO SIGNAL THE NEED FOR INTERVENTION AND THE REQUIRED CORRECTIVE ACTION? N/A ☐ YES ☒ NO ☐
8. IF THE ANSWER TO EITHER 1 OR 3 IS YES:
 - A. CAN THE BFS BE ENGAGED AFTER OCCURRENCE? YES ☐ *NO ☐
 - B. WILL BFS TOLERATE FAILURE WITHOUT LOSS OF CREW/VEHICLE? YES ☐ *NO ☐

*EXPLANATION REQUIRED (SEE BELOW)

CHANGE/RETENTION RATIONALE SUMMARY

- | | | |
|--|---|--|
| 1. <input type="checkbox"/> NO H/S ISSUES | 3. <input type="checkbox"/> NO SOFTWARE DETECTION | 5. <input type="checkbox"/> ACCEPTANCE RATIONALE BELOW |
| 2. <input checked="" type="checkbox"/> HARDWARE ACCEPTS RISK | 4. <input type="checkbox"/> DETECTION DURING CHECKOUT | 6. <input type="checkbox"/> RECOMMENDED CHANGES BELOW |

☒ FMEA CHANGE RECOMMENDED

EXPLANATION/COMMENTS:

1. Per backup flight system program requirements document MG038103, once a pre-set delta between the propellant quantities is reached a class 2 caution and warning light and tone will be annunciated. Also primary flight control requirements FSSR 0026A except OPS 1,6.
2. The above statement indicates in-flight detection.
6. Capped quick disconnect provides one redundant success path.

SHUTTLE FAILURE MODE AND EFFECTS ANALYSIS - ORBITER 102

```
SUBSYSTEM : FWD - REACTION CONTROL          FMEA NO 03-2F -10109C-1      REV:12/08/76
.ASSEMBLY  : PRESSURIZATION                  ABORT:                      CRIT. FUNC:    I
.P/N RI    : MC276-CC13                     CRIT. HWD:    I
.P/N VENDOR: 763060G0                        MISSIONS:   HF     VF X FF     CF     SM
.QUANTITY  : 14                             PHASE(S):   PL     LG X GJ X DO X LS
.          : TWO INLETS AND FIVE             NUMBER OF SUCCESS PATHS REMAINING
.          : OUTLETS FOR EACH PROP           AFTER FIRST FAILURE:
. REDUNDANCY SCREEN: A-N/A B-N/A C-N/A
.FAILURE DETECTABLE IN FLIGHT?. NO            TIME TO EFFECT:
. SECONDS TO DAYS
. REFERENCE DOCUMENTS:
. MJ070-CGC1-01B
.GROUND TURNAROUND?.....YES                SD72-SH-9103-2
.VISUAL INSPECTION                          VS70-421001
```

PREPARED BY:

DE S

KEL

C SCARLETT

R DIEHL

APPROVED BY:

DES

REL

- .ITEM: DISCONNECT, QCK, PURGE, 12/10
- . VENT, PROPELLANT WITH STRUCTURAL END CAP AND SPRING LOADED POPPET (1/2"). (MD 117,118,123,124,127,137,138,147,161,162,163,164).
- .FUNCTION:
- . TO ALLOW GROUND PURGE OF PROPELLANT TANKS AND ASSOCIATED MANIFOLDS/LINES/THRUSTERS AFTER LANDING & PROPELLANT TANKS FILL, DRAIN & VENT
- .FAILURE MODE: EXTERNAL LEAKAGE (S)
- . DURING FLIGHT
- .CAUSE(S):
- . VIBRATION AND LOOSENING OF THE RETAINER NUT, STRUCTURAL FAILURE, PIECE PART FAILURE MECHANICAL SHOCK, IMPROPER GROUND HANDLING.
- .EFFECT(S): (A)SUBSYSTEM (B)INTERFACES (C)MISSION (D)CREW/VEHICLE:
- . (A) LOSS OF PROPELLANT FIRST ORDER FAILURE FOR LOOSE RETAINER NUT. (B) POSSIBLE FIRE/EXPLOSION IF FUEL REACTS WITH COMPLEMENTARY OXIDIZER (OK EXTREME HEAT DURING RE-ENTRY).(C) POSSIBLE LOSS OF MISSION DUE TO FLUID SEPARATION. (D) POSSIBLE LOSS OF CREW/VEHICLE IF FAILURE OCCURS PRIOR TO ET SEPARATION.
- .CORRECTING ACTION:
- . NONE AVAILABLE - IN FORWARD MODULE, CRITICALITY IS LESS SEVERE IF AFT MODULES OPERATIVE
- .REMARKS/HAZARDS:
- . POTENTIAL CORROSION OF SURROUNDING COMPONENTS. STRUCTURAL CAP CONSIDERED AS STRUCTURE.

SHUTTLE CRITICAL ITEMS LIST - ORBITER 102

SUBSYSTEM : FWD - REACTION CONTROL FMEA NO 03-2F -101080-1 REV: 12/08/77
 .ASSEMBLY : PRESSURIZATION ABORT: CRIT. FUNC: 1
 .P/N RI : MC276-0018 CRIT. HOW: 1
 .P/N VENDOR: 76306000 MISSIONS: HF VF X FF OF SM
 .QUANTITY : 14 PHASE(S): PL LO X OC X DO X LS
 . : TWO INLETS AND FIVE
 . : OUTLETS FOR EACH PROP
 . :
 . : REDUNDANCY SCREEN: A-N/A B-N/A C-N/A

.PREPARED BY: APPROVED BY: APPROVED BY (NASA):
 .DES C SCARLETT DES *C. Scarlett* 12/13/8 SSM *W. Karst*
 .REL R DIEHL REL *R. Diehl* 12/15/76 REL *R. Diehl*
 . :
 . : APPROVED WITH CHANGES
 . : See Section 13.0

- .ITEM: DISCONNECT, QCK, PURGE,
- . VENT, PROPELLANT WITH STRUCTURAL END CAP AND SPRING LOADED POPPET (1/2"). (MD 117,118,123,124,127,137,138,147,161,162,163,164).
- .FUNCTION:
- . TO ALLOW GROUND PURGE OF PROPELLANT TANKS AND ASSOCIATED MANIFOLDS/LINES/THRUSTERS AFTER LANDING & PROPELLANT TANKS FILL, DRAIN & VENT
- .FAILURE MODE: EXTERNAL LEAKAGE (S)
- . DURING FLIGHT
- .CAUSE(S):
- . VIBRATION AND LOOSENING OF THE RETAINER NUT, STRUCTURAL FAILURE, PIECE PART FAILURE MECHANICAL SHOCK, IMPROPER GROUND HANDLING.
- .EFFECT(S): ON (A)SUBSYSTEM (B)INTERFACES (C)MISSION (D)CREW/VEHICLE:
- . (A) LOSS OF PROPELLANT FIRST ORDER FAILURE FOR LOOSE RETAINER NUT. (B) POSSIBLE FIRE/EXPLOSION IF FUEL REACTS WITH COMPLEMENTARY OXIDIZER (OR EXTREME HEAT DURING RE-ENTRY). (C) POSSIBLE LOSS OF MISSION DUE TO FLUID SEPARATION. (D) POSSIBLE LOSS OF CREW/VEHICLE IF FAILURE OCCURS PRIOR TO ET SEPARATION.
- .DISPOSITION & RATIONALE (A)DESIGN (B)TEST (C)INSPECTION (D)FAILURE HISTORY:
- . (A) CAP SEAL DESIGN DETERMINED TO BE ADEQUATE TO PRECLUDE LEAKAGE. DESIGN FACTOR OF SAFETY IS 3.0 X 710 PSIG MAX WORKING PRESSURE. CAP PLUS COUPLING CONSTITUTES DUAL SEALING. ALL RETAINER NUTS ARE PROPERLY TORQUED TO PRECLUDE LOOSENING. (B) SEALS ARE EXPOSED TO OVER 500 CYCLES DURING DEVELOPMENT. COUPLINGS ARE SUBJECTED TO 600 OPERATIONAL CYCLES IN QUAL TEST. ALL CAPS AND COUPLINGS LEAK TESTED FOR 3 MINUTES AT PRESSURES UP TO MAX WORKING PRESSURE DURING ACCEPTANCE TEST. TURNAROUND LEAK CHECKS PERFORMED BEFORE EACH FLIGHT. RANDOM VIBRATION PERFORMED DURING QUAL PROGRAM. 68 MINUTES IN TWO AXES AT ANTICIPATED MISSION LEVELS. (C) TURNAROUND INSPECTION INCLUDES VISUAL INSPECTING ALL COUPLINGS USED DURING TURNAROUND FOR DAMAGE PLUS INSPECTING FOR LEAKS DURING LEAK CHECKS. ALSO, PROPER BLEED SCREW TORQUE IS VERIFIED PRIOR TO REINSTALLATION OF ANY CAPS THAT HAVE BEEN REMOVED. SUPPLIER AUDIT CONDUCTED 4-5-77 VERIFIED THAT SUPPLIER INSPECTION CONTROLS RAW MATERIAL PARTS IDENTIFICATION, MFG PROCESSES, CONTAMINATION CONTROL, AND STORAGE ENVIRONMENTS. (D) NEW DESIGN FOR SHUTTLE APPLICATION. NO FLIGHT FAILURE HISTORY.

ORIGINAL PAGE IS
 OF POOR QUALITY

1028
 49

SD75-SH-0003

HARDWARE/SOFTWARE ANALYSIS CHECKLIST 03-2F-101080-2

SUBSYSTEM Fwd. Reaction Control

FMEA NUMBER

SD75-SH-0016A

ITEM Purge Quick Disconnect, PropellantFAILURE MODE Fails Closed/Ground Ops.

1. DOES THE FLIGHT SOFTWARE DETECT THIS FAILURE MODE (i.e., AUTOMATICALLY ANNUNCIATE OR TAKE ACTION IN RESPONSE)? YES ☐ NO ☐
- 1a. IF NOT, DOES THE HARDWARE PROVIDE INFORMATION THAT THE FLIGHT SOFTWARE COULD USE TO DETECT THE FAILURE? *YES ☐ NO ☐
2. ARE THE ANSWERS TO QUESTIONS 1 AND 1a CONSISTENT WITH THE FMEA EVALUATION OF IN-FLIGHT DETECTABILITY? YES ☐ *NO ☐
3. DOES THE FLIGHT SOFTWARE TAKE ACTION TO NEGATE THE EFFECTS OF THE FAILURE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? YES ☐ NO ☐
- 3a. IF NOT, DOES THE CAPABILITY EXIST FOR THE SOFTWARE TO COMPENSATE FOR THIS FAILURE MODE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? *YES ☐ NO ☐
4. AS A RESULT OF THIS FAILURE MODE, CAN THE SOFTWARE OVERSTRESS THE HARDWARE OR INDUCE ANOTHER FAILURE? *YES ☐ NO ☐
5. CAN THIS FAILURE MODE, IN COMBINATION WITH SOFTWARE LOGIC, ADVERSELY AFFECT OTHER FUNCTIONS? *YES ☐ NO ☐
6. HOW MANY OF THESE HARDWARE FAILURES CAN THE SHUTTLE TOLERATE (CONSIDER CREW ACTION AND HARDWARE/SOFTWARE OPERATION)? NOTE CHANGE TO FMEA CRITICALITY. *0 ☐ *1 ☐ 2 ☐
7. IF CREW ACTION IS REQUIRED TO RESPOND TO THIS FAILURE MODE, ARE CUES PROVIDED TO SIGNAL THE NEED FOR INTERVENTION AND THE REQUIRED CORRECTIVE ACTION? N/A ☐ YES ☐ NO ☐
8. IF THE ANSWER TO EITHER 1 OR 3 IS YES:
- A. CAN THE BFS BE ENGAGED AFTER OCCURRENCE? YES ☐ *NO ☐
- B. WILL BFS TOLERATE FAILURE WITHOUT LOSS OF CREW/VEHICLE? YES ☐ *NO ☐

*EXPLANATION REQUIRED (SEE BELOW)

CHANGE/RETENTION RATIONALE SUMMARY

- | | | |
|---|---|--|
| 1. <input type="checkbox"/> NO H/S ISSUES | 3. <input type="checkbox"/> NO SOFTWARE DETECTION | 5. <input type="checkbox"/> ACCEPTANCE RATIONALE BELOW |
| 2. <input type="checkbox"/> HARDWARE ACCEPTS RISK | 4. <input type="checkbox"/> DETECTION DURING CHECKOUT | 6. <input type="checkbox"/> RECOMMENDED CHANGES BELOW |

☐ FMEA CHANGE RECOMMENDEDEXPLANATION/COMMENTS:

1. Out of scope/ground operations only.

SHUTTLE FAILURE MODE AND EFFECTS ANALYSIS - ORBITER 102

SUBSYSTEM : FWD - REACTION CONTROL FMEA NO 03-2F -101080-2 REV: 03/16/71
 .ASSEMBLY : PRESSURIZATION ABORT: CRIT. FUNC:
 .P/N RI : MC276-0018 CRIT. FWD: 1
 .P/N VENDOR: 76306000 MISSIONS: HF VF X FF CF SM
 .QUANTITY : 14 PHASE(S): PL X LG GG DG LS
 . : TWO INLETS AND FIVE NUMBER OF SUCCESS PATHS REMAINING
 . : OUTLETS FOR EACH PROP AFTER FIRST FAILURE: 1
 . REDUNDANCY SCREEN: A-N/A B-N/A C-N/A
 . FAILURE DETECTABLE IN FLIGHT? N/A TIME TO EFFECT:
 . IMMEDIATE
 . REFERENCE DOCUMENTS:
 . MJ070-0001-01E
 . SD72-SH-0103-2
 . VS70-421001
 . GROUND TURNAROUND?YES
 . GSE EQUIPMENT FLOW RATE AND TANK OUTPUT
 . PRESSURE V42F-1210C, 1310C
 .
 . PREPARED BY: DES C SCARLETT APPROVED BY: DES _____
 . REL R DIEHL REL _____
 .
 . ITEM: DISCONNECT, QCK, PURGE,
 . VENT, PROPELLANT WITH STRUCTURAL END CAP AND SPRING LOADED POPPET
 . (1/2"). (MD 117,118,123,124,127,137,138,147,161,162,163,164).
 . FUNCTION:
 . TO ALLOW GROUND PURGE OF PROPELLANT TANKS AND ASSOCIATED
 . MANIFOLDS/LINES/THRUSTERS AFTER LANDING & PROPELLANT TANKS FILL, DRAIN
 . & VENT
 . FAILURE MODE: FAILS CLOSED (F)
 . DURING GROUND OPERATIONS
 . CAUSE(S):
 . CONTAMINATION PIECE PART STRUCTURAL FAILURE, MECHANICAL SHOCK.
 . EFFECT(S): ON (A) SUBSYSTEM (B) INTERFACES (C) MISSION (D) CREW/VEHICLE:
 . (A) LOSS OF PURGE FUNCTION. (B) NO EFFECT. (C) POTENTIAL LAUNCH
 . DELAY. (D) NONE.
 . CORRECTING ACTION:
 . ATTEMPT TO REMOVE BLOCKAGE (BACK-FLOW) OR REMOVE COUPLING AND REPLACE
 . REMARKS/HAZARDS:
 . NONE. NO REDUNDANCY PROVIDED FOR THIS ITEM.

HARDWARE/SOFTWARE ANALYSIS CHECKLIST

03-2F-101090-1

SUBSYSTEM Fwd. Reaction Control

FMEA NUMBER _____

ITEM Test Quick Disconnect, Propellant

FAILURE MODE Ext. Leakage/Flight

1. DOES THE FLIGHT SOFTWARE DETECT THIS FAILURE MODE (i.e., AUTOMATICALLY ANNUNCIATE OR TAKE ACTION IN RESPONSE)? YES ☒ NO ☐
- 1a. IF NOT, DOES THE HARDWARE PROVIDE INFORMATION THAT THE FLIGHT SOFTWARE COULD USE TO DETECT THE FAILURE? *YES ☐ NO ☐
2. ARE THE ANSWERS TO QUESTIONS 1 AND 1a CONSISTENT WITH THE FMEA EVALUATION OF IN-FLIGHT DETECTABILITY? YES ☐ *NO ☐
3. DOES THE FLIGHT SOFTWARE TAKE ACTION TO NEGATE THE EFFECTS OF THE FAILURE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? YES ☐ NO ☒
- 3a. IF NOT, DOES THE CAPABILITY EXIST FOR THE SOFTWARE TO COMPENSATE FOR THIS FAILURE MODE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? *YES ☐ NO ☒
4. AS A RESULT OF THIS FAILURE MODE, CAN THE SOFTWARE OVERSTRESS THE HARDWARE OR INDUCE ANOTHER FAILURE? *YES ☐ NO ☒
5. CAN THIS FAILURE MODE, IN COMBINATION WITH SOFTWARE LOGIC, ADVERSELY AFFECT OTHER FUNCTIONS? *YES ☐ NO ☒
6. HOW MANY OF THESE HARDWARE FAILURES CAN THE SHUTTLE TOLERATE (CONSIDER CREW ACTION AND HARDWARE/SOFTWARE OPERATION)? NOTE CHANGE TO FMEA CRITICALITY. *0 ☐ *1 ☒ 2 ☐
7. IF CREW ACTION IS REQUIRED TO RESPOND TO THIS FAILURE MODE, ARE CUES PROVIDED TO SIGNAL THE NEED FOR INTERVENTION AND THE REQUIRED CORRECTIVE ACTION? N/A ☐ YES ☒ NO ☐
8. IF THE ANSWER TO EITHER 1 OR 3 IS YES:
 - A. CAN THE BFS BE ENGAGED AFTER OCCURRENCE? YES ☒ *NO ☐
 - B. WILL BFS TOLERATE FAILURE WITHOUT LOSS OF CREW/VEHICLE? YES ☒ *NO ☐

*EXPLANATION REQUIRED (SEE BELOW)

CHANGE/RETENTION RATIONALE SUMMARY

- | | | |
|--|---|--|
| 1. <input type="checkbox"/> NO H/S ISSUES | 3. <input type="checkbox"/> NO SOFTWARE DETECTION | 5. <input type="checkbox"/> ACCEPTANCE RATIONALE BELOW |
| 2. <input checked="" type="checkbox"/> HARDWARE ACCEPTS RISK | 4. <input type="checkbox"/> DETECTION DURING CHECKOUT | 6. <input type="checkbox"/> RECOMMENDED CHANGES BELOW |

☐ FMEA CHANGE RECOMMENDED

EXPLANATION/COMMENTS:

1 & 2. V42P1110C, V42P1112C and V42P1113C will detect the failure and issue class 3 alarm (system management blue light on crew-cockpit glare shield) at <500 psia.

Gross leak indication is quicker (class 2).

6. Capped quick disconnect provides one redundant success path.

SHUTTLE FAILURE MODE AND EFFECTS ANALYSIS - ORBITER 102

SUBSYSTEM : FWD - REACTION CONTROL FMEA NO 03-2F -101090-1 REV: 11/09/78
 .ASSEMBLY : PRESSURIZATION ABORT: CRIT. FUNC: 1K
 .P/N RI : ME276-0032 CRIT. HWL: 3
 .P/N VENDOR: RR42670-5&7, R642500-1&3 MISSIONS: HF VF X FF OF SM
 .QUANTITY : 14 PHASE(S): PL LU X OU X DU X LS
 . : SEVEN REQ'D FOR EACH NUMBER OF SUCCESS PATHS REMAINING
 . : PROPELLANT AFTER FIRST FAILURE: 1
 . REDUNDANCY SCREEN: A-PASS B-FAIL C-PASS
 .FAILURE DETECTABLE IN FLIGHT? YES TIME TO EFFECT:
 .HELIUM TANK PRESSURE V42P-1110C, 1112C, 1113C, SECONDS TO DAYS
 .1114C REFERENCE DOCUMENTS:
 . MJ070-0001-01B
 . S072-SH-0103-2
 . S070-421001
 . SPOUND TURNAROUND?.....N/A

PREPARED BY:

DES

REL

C SCARLETT

R DIEHL

APPROVED BY:

DES

REL

.ITEM: DISCONNECT, QUICK, TEST
 . PT. (1/4") WITH SPRING LOADED POPPET AND STRUCTURAL CAP. (MD 101, 102, 103, 104, 107, 108, 109, 110, 111, 112, 113, 114, 177 & 178).
 .FUNCTION:
 . TO PROVIDE ACCESS TO THE HELIUM SUPPLY SYSTEM AT VARIOUS POINTS IN THE SYSTEM: (1) RELIEF VALVES/BURST DISCS (2) REGULATORS (3) CHECK VALVES. PROVIDES FOR C/O OF PRESSURIZATION SUB-SYS COMPONENTS. COMPONENT INPUTS & OUTPUTS ARE ACCESSABLE AT THE SERVICE PANEL.
 .FAILURE MODE: EXTERNAL LEAKAGE (S)
 . DURING FLIGHT
 .CAUSE(S):
 . VIBRATION, PIECE PART STRUCTURAL FAILURE (POPPET, SEAL), MECHANICAL SHOCK.
 .EFFECT(S): ON (A) SUBSYSTEM (B) INTERFACES (C) MISSION (D) CREW/VEHICLE:
 . (A) LOSS OF HELIUM PRESSURANT. (SECOND ORDER FAILURE). (B) LOSS OF PROPELLANT FEED CAPABILITY. (C) POTENTIAL LOSS OF MISSION DUE TO FLUID LOSS. (D) NONE. (E) FUNCTIONAL CRITICALITY EFFECTS - POTENTIAL LOSS OF HELIUM SUPPLY WHICH COULD RESULT IN LOSS OF VEHICLE IF THE LOSS OCCURRED BEFORE ET SEPARATION.
 .CORRECTING ACTION:
 . UTILIZE AFT MODULES TO ORIENT VEHICLE FOR ENTRY AND COMPLETE ABORT.
 .REMARKS/HAZARDS:
 . NONE.

SHUTTLE CRITICAL ITEMS LIST - ORBITER 102

SUBSYSTEM : FWD - REACTION CONTROL FMEA NO 03-2F -101090-1 REV: 11/09/
 . ASSEMBLY : PRESSURIZATION ABORT: CRIT. FUNC: 1R
 . P/N RI : ME276-0032 CRIT. HOW: 3
 . P/N VENDOR: RR42670-5&7, R642900-1&3 MISSIONS: HF VF X FF OF SM
 . QUANTITY : 14 PHASE(S): PL LO X CO X DO X LS
 . : SEVEN REQ'D FOR EACH
 . : PROPELLANT

REDUNDANCY SCREEN: A-PASS B-FAIL C-PA

PREPARED BY: APPROVED BY: APPROVED BY (NASA)
 . DES C SCARLETT DES *C. Scarlett 12/7/8* SSM *W. H. H. H.*
 . REL R DIEHL REL *C. E. D. D. 12/15/8* RE *W. H. H. H.*

APPROVED WITH CHANGES
 See Section 13.0

- . ITEM: DISCONNECT, QUICK, TEST
- . PT. (1/4") WITH SPRING LOADED POPPET AND STRUCTURAL CAP. (MD 101, 102, 103, 104, 107, 108, 109, 110, 111, 112, 113, 114, 177 & 178).
- . FUNCTION:
 - . TO PROVIDE ACCESS TO THE HELIUM SUPPLY SYSTEM AT VARIOUS POINTS IN THE SYSTEM: (1) RELIEF VALVES/BURST DISCS (2) REGULATORS (3) CHECK VALVES. PROVIDES FOR C/O OF PRESSURIZATION SUB-SYS COMPONENTS. COMPONENT INPUTS & OUTPUTS ARE ACCESSABLE AT THE SERVICE PANEL.
- . FAILURE MODE: EXTERNAL LEAKAGE (S)
- . DURING FLIGHT
- . CAUSE(S):
 - . VIBRATION, PIECE PART STRUCTURAL FAILURE (POPPET, SEAL), MECHANICAL SHOCK.
- . EFFECT(S): ON (A) SUBSYSTEM (B) INTERFACES (C) MISSION (D) CREW/VEHICLE:
 - . (A) LOSS OF HELIUM PRESSURANT. (SECOND ORDER FAILURE). (B) LOSS OF PROPELLANT FEED CAPABILITY. (C) POTENTIAL LOSS OF MISSION DUE TO FLUID LOSS. (D) NONE. (E) FUNCTIONAL CRITICALITY EFFECTS - POTENTIAL LOSS OF HELIUM SUPPLY WHICH COULD RESULT IN LOSS OF VEHICLE IF THE LOSS OCCURRED BEFORE ET SEPARATION.
- . DISPOSITION & RATIONALE (A) DESIGN (B) TEST (C) INSPECTION (D) FAILURE HISTORY:
 - . (A) DUAL SEALING SURFACES ON CAP WILL PRECLUDE FAILURE. EACH SEALING SURFACE INDEPENDANT OF THE OTHER DESIGN BURST PRESSURE IS TWO TIMES OPER PRESSURE. (B) EACH COUPLING PROOF TESTED TO AT LEAST 1.5 OPER PRESSURE & LEAK TESTED FOR 15 MIN DURING ACCEPTANCE TESTING. (C) AUDIT CONDUCTED ON 11-3-76 VERIFY THAT SUPPLIER INSPECT. INCLUDES VERIFY. OF RAW MAT'L. PARTS MFG, IDENTIFICATION, AND PROTECTION, ASSY OPERATIONS, NOE EXAM OF WELDS, BRAZES, AND MAT'L AND EQUIP CONFORMANCE. TURNAROUND INSPECTION INCLUDES VISUALLY INSPECTING ALL COUPLINGS THAT HAVE BEEN USED FOR DAMAGE AND LEAKAGE. ALSO, PROPER AHC CAP TORQUE IS VERIFIED UPON REINSTALLATION OF ANY CAPS THAT HAVE BEEN REMOVED. (D) 14 NON-FLIGHT EXTERNAL LEAKAGE FAILURES EXPERIENCED ON LH/SM RCS DUE TO PROCESS DEFICIENCIES.

SUBSYSTEM Fwd. Reaction Control

FMEA NUMBER

SD75-SH-0016A

ITEM Test Quick Disconnect, Propellant

FAILURE MODE Fails Closed/Ground Ops

- | | |
|--|---|
| 1. DOES THE FLIGHT SOFTWARE DETECT THIS FAILURE MODE (i.e., AUTOMATICALLY ANNUNCIATE OR TAKE ACTION IN RESPONSE)? | YES <input type="checkbox"/> NO <input type="checkbox"/> |
| 1a. IF NOT, DOES THE HARDWARE PROVIDE INFORMATION THAT THE FLIGHT SOFTWARE COULD USE TO DETECT THE FAILURE? | *YES <input type="checkbox"/> NO <input type="checkbox"/> |
| 2. ARE THE ANSWERS TO QUESTIONS 1 AND 1a CONSISTENT WITH THE FMEA EVALUATION OF IN-FLIGHT DETECTABILITY? | YES <input type="checkbox"/> *NO <input type="checkbox"/> |
| 3. DOES THE FLIGHT SOFTWARE TAKE ACTION TO NEGATE THE EFFECTS OF THE FAILURE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? | YES <input type="checkbox"/> NO <input type="checkbox"/> |
| 3a. IF NOT, DOES THE CAPABILITY EXIST FOR THE SOFTWARE TO COMPENSATE FOR THIS FAILURE MODE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? | *YES <input type="checkbox"/> NO <input type="checkbox"/> |
| 4. AS A RESULT OF THIS FAILURE MODE, CAN THE SOFTWARE OVERSTRESS THE HARDWARE OR INDUCE ANOTHER FAILURE? | *YES <input type="checkbox"/> NO <input type="checkbox"/> |
| 5. CAN THIS FAILURE MODE, IN COMBINATION WITH SOFTWARE LOGIC, ADVERSELY AFFECT OTHER FUNCTIONS? | *YES <input type="checkbox"/> NO <input type="checkbox"/> |
| 6. HOW MANY OF THESE HARDWARE FAILURES CAN THE SHUTTLE TOLERATE (CONSIDER CREW ACTION AND HARDWARE/SOFTWARE OPERATION)? NOTE CHANGE TO FMEA CRITICALITY. | *0 <input type="checkbox"/> *1 <input type="checkbox"/> 2 <input type="checkbox"/> |
| 7. IF CREW ACTION IS REQUIRED TO RESPOND TO THIS FAILURE MODE, ARE CUES PROVIDED TO SIGNAL THE NEED FOR INTERVENTION AND THE REQUIRED CORRECTIVE ACTION? | N/A <input type="checkbox"/> YES <input type="checkbox"/> NO <input type="checkbox"/> |
| 8. IF THE ANSWER TO EITHER 1 OR 3 IS YES: | |
| A. CAN THE BFS BE ENGAGED AFTER OCCURRENCE? | YES <input type="checkbox"/> *NO <input type="checkbox"/> |
| B. WILL BFS TOLERATE FAILURE WITHOUT LOSS OF CREW/VEHICLE? | YES <input type="checkbox"/> *NO <input type="checkbox"/> |

*EXPLANATION REQUIRED (SEE BELOW)

CHANGE/RETENTION RATIONALE SUMMARY

- | | | |
|---|---|--|
| 1. <input type="checkbox"/> NO H/S ISSUES | 3. <input type="checkbox"/> NO SOFTWARE DETECTION | 5. <input type="checkbox"/> ACCEPTANCE RATIONALE BELOW |
| 2. <input type="checkbox"/> HARDWARE ACCEPTS RISK | 4. <input type="checkbox"/> DETECTION DURING CHECKOUT | 6. <input type="checkbox"/> RECOMMENDED CHANGES BELOW |

☐ FMEA CHANGE RECOMMENDED

EXPLANATION/COMMENTS:

1. Out of scope - ground operations only.

SHUTTLE FAILURE MODE AND EFFECTS ANALYSIS - ORBITER 102

SUBSYSTEM : FWD - REACTION CONTROL FMEA NO 03-2F -101090-2 REV:03/06/71
 .ASSEMBLY : PRESSURIZATION ABORT: CRIT. FUNC:
 .P/N RI : ME276-0032 CRIT. FWD: 3
 .P/N VENDOR: RR4267G-5&7,R642900-1&3 MISSIONS: HF VF X FF UF SM
 .QUANTITY : 14 PHASE(S): PL X LG GG DD LS
 . : SEVEN REQ'D FOR EACH NUMBER OF SUCCESS PATHS REMAINING
 . : PROPELLANT AFTER FIRST FAILURE: 1
 . REDUNDANCY SCREEN: A-PASS B-N/A C-PAS:
 .FAILURE DETECTABLE IN FLIGHT?. N/A TIME TO EFFECT:
 . SECONDS TO HOURS
 . REFERENCE DOCUMENTS:
 . MJ070-0001-018
 . SD72-SH-0103-2
 . V570-421:01
 . GROUND TURNAROUND?.....YES
 .NO PRESSURE READ-OUT V42P-1110C,1112C,1113C,
 .1114C
 .
 .
 .
 . PREPARED BY: DES C SCARLETT APPROVED BY: DES _____
 . REL R DIEHL REL _____
 .
 .
 .ITEM: DISCONNECT, QUICK, TEST
 . PT. (1/4") WITH SPRING LOADED POPPET AND STRUCTURAL CAP. (MD 101,102,
 103,104,107,108,109,110,111,112,113,114,177 & 178).
 .FUNCTION:
 . TO PROVIDE ACCESS TO THE HELIUM SUPPLY SYSTEM AT VARIOUS POINTS IN THE
 SYSTEM: (1) RELIEF VALVES/BURST DISCS (2) REGULATORS (3) CHECK VALVES.
 PROVIDES FOR C/O OF PRESSURIZATION SUB-SYS COMPONENTS. COMPONENT
 INPUTS & OUTPUTS ARE ACCESSABLE AT THE SERVICE PANEL.
 .FAILURE MODE: FAILS CLOSED (F)
 . DURING TURN-AROUND/GROUND OPERATIONS
 .CAUSE(S):
 . CONTAMINATION, PIECE PART STRUCTURAL FAILURE (POPPET, SEAL).
 .EFFECT(S): ON (A)SUBSYSTEM (B)INTERFACES (C)MISSION (D)CREW/VEHICLE:
 . (A) LOSS OF TEST/CHECKOUT DATA. (B) INCREASED GROUND EQUIPMENT
 . REQUIREMENTS. (C) POTENTIAL MISSION LAUNCH DELAY. (D) NONE.
 .CORRECTING ACTION:
 . TEST AT ALTERNATE POINT (IF AVAILABLE) OR REMOVE AND REPLACE COUPLING.
 .REMARKS/HAZARDS:
 . NONE.

ORIGINAL PAGE IS
OF POOR QUALITY

HARDWARE/SOFTWARE ANALYSIS CHECKLIST 03-2F-101095-1

SUBSYSTEM Fwd. Reaction Control FMEA NUMBER SD75-SH-0016A

ITEM Helium Quad Check Valve FAILURE MODE Fails Open

1. DOES THE FLIGHT SOFTWARE DETECT THIS FAILURE MODE (i.e., AUTOMATICALLY ANNUNCIATE OR TAKE ACTION IN RESPONSE)? YES ☐ NO ☒
- 1a. IF NOT, DOES THE HARDWARE PROVIDE INFORMATION THAT THE FLIGHT SOFTWARE COULD USE TO DETECT THE FAILURE? *YES ☐ NO ☐
2. ARE THE ANSWERS TO QUESTIONS 1 AND 1a CONSISTENT WITH THE FMEA EVALUATION OF IN-FLIGHT DETECTABILITY? YES ☒ *NO ☐
3. DOES THE FLIGHT SOFTWARE TAKE ACTION TO NEGATE THE EFFECTS OF THE FAILURE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? YES ☐ NO ☒
- 3a. IF NOT, DOES THE CAPABILITY EXIST FOR THE SOFTWARE TO COMPENSATE FOR THIS FAILURE MODE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? *YES ☐ NO ☒
4. AS A RESULT OF THIS FAILURE MODE, CAN THE SOFTWARE OVERSTRESS THE HARDWARE OR INDUCE ANOTHER FAILURE? *YES ☐ NO ☒
5. CAN THIS FAILURE MODE, IN COMBINATION WITH SOFTWARE LOGIC, ADVERSELY AFFECT OTHER FUNCTIONS? *YES ☐ NO ☒
6. HOW MANY OF THESE HARDWARE FAILURES CAN THE SHUTTLE TOLERATE (CONSIDER CREW ACTION AND HARDWARE/SOFTWARE OPERATION)? NOTE CHANGE TO FMEA CRITICALITY. *0 ☐ *1 ☐ 2 ☒
7. IF CREW ACTION IS REQUIRED TO RESPOND TO THIS FAILURE MODE, ARE CUES PROVIDED TO SIGNAL THE NEED FOR INTERVENTION AND THE REQUIRED CORRECTIVE ACTION? N/A ☒ YES ☐ NO ☐
8. IF THE ANSWER TO EITHER 1 OR 3 IS YES:
 - A. CAN THE BFS BE ENGAGED AFTER OCCURRENCE? YES ☒ *NO ☐
 - B. WILL BFS TOLERATE FAILURE WITHOUT LOSS OF CREW/VEHICLE? YES ☒ *NO ☐

*EXPLANATION REQUIRED (SEE BELOW)

CHANGE/RETENTION RATIONALE SUMMARY

- | | | |
|--|---|--|
| 1. <input checked="" type="checkbox"/> NO H/S ISSUES | 3. <input type="checkbox"/> NO SOFTWARE DETECTION | 5. <input type="checkbox"/> ACCEPTANCE RATIONALE BELOW |
| 2. <input type="checkbox"/> HARDWARE ACCEPTS RISK | 4. <input type="checkbox"/> DETECTION DURING CHECKOUT | 6. <input type="checkbox"/> RECOMMENDED CHANGES BELOW |

☐ FMEA CHANGE RECOMMENDED

EXPLANATION/COMMENTS:

1. Series redundant.
6. Series redundant.

SHUTTLE FAILURE MODE AND EFFECTS ANALYSIS - ORBITER 102

```

SUBSYSTEM : FWD - REACTION CONTROL          FMEA NO C3-2F -1C1095-1      REV:11/09/78
ASSEMBLY   : PRESSURIZATION                  ABORT:                      CRIT. FUNC:    3
P/N RI     : MC284-0481-CC01/-0002           CRIT. HWE:    3
P/N VENDOR : RSC105CO-001/-011              MISSIONS: HF VF X FF OF SM
QUANTITY   : 2                               PHASE(S): PL LD X DO X DO X LS
ONE PER HELIUM SUPPLY                         NUMBER OF SUCCESS PATHS REMAINING
                                              AFTER FIRST FAILURE:                1
REDUNDANCY SCREEN: A-N/A P-N/A C-N/A
FAILURE DETECTABLE IN FLIGHT?. NO             TIME TO EFFECT:
MINUTES
REFERENCE DOCUMENTS:
MJ070-0001-C1E
SD72-SH-0102-2
VS70-421001
GROUND TURNAROUND?.....YES
GROUND TEST PORTS
PREPARED BY:                                APPROVED BY:
DES                                           DES _____
REL                                           REL _____
ITEM: VALVE, QUAD, CHECK, HE
(CV 101/102)
FUNCTION:
TO PRECLUDE PROPELLANT VAPORS FROM MIGRATING TO REGULATORS (FROM THE
PROPELLANT TANK).
FAILURE MODE: FAILS OPEN (F)
OR FAILS TO REMAIN CLOSED (INTERNAL LEAKAGE).
CAUSE(S):
CONTAMINATION, VIBRATION, PIECE PART STRUCTURAL FAILURE, MECHANICAL
SHOCK, VIBRATION.
EFFECT(S): ON (A) SUBSYSTEM (B) INTERFACES (C) MISSION (D) CREW/VEHICLE:
(A) LOSS OF REDUNDANCY-SERIES VALVE WILL PROTECT REGULATORS FROM
VAPORS. (B,C,D) NO EFFECT UNLESS MULTIPLE FAILURES OCCUR. (E)
FUNCTIONAL CRITICALITY EFFECT - POSSIBLE CONTAMINATION OF REGULATORS
WITH PROPELLANT VAPORS IF BOTH CHECK VALVES ARE OPEN.
CORRECTING ACTION:
NONE AVAILABLE.
REMARKS/HAZARDS:
NO HAZARDS
ACTION OF PROPELLANT VAPORS AND CONTAMINATION.

```

ORIGINAL PAGE IS
OF POOR QUALITY

. **HARDWARE/SOFTWARE ANALYSIS CHECKLIST** 03-2F-101095-2

SUBSYSTEM Fwd Reaction Control FMEA NUMBER SD75-SH-0016A

ITEM Helium Quad Check Valve FAILURE MODE Fails Closed

1. DOES THE FLIGHT SOFTWARE DETECT THIS FAILURE MODE (i.e., AUTOMATICALLY ANNUNCIATE OR TAKE ACTION IN RESPONSE)? YES ☐ NO ☒
- 1a. IF NOT, DOES THE HARDWARE PROVIDE INFORMATION THAT THE FLIGHT SOFTWARE COULD USE TO DETECT THE FAILURE? *YES ☐ NO ☐
2. ARE THE ANSWERS TO QUESTIONS 1 AND 1a CONSISTENT WITH THE FMEA EVALUATION OF IN-FLIGHT DETECTABILITY? YES ☐ *NO ☒
3. DOES THE FLIGHT SOFTWARE TAKE ACTION TO NEGATE THE EFFECTS OF THE FAILURE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? YES ☐ NO ☒
- 3a. IF NOT, DOES THE CAPABILITY EXIST FOR THE SOFTWARE TO COMPENSATE FOR THIS FAILURE MODE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? *YES ☐ NO ☒
4. AS A RESULT OF THIS FAILURE MODE, CAN THE SOFTWARE OVERSTRESS THE HARDWARE OR INDUCE ANOTHER FAILURE? *YES ☐ NO ☒
5. CAN THIS FAILURE MODE, IN COMBINATION WITH SOFTWARE LOGIC, ADVERSELY AFFECT OTHER FUNCTIONS? *YES ☐ NO ☒
6. HOW MANY OF THESE HARDWARE FAILURES CAN THE SHUTTLE TOLERATE (CONSIDER CREW ACTION AND HARDWARE/SOFTWARE OPERATION)? NOTE CHANGE TO FMEA CRITICALITY. *0 ☐ *1 ☒ 2 ☐
7. IF CREW ACTION IS REQUIRED TO RESPOND TO THIS FAILURE MODE, ARE CUES PROVIDED TO SIGNAL THE NEED FOR INTERVENTION AND THE REQUIRED CORRECTIVE ACTION? N/A ☐ YES ☐ NO ☐
8. IF THE ANSWER TO EITHER 1 OR 3 IS YES:
 - A. CAN THE BFS BE ENGAGED AFTER OCCURRENCE? YES ☐ *NO ☐
 - B. WILL BFS TOLERATE FAILURE WITHOUT LOSS OF CREW/VEHICLE? YES ☐ *NO ☐

*EXPLANATION REQUIRED (SEE BELOW)

CHANGE/RETENTION RATIONALE SUMMARY

- | | | |
|--|---|--|
| 1. <input type="checkbox"/> NO H/S ISSUES | 3. <input type="checkbox"/> NO SOFTWARE DETECTION | 5. <input type="checkbox"/> ACCEPTANCE RATIONALE BELOW |
| 2. <input checked="" type="checkbox"/> HARDWARE ACCEPTS RISK | 4. <input type="checkbox"/> DETECTION DURING CHECKOUT | 6. <input type="checkbox"/> RECOMMENDED CHANGES BELOW |

☐ FMEA CHANGE RECOMMENDED

EXPLANATION/COMMENTS:

1 & 2. Upon using the thrusters, tank ullage pressure will decay until <200 psi which will give a class 2 caution and warning alarm.

SHUTTLE FAILURE MODE AND EFFECTS ANALYSIS - ORBITER 102

SUBSYSTEM : FWD - REACTION CONTROL FMEA NO 03-2F -101095-2 REV:11/10/7:
 .ASSEMBLY : PRESSURIZATION ABORT: CRIT. FUNC: 1K
 .P/N RI : MC284-0481-0001/-0002 CRIT. HWB: 3
 .P/N VENDOR: KSC10500-001/-011 MISSIONS: HF VF X HF OF SM
 .QUANTITY : 2 PHASE(S): PL LO X DO X DO X LS
 . : ONE PER HELIUM SUPPLY NUMBER OF SUCCESS PATHS REMAINING
 . : AFTER FIRST FAILURE: 1
 . REDUNDANCY SCREEN: A-PASS B-FAIL C-FAIL
 .FAILURE DETECTABLE IN FLIGHT? NO TIME TO EFFECT:
 .DUE TO SMALL P THE LEAKAGE IS NOT DETEC- MINUTES
 .TABLE REFERENCE DOCUMENTS:
 . MJC70-0001-01E
 .GROUND TURNAROUND?.....YES SD72-SH-1103-2
 .SAME AS FLIGHT INSTRUMENTATION VS70-421001
 .
 .
 .
 . PREPARED BY: APPROVED BY:
 . DES R BURKHART DES _____
 . REL R DIEHL REL _____
 .
 .
 .ITEM: VALVE, QUAD, CHECK, HE
 . (CV 101/102)
 .FUNCTION:
 . TO PRECLUDE PROPELLANT VAPORS FROM MIGRATING TO REGULATORS (FROM THE
 PROPELLANT TANK).
 .FAILURE MODE: FAILS CLOSED (F)
 . RESTRICTED FLOW.
 .CAUSE(S):
 . PIECE PART STRUCTURAL FAILURE, MECHANICAL SHOCK, ACCELERATION.
 .EFFECT(S): ON (A)SUBSYSTEM (B)INTERFACES (C)MISSION (D)CREW/VEHICLE:
 . (A) LOSS OF REDUNDANCY - PARALLEL PATH PROVIDES PRESSURANT FEED.
 . (B,C,) NO EFFECT UNLESS MULTIPLE FAILURES OCCUR. (D) NO EFFECT.
 . (E) FUNCTIONAL CRITICAL EFFECTS - IF FAILURE OCCURS BEFORE ET SEPARATION
 ,LOSS OF DOWN FIRING THRUSTERS WILL PREVENT ET SEPARATION AND RESULT IN
 LOSS OF CREW/VEHICLE.
 .CORRECTING ACTION:
 . NONE (BLOWDOWN MAY BE USED AFTER SECOND FAILURE).
 .REMARKS/HAZARDS:
 . MINIMUM DELTA CRACKING PRESSURE FOR CRACKING IS NECESSARY REQUIREMENT
 TO MINIMIZE SYSTEM PRESSURE DROP TO TANKS.

ORIGINAL PAGE IS
OF POOR QUALITY

SHUTTLE CRITICAL ITEMS LIST - ORBITER 102

SUBSYSTEM : FWD - REACTION CONTROL FMEA NO 03-2F -101095-2 REV: 11/10/78
 .ASSEMBLY : PRESSURIZATION ABORT: CRIT. FUNC: 1R
 .P/N RI : HC284-0481-0001/-0002 CRIT. HDW: 3
 .P/N VENDOR: RS010500-001/-011 MISSIONS: HF VF X FF OF SM
 .QUANTITY : 2 PHASE(S): PL LC X OO X DO X LS
 . : ONE PER HELIUM SUPPLY

REDUNDANCY SCREEN: A-PASS B-FAIL C-FAIL

PREPARED BY: DES R BURKHART APPROVED BY: *[Signature]* APPROVED BY: (NASA) *[Signature]*
 REL R DIEHL DES *[Signature]* SS: *[Signature]*
 REL *[Signature]* 12/5/78 REV: *[Signature]*
 APPROVED WITH CHANGES
 See Section 13.0

- . ITEM: VALVE, QUAD, CHECK, HE
- . (CV 101/102)
- . FUNCTION:
- . TO PRECLUDE PROPELLANT VAPORS FROM MIGRATING TO REGULATORS (FROM THE PROPELLANT TANK).
- . FAILURE MODE: FAILS CLOSED (F)
- . RESTRICTED FLOW.
- . CAUSE(S):
- . PIECE PART STRUCTURAL FAILURE, MECHANICAL SHOCK, ACCELERATION.
- . EFFECT(S): ON (A) SUBSYSTEM (B) INTERFACES (C) MISSION (D) CREW/VEHICLE:
- . (A) LOSS OF REDUNDANCY - PARALLEL PATH PROVIDES PRESSURANT FEED.
- . (B,C,) NO EFFECT UNLESS MULTIPLE FAILURES OCCUR. (D) NO EFFECT.
- . (E) FUNCTIONAL CRITICAL EFFECTS - IF FAILURE OCCURS BEFORE ET SEPARATION
- . LOSS OF DOWN FIRING THRUSTERS WILL PREVENT ET SEPARATION AND RESULT IN LOSS OF CREW/VEHICLE.
- . DISPOSITION & RATIONALE (A) DESIGN (B) TEST (C) INSPECTION (D) FAILURE HISTORY:
- . (A) VALVE SEAT MATERIAL WILL NOT STICK CAUSING A FAILURE TO OPEN AND SPECIFIED MAXIMUM CRACKING PRESSURE IS ONLY 5 PSI. (B) CHECK VALVE TO BE CERTIFIED FOR 100,000 CYCLES WITHOUT CHANGE IN PERFORMANCE.
- . CHARACTERISTICS/ALSO, WILL CHECK OUT EACH VALVE ELEMENT (PARALLEL - SERIES) AFTER EACH FLIGHT. VALVE SUBJECTED TO 48 MIN OF 10.6 GRMS RANDOM VIBRATION PER AXIS DURING QUAL PROGRAM. (C) AN AUDIT CONDUCTED ON 1-16-78 INDICATED THAT SUPPLIER QC VERIFIED RAW MAT'L. CERTIFICATION TO SATISFY SHUTTLE DESIGN REQUIREMENTS, VERIFIED PROTECTION OF DETAIL PARTS FROM DAMAGE DURING MFG AND TEST, IN-PROCESS INSPECTION VERIFIED MFG TRAVELER SEQUENCES. TURNAROUND INSPECTION TO INCLUDE MONITORING FUNCTIONAL TESTS TO VERIFY FLOW AND CHECK FOR LEAKAGE. (D) NO FAILURE HISTORY. THIS IS A NEW DESIGN FOR SHUTTLE USE.

. HARDWARE/SOFTWARE ANALYSIS CHECKLIST 03-2F-102106-1

SUBSYSTEM Fwd Reaction Control

FMEA NUMBER SD75-SH-0016A

ITEM Propellant Line Flex Assy.

FAILURE MODE External Leakage

1. DOES THE FLIGHT SOFTWARE DETECT THIS FAILURE MODE (i.e., AUTOMATICALLY ANNUNCIATE OR TAKE ACTION IN RESPONSE)? YES ☒ NO ☐
- 1a. IF NOT, DOES THE HARDWARE PROVIDE INFORMATION THAT THE FLIGHT SOFTWARE COULD USE TO DETECT THE FAILURE? *YES ☐ NO ☐
2. ARE THE ANSWERS TO QUESTIONS 1 AND 1a CONSISTENT WITH THE FMEA EVALUATION OF IN-FLIGHT DETECTABILITY? YES ☒ *NO ☐
3. DOES THE FLIGHT SOFTWARE TAKE ACTION TO NEGATE THE EFFECTS OF THE FAILURE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? YES ☐ NO ☒
- 3a. IF NOT, DOES THE CAPABILITY EXIST FOR THE SOFTWARE TO COMPENSATE FOR THIS FAILURE MODE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? *YES ☐ NO ☒
4. AS A RESULT OF THIS FAILURE MODE, CAN THE SOFTWARE OVERSTRESS THE HARDWARE OR INDUCE ANOTHER FAILURE? *YES ☐ NO ☒
5. CAN THIS FAILURE MODE, IN COMBINATION WITH SOFTWARE LOGIC, ADVERSELY AFFECT OTHER FUNCTIONS? *YES ☐ NO ☒
6. HOW MANY OF THESE HARDWARE FAILURES CAN THE SHUTTLE TOLERATE (CONSIDER CREW ACTION AND HARDWARE/SOFTWARE OPERATION)? NOTE CHANGE TO FMEA CRITICALITY. *0 ☒ *1 ☐ 2 ☐
7. IF CREW ACTION IS REQUIRED TO RESPOND TO THIS FAILURE MODE, ARE CUES PROVIDED TO SIGNAL THE NEED FOR INTERVENTION AND THE REQUIRED CORRECTIVE ACTION? N/A ☐ YES ☒ NO ☐
8. IF THE ANSWER TO EITHER 1 OR 3 IS YES:
 - A. CAN THE BFS BE ENGAGED AFTER OCCURRENCE? YES ☒ *NO ☐
 - B. WILL BFS TOLERATE FAILURE WITHOUT LOSS OF CREW/VEHICLE? YES ☒ *NO ☐

*EXPLANATION REQUIRED (SEE BELOW)

CHANGE/RETENTION RATIONALE SUMMARY

- | | | |
|--|---|--|
| 1. <input type="checkbox"/> NO H/S ISSUES | 3. <input type="checkbox"/> NO SOFTWARE DETECTION | 5. <input type="checkbox"/> ACCEPTANCE RATIONALE BELOW |
| 2. <input checked="" type="checkbox"/> HARDWARE ACCEPTS RISK | 4. <input type="checkbox"/> DETECTION DURING CHECKOUT | 6. <input type="checkbox"/> RECOMMENDED CHANGES BELOW |

☒ FMEA CHANGE RECOMMENDED

EXPLANATION/COMMENTS:

1. V42P1115C, 1116C will give a class 2 alert once pressure drops to a pre-determined low. Gross leak indication occurs first.

6. No redundancy available.

7. V42P1116C and V42P1115C goes to shared meter M2 and will show a large pressure drop for worst case (large leak).

FMEA Change - add V42P1116C to "failure detectable in flight".

SHUTTLE FAILURE MODE AND EFFECTS ANALYSIS - ORBITER 102

SUBSYSTEM : FWD - REACTION CONTROL FMEA NO 03-2F -102106-1 REV:11/09/7.

ASSEMBLY : PROPELLANT FEED ABORT: CRIT. FUNC: 1

P/N RI : CRIT. HWD: 1

P/N VENDOR: MC271-0095 MISSIONS: HF VF X FF CF SM

QUANTITY : 2 PHASE(S): FL LO X OO X DO X LS

: ONE PER PROPELLANT NUMBER OF SUCCESS PATHS REMAINING

: AFTER FIRST FAILURE: C

: REDUNDANCY SCREEN: A-N/A B-N/A C-N/A

FAILURE DETECTABLE IN FLIGHT? YES TIME TO EFFECT:

PROPELLANT TANK PRESSURE V42P-1310C AND MANIFOLD SECONDS TO DAYS

PRESSURE 1312C&1316C REFERENCE DOCUMENTS:

: V070-421001

GROUND TURNAROUND?.....YES XJ070-0001-C15

SAME AS FLIGHT INSTRUMENTATION SD72-SH-0103-2

: VS70-421001

:

:

:

:

PREPARED BY: APPROVED BY:

DES J. TAGGART DES _____

REL R DIEHL REL _____

:

:

ITEM: PROP LINE FLEX ASSY

:

FUNCTION:

: TO PROVIDE PROPELLANT FEED TO APPROPRIATE PROPELLANT FEEDLINES.

FAILURE MODE: EXTERNAL LEAKAGE (S)

:

CAUSE(S):

: MECHANICAL SHOCK, VIBRATION, FLOW, FATIGUE, IMPROPER INSTALLATION (WELD)

EFFECT(S): ON (A) SUBSYSTEM (E) INTERFACES (C) MISSION (D) CREW/VEHICLE:

: (A) LOSS OF PROPELLANTS. (B) POTENTIAL CORROSION FROM FREE

: PROPELLANTS IN MODULE. (C) POTENTIAL MISSION LOSS OR ABORT DECISION.

: (D) POTENTIAL LOSS OF CREW/VEHICLE IF FAILURE RESULTS IN LOSS OF RCS

: FUNCTION BEFORE ET SEPARATION.

CORRECTING ACTION:

: ATTEMPT TO ISOLATE AND INITIATE ABORT IF REQ'D.

REMARKS/HAZARDS:

: POTENTIAL HAZARD OF FIRE/EXPLOSION FROM FREE PROPELLANTS. SOME LEAK

: POINTS MAY NOT BE ISOLATABLE (I.E. BEFORE/UPSTREAM OF TANK ISOLATION

: VALVES) NO REDUNDANCY PROVIDED FOR LINES. SEE HAZARD NO. 1YXX-0302-04.

SHUTTLE CRITICAL ITEMS LIST - ORBITER 102

```

SUBSYSTEM : FWD - REACTION CONTROL      FMEA NO 03-2F -102106-1      REV:11/09/78
ASSEMBLY  : PROPELLANT FEED             ABORT:                CRIT. FUNC:    1
P/N RI    :                             CRIT. HD# :    1
P/N VENDOR: HC271-0095                  MISSIONS:  HF      VF X  FF      OF      SM
QUANTITY  : 2                           PHASE(S):  PL      LO X  OO X  DO X  LS
: ONE PER PROPELLANT

```

REDUNDANCY SCREEN: A-N/A B-N/A C-N/A

.PREPARED BY:
 .DES J. TAGGART
 .REL R DIEHL

APPROVED BY: *[Signature]*
DES *[Signature]*
REL *[Signature]* 2/15/78

APPROVED BY (NASA):
SSM
RED

APPROVED WITH CHANGES
See Section 13.0

ITEM: PROP LINE FLEX ASSY

FUNCTION:

• TO PROVIDE PROPELLANT FEED TO APPROPRIATE PROPELLANT FEEDLINES.

• FAILURE MODE: EXTERNAL LEAKAGE (S)

• CAUSE(S):

- MECHANICAL SHOCK, VIBRATION, FLOW, FATIGUE, IMPROPER INSTALLATION (WELD)
- EFFECT(S): ON (A) SUBSYSTEM (B) INTERFACES (C) MISSION (D) CREW/VEHICLE:
- (A) LOSS OF PROPELLANTS. (B) POTENTIAL CORROSION FROM FREE PROPELLANTS IN MODULE. (C) POTENTIAL MISSION LOSS OR ABORT DECISION. (D) POTENTIAL LOSS OF CREW/VEHICLE IF FAILURE RESULTS IN LOSS OF RCS FUNCTION BEFORE ET SEPARATION.

•DISPOSITION & RATIONALE (A)DESIGN (B)TEST (C)INSPECTION (D)FAILURE HISTORY:

• (A) STRUCTURAL MARGIN OF 2.0 WILL MINIMIZE FAILURE MODE POTENTIAL. (B) PROOF TESTED TO 1.5 TIMES WORKING PRESSURE AND 65 MINUTES OF RANDOM VIBRATION AT ANTICIPATED MISSION LEVELS. (C) IN PROCESS INSPECTIONS X-RAY OF WELDS & PENETRANT INSPECT. TURN AROUND INSPECTION INCLUDES MONITORING FUNCTIONAL TESTS DURING PRESSURIZATION CYCLE FOR EVIDENCE OF LEAKS AND DAMAGE. SUPPLIER INSPECTION DEEMED TO BE SATISFACTORY BASED ON SURVEY CONDUCTED ON 4-20-77. (D) NO FAILURE HISTORY FOR THIS SPECIFIC DESIGN.

. HARDWARE/SOFTWARE ANALYSIS CHECKLIST 03-2F-102108-1

SUBSYSTEM Fwd Reaction Control

FMEA NUMBER

SD75-SH-0016A

ITEM Feedline and Fittings

FAILURE MODE

External Leakage

1. DOES THE FLIGHT SOFTWARE DETECT THIS FAILURE MODE (i.e., AUTOMATICALLY ANNUNCIATE OR TAKE ACTION IN RESPONSE)? YES ☒ NO ☐
- 1a. IF NOT, DOES THE HARDWARE PROVIDE INFORMATION THAT THE FLIGHT SOFTWARE COULD USE TO DETECT THE FAILURE? *YES ☐ NO ☐
2. ARE THE ANSWERS TO QUESTIONS 1 AND 1a CONSISTENT WITH THE FMEA EVALUATION OF IN-FLIGHT DETECTABILITY? YES ☒ *NO ☐
3. DOES THE FLIGHT SOFTWARE TAKE ACTION TO NEGATE THE EFFECTS OF THE FAILURE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? YES ☐ NO ☒
- 3a. IF NOT, DOES THE CAPABILITY EXIST FOR THE SOFTWARE TO COMPENSATE FOR THIS FAILURE MODE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? *YES ☐ NO ☒
4. AS A RESULT OF THIS FAILURE MODE, CAN THE SOFTWARE OVERSTRESS THE HARDWARE OR INDUCE ANOTHER FAILURE? *YES ☐ NO ☒
5. CAN THIS FAILURE MODE, IN COMBINATION WITH SOFTWARE LOGIC, ADVERSELY AFFECT OTHER FUNCTIONS? *YES ☐ NO ☒
6. HOW MANY OF THESE HARDWARE FAILURES CAN THE SHUTTLE TOLERATE (CONSIDER CREW ACTION AND HARDWARE/SOFTWARE OPERATION)? NOTE CHANGE TO FMEA CRITICALITY. *0 ☒ *1 ☐ 2 ☐
7. IF CREW ACTION IS REQUIRED TO RESPOND TO THIS FAILURE MODE, ARE CUES PROVIDED TO SIGNAL THE NEED FOR INTERVENTION AND THE REQUIRED CORRECTIVE ACTION? N/A ☐ YES ☒ NO ☐
8. IF THE ANSWER TO EITHER 1 OR 3 IS YES:
 - A. CAN THE BFS BE ENGAGED AFTER OCCURRENCE? YES ☒ *NO ☐
 - B. WILL BFS TOLERATE FAILURE WITHOUT LOSS OF CREW/VEHICLE? YES ☒ *NO ☐

*EXPLANATION REQUIRED (SEE BELOW)

CHANGE/RETENTION RATIONALE SUMMARY

- | | | |
|--|---|--|
| 1. <input type="checkbox"/> NO H/S ISSUES | 3. <input type="checkbox"/> NO SOFTWARE DETECTION | 5. <input type="checkbox"/> ACCEPTANCE RATIONALE BELOW |
| 2. <input checked="" type="checkbox"/> HARDWARE ACCEPTS RISK | 4. <input type="checkbox"/> DETECTION DURING CHECKOUT | 6. <input type="checkbox"/> RECOMMENDED CHANGES BELOW |

☐ FMEA CHANGE RECOMMENDED

EXPLANATION/COMMENTS:

1. V42P1115C, 1116C will give a class 2 alert once pressure drops to a pre-determined low. Gross leak indication occurs first.

6. No redundancy available.

7. V42P1115C and V42P1116C goes to shared meter M2 and will show a large pressure drop for worst case (large leak).

SHUTTLE FAILURE MODE AND EFFECTS ANALYSIS - ORBITER 102

SUBSYSTEM : FWD - REACTION CONTROL FMEA NO 03-2F -102108-1 REV: 12/08/71
 .ASSEMBLY : PROPELLANT FEED. ABORT: CRIT. FUNC: 1
 .P/N RI : V070-421001 CRIT. HWL: 1
 .P/N VENDOR: MISSIONS: HF VF X FF OF SM
 .QUANTITY : 1 PHASE(S): PL LO X OG X DU X LS
 . : ONE SET PER PROPELLANT NUMBER OF SUCCESS PATHS REMAINING
 . : AFTER FIRST FAILURE: 0
 . REDUNDANCY SCREEN: A-N/A B-N/A C-N/A
 .FAILURE DETECTABLE IN FLIGHT?. YES TIME TO EFFECT:
 .PROPELLANT TANK PRESSURE V42P-1310C AND MANIFOLD SECONDS TO DAYS
 .PRESSURE 1312C & 1316C REFERENCE DOCUMENTS:
 . V070-421001
 .GROUND TURNAROUND?.....YES MJO70-0001-01B
 .SAME AS FLIGHT INSTRUMENTATION SC72-SH-0103-2
 . VS70-421001
 .
 .
 .
 . PREPARED BY: APPROVED BY:
 . DES A SIEGELIN DES _____
 . REL R DIEHL REL _____
 .
 .
 .
 .ITEM: FEEDLINE AND FITTINGS
 . FROM TANK TO 1) TANK VALVES TO 2) MANIFOLD VALVES, TO 3) THRUSTERS.
 .FUNCTION:
 . TO PROVIDE FEED TO APPROPRIATE PROPELLANT COMPONENTS FOR THRUSTER
 OPERATION - 3 AXIS ACCELERATION CONTROL AND ROTATIONAL CONTROL.
 .FAILURE MODE: EXTERNAL LEAKAGE (S)
 .
 .CAUSE(S):
 . MECHANICAL SHOCK, VIBRATION/FATIGUE, STRUCTURAL FAILURE, IMPROPER
 INSTALLATION (WELD). FLUID FITTING SEAL FAILURE.
 .EFFECT(S): ON (A)SUBSYSTEM (B)INTERFACES (C)MISSION (D)CREW/VEHICLE:
 . (A) POTENTIAL LOSS OF PROPELLANTS. (B) POTENTIAL CORROSION FROM FREE
 PROPELLANTS IN MODULE. (C) POTENTIAL MISSION LOSS OR ABORT DECISION.
 (D) POTENTIAL LOSS OF CREW/VEHICLE IF LEAKING PROPELLANT EXPLODES DUE
 TO CONTACT WITH CATALYTIC AGENT OR HEAT SOURCE WITH SUBSEQUENT LOSS OF
 FORWARD MODULE OR IF LOSS OF PROPELLANT PROHIBITS ET SEPARATION.
 .CORRECTING ACTION:
 . ATTEMPT TO ISOLATE AND INITIATE ABORT IF REQ'D.
 .REMARKS/HAZARDS:
 . POTENTIAL HAZARD OF FIRE/EXPLOSION FROM FREE PROPELLANTS. SOME LEAK
 POINTS MAY NOT BE ISOLATABLE (I.E. BEFORE/UPSTREAM OF TANK ISOLATION
 VALVES) NO REDUNDANCY PROVIDED FOR LINES. SEE HAZARD NO. 1YXX-0302-04.

SHUTTLE CRITICAL ITEMS LIST - ORBITER 102

SUBSYSTEM : FWD - REACTION CONTROL FMEA NO 03-2F -102108-1 REV: 12/08/
 .ASSEMBLY : PROPELLANT FEED. ABORT: CRIT. FUNC: 1
 .P/N RI : V070-421001 CRIT. HDW: 1
 .P/N VENDOR: MISSIONS: HF VF X FF OF SM
 .QUANTITY : 1 PHASE(S): PL LO X CO X DO X LS
 . : ONE SET PER PROPELLANT
 . :
 . : REDUNDANCY SCREEN: A-N/A B-N/A C-N/
 . :
 .PREPARED BY: APPROVED BY: *[Signature]* 12/15/78 APPROVED BY (NASA): *[Signature]*
 .DES A SIEGELIN DES *[Signature]* SSM *[Signature]*
 .REL R DIEHL REL *[Signature]* 12/15/78 REL *[Signature]*

APPROVED WITH CHANGES

See Section 13.0

- .ITEM: FEEDLINE AND FITTINGS
- . FROM TANK TO 1) TANK VALVES TO 2) MANIFOLD VALVES, TO 3) THRUSTERS.
- .FUNCTION:
- . TO PROVIDE FEED TO APPROPRIATE PROPELLANT COMPONENTS FOR THRUSTER OPERATION - 3 AXIS ACCELERATION CONTROL AND ROTATIONAL CONTROL.
- .FAILURE MODE: EXTERNAL LEAKAGE (S)
- .CAUSE(S):
- . MECHANICAL SHOCK, VIBRATION/FATIGUE, STRUCTURAL FAILURE, IMPROPER INSTALLATION (WELD). FLUID FITTING SEAL FAILURE.
- .EFFECT(S): ON (A)SUBSYSTEM (B)INTERFACES (C)MISSION (D)CREW/VEHICLE:
- . (A) POTENTIAL LOSS OF PROPELLANTS. (B) POTENTIAL CORROSION FROM FREE PROPELLANTS IN MODULE. (C) POTENTIAL MISSION LOSS OR ABORT DECISION. (D) POTENTIAL LOSS OF CREW/VEHICLE IF LEAKING PROPELLANT EXPLODES DUE TO CONTACT WITH CATALYTIC AGENT OR HEAT SOURCE WITH SUBSEQUENT LOSS OF FORWARD MODULE OR IF LOSS OF PROPELLANT PROHIBITS ET SEPARATION.
- .DISPOSITION & RATIONALE (A)DESIGN (B)TEST (C)INSPECTION (D)FAILURE HISTORY
- . (A) FACTOR OF SAFETY OF 4.0 WILL MINIMIZE FAILURE POTENTIAL. DYNATUBE FITTINGS HAVE DUAL SEALS. WELD CONSTRUCTION REDUCES JOINTS & POSSIBLE LEAK PATHS. FASTENING CLAMPS AND TUBE BEND DESIGN ALLOWS DEGREE OF MOVEMENT WHICH HELPS PREVENTING LEAKS. (B) POST INSTALLATION TEST AND OPERATIONAL CHECKOUTS WILL VERIFY SYSTEM INTEGRITY. ALL LINES SUBJECTED TO PROOF TEST OF 1.25 X MAX OPERATING PRESSURE OR 1.1 X SURGE (TRANSIT) PRESSURE WHICHEVER IS GREATER. PERFORMED TUBING CERTIFICATION PER "ORBITER TUBING VERIFICATION PLAN SD75-SH-0205". (C) IN-PROCESS INSPECT INCLUDES NDT & CHECKS DURING INSTALLATION. TURNAROUND INSPECTION INCLUDES MONITORING FUNCTIONAL TESTS DURING PRESSURIZATION CYCLE FOR EVIDENCE OF LEAKS. VISUALLY INSPECT FOR DAMAGE WHERE ACCESSIBLE. HARDWARE INSPECTION IN ACCORDANCE WITH PLANNING RQMTS APPROVED BY NASA (D) MINOR FAILURE HISTORY-CORROSION AND FAB PROBLEMS REPORTED DURING APOLLO PROGRAM AND CORRECTED WITH APPLICABLE TMO/TPC REQUIREMENT.

1020

SUBSYSTEM Fwd Reaction Control

FMEA NUMBER SD75-SH-00016A

ITEM AC Motor Operated Valve (Tank)

FAILURE MODE Fails Closed

- | | |
|--|--|
| 1. DOES THE FLIGHT SOFTWARE DETECT THIS FAILURE MODE (i.e., AUTOMATICALLY ANNUNCIATE OR TAKE ACTION IN RESPONSE)? | YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> |
| 1a. IF NOT, DOES THE HARDWARE PROVIDE INFORMATION THAT THE FLIGHT SOFTWARE COULD USE TO DETECT THE FAILURE? | *YES <input type="checkbox"/> NO <input type="checkbox"/> |
| 2. ARE THE ANSWERS TO QUESTIONS 1 AND 1a CONSISTENT WITH THE FMEA EVALUATION OF IN-FLIGHT DETECTABILITY? | YES <input checked="" type="checkbox"/> *NO <input type="checkbox"/> |
| 3. DOES THE FLIGHT SOFTWARE TAKE ACTION TO NEGATE THE EFFECTS OF THE FAILURE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? | YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> |
| 3a. IF NOT, DOES THE CAPABILITY EXIST FOR THE SOFTWARE TO COMPENSATE FOR THIS FAILURE MODE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? | *YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> |
| 4. AS A RESULT OF THIS FAILURE MODE, CAN THE SOFTWARE OVERSTRESS THE HARDWARE OR INDUCE ANOTHER FAILURE? | *YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> |
| 5. CAN THIS FAILURE MODE, IN COMBINATION WITH SOFTWARE LOGIC, ADVERSELY AFFECT OTHER FUNCTIONS? | *YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> |
| 6. HOW MANY OF THESE HARDWARE FAILURES CAN THE SHUTTLE TOLERATE (CONSIDER CREW ACTION AND HARDWARE/SOFTWARE OPERATION)? NOTE CHANGE TO FMEA CRITICALITY. | *0 <input type="checkbox"/> *1 <input checked="" type="checkbox"/> 2 <input type="checkbox"/> |
| 7. IF CREW ACTION IS REQUIRED TO RESPOND TO THIS FAILURE MODE, ARE CUES PROVIDED TO SIGNAL THE NEED FOR INTERVENTION AND THE REQUIRED CORRECTIVE ACTION? | N/A <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> |
| 8. IF THE ANSWER TO EITHER 1 OR 3 IS YES: | |
| A. CAN THE BFS BE ENGAGED AFTER OCCURRENCE? | YES <input checked="" type="checkbox"/> *NO <input type="checkbox"/> |
| B. WILL BFS TOLERATE FAILURE WITHOUT LOSS OF CREW/VEHICLE? | YES <input checked="" type="checkbox"/> *NO <input type="checkbox"/> |

*EXPLANATION REQUIRED (SEE BELOW)

CHANGE/RETENTION RATIONALE SUMMARY

- | | | |
|--|---|--|
| 1. <input type="checkbox"/> NO H/S ISSUES | 3. <input type="checkbox"/> NO SOFTWARE DETECTION | 5. <input type="checkbox"/> ACCEPTANCE RATIONALE BELOW |
| 2. <input checked="" type="checkbox"/> HARDWARE ACCEPTS RISK | 4. <input type="checkbox"/> DETECTION DURING CHECKOUT | 6. <input type="checkbox"/> RECOMMENDED CHANGES BELOW |

☐ FMEA CHANGE RECOMMENDED

EXPLANATION/COMMENTS:

- "RCS JETS" light on caution and warning panel.
- The manifolds are in parallel (2 legs) giving one redundant path.

SHUTTLE FAILURE MODE AND EFFECTS ANALYSIS - ORBITER 102

SUBSYSTEM : FWD - REACTION CONTROL FMEA NO 03-2F -102120-1 REV:11/10/77
 .ASSEMBLY : PROPELLANT FEED ABORT: ABORT, CRIT. FUNC: 1R
 .P/N RI : MC284-C430-0007/-0008 RTLS CRIT. FWD: 2
 .P/N VENDOR: 5750025/5750026 MISSIONS: HF VF X FF CF SM
 .QUANTITY : 4 PPASE(S): PL LO X OG X DU LS
 . : TWO REQ'D PER PROP TANK NUMBER OF SUCCESS PATHS REMAINING
 . : AFTER FIRST FAILURE: 1
 . REDUNDANCY SCREEN: A-PASS F-PASS C-PAS:
 .FAILURE DETECTABLE IN FLIGHT? YES TIME TO EFFECT:
 .THRUSTER CHAMBER PRESS., MANIFOLD PRESSURE MONITOR SECONDS
 .N V42P-1212-1216,1312- 1316,1521-1522 REFERENCE DOCUMENTS:
 . MJ070-0001-016
 .GROUND TURNAROUND?.....YES S072-SM-0103-2
 .SAME AS FLIGHT VS70-421001
 .
 .
 .
 . PREPARED BY: APPROVED BY:
 . DES R GONZALEZ DES _____
 . REL R DIEHL REL _____
 .
 .
 .ITEM: VLV, AC MOTOR OPERATED -
 . TANK (1 1/2"). (LV 161-164).
 .FUNCTION:
 . 1) PROVIDES ISOLATION OF TANKS FROM MANIFOLDS. 2) PROVIDES BACK-UP
 SHUT-OFF/ISOLATION OF PROP MANIFOLDS AND ASSOCIATED THRUSTERS'
 COMPONENTS. EI-STABLE, (TANK PRESSURE-245 PSI). AC MOTOR DRIVEN 3
 PHASE (2 OF 3 WILL ACTUATE VALVE) 115 TO 200 VOLTS 400 HZ.
 .FAILURE MODE: FAILS CLOSED (F)
 . POSITION - INCLUDES RESTRICTED FLOW TO LEVEL THAT DOES NOT ALLOW PROPER
 MIXTURE RATIO.
 .CAUSE(S):
 . VIBRATION, STRUCTURAL FAILURE. PREMATURE POWER TO MOTOR, ELECTRICAL
 SHORT.
 .EFFECT(S): ON (A)SUBSYSTEM (B)INTERFACES (C)MISSION (D)CREW/VEHICLE:
 . (A) LOSS OF PROPELLANT FLOW IN TWO MANIFOLDS AND SUBSEQUENT LOSS OF
 THRUSTER FUNCTION (THRUSTER BURN-THRU DUE TO OXID RICH MIXTURE). (B)
 POSSIBLE BURN-THRU PROPAGATION. (C) LOSS OF MISSION. ABORT DECISION.
 (D) POTENTIAL VEHICLE DAMAGE FROM COLLISION WITH RENDEZVOUS TARGET,
 AFTER SECOND FAILURE. CRIT 1 FOR RTLS ABORT.
 .CORRECTING ACTION:
 . UTILIZE REMAINING FORWARD THRUSTERS IN COUPLE WITH APPROPRIATE AFT
 THRUSTERS FOR BRAKING. DE-ORBIT WITH AFT MODULES
 .REMARKS/HAZARDS:
 . POTENTIAL HAZARD OF EXPLOSION IF OX VALVE FAILS. SEE PARKER FMEA & RMR
 5750023.

SHUTTLE CRITICAL ITEMS LIST - ORBITER 102

```

SUBSYSTEM : FWD - REACTION CONTROL      FMEA NO 03-2F -102120-1 . REV: 11/10/7
ASSEMBLY  : PROPELLANT FEED             ABORT: ABCRT,          CRIT. FUNC: 1R
P/N RI    : MC284-0430-0007/-0008      RTLS                 CRIT. HDW: 2
P/N VENDOR: 5750025/5750026            MISSIONS: HF VF X FF OF SM
QUANTITY  : 4                          PHASE(S): PL LO X CG X DO LS
: TWO REQ'D PER PROP TANK

```

REDUNDANCY SCREEN: A-PASS B-PASS C-PASS

SD75-SH-0003

1. DOES THE FLIGHT SOFTWARE DETECT THIS FAILURE MODE (i.e., AUTOMATICALLY ANNUNCIATE OR TAKE ACTION IN RESPONSE)? YES ☒ NO ☐
- 1a. IF NOT, DOES THE HARDWARE PROVIDE INFORMATION THAT THE FLIGHT SOFTWARE COULD USE TO DETECT THE FAILURE? *YES ☐ NO ☐
2. ARE THE ANSWERS TO QUESTIONS 1 AND 1a CONSISTENT WITH THE FMEA EVALUATION OF IN-FLIGHT DETECTABILITY? YES ☒ *NO ☐
3. DOES THE FLIGHT SOFTWARE TAKE ACTION TO NEGATE THE EFFECTS OF THE FAILURE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? YES ☐ NO ☒
- 3a. IF NOT, DOES THE CAPABILITY EXIST FOR THE SOFTWARE TO COMPENSATE FOR THIS FAILURE MODE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? *YES ☐ NO ☒
4. AS A RESULT OF THIS FAILURE MODE, CAN THE SOFTWARE OVERSTRESS THE HARDWARE OR INDUCE ANOTHER FAILURE? *YES ☐ NO ☒
5. CAN THIS FAILURE MODE, IN COMBINATION WITH SOFTWARE LOGIC, ADVERSELY AFFECT OTHER FUNCTIONS? *YES ☐ NO ☒
6. HOW MANY OF THESE HARDWARE FAILURES CAN THE SHUTTLE TOLERATE (CONSIDER CREW ACTION AND HARDWARE/SOFTWARE OPERATION)? NOTE CHANGE TO FMEA CRITICALITY. *0 ☐ *1 ☒ 2 ☐
7. IF CREW ACTION IS REQUIRED TO RESPOND TO THIS FAILURE MODE, ARE CUES PROVIDED TO SIGNAL THE NEED FOR INTERVENTION AND THE REQUIRED CORRECTIVE ACTION? N/A ☐ YES ☒ NO ☐
8. IF THE ANSWER TO EITHER 1 OR 3 IS YES:
 - A. CAN THE BFS BE ENGAGED AFTER OCCURRENCE? YES ☒ *NO ☐
 - B. WILL BFS TOLERATE FAILURE WITHOUT LOSS OF CREW/VEHICLE? YES ☒ *NO ☐

*EXPLANATION REQUIRED (SEE BELOW)

CHANGE/RETENTION RATIONALE SUMMARY

- | | | |
|--|---|--|
| 1. <input type="checkbox"/> NO H/S ISSUES | 3. <input type="checkbox"/> NO SOFTWARE DETECTION | 5. <input type="checkbox"/> ACCEPTANCE RATIONALE BELOW |
| 2. <input checked="" type="checkbox"/> HARDWARE ACCEPTS RISK | 4. <input type="checkbox"/> DETECTION DURING CHECKOUT | 6. <input type="checkbox"/> RECOMMENDED CHANGES BELOW |

☒ FMEA CHANGE RECOMMENDED

EXPLANATION/COMMENTS:

1. The tank pressure drop (worst case/full open) will be detected by V42P1115C, 1116C; unless regulated the gross leak indication will detect it. Also measurements 1313C, and 1314C appear obsolete and should be removed from the FMEA.

SHUTTLE FAILURE MODE AND EFFECTS ANALYSIS - ORBITER 102

SUBSYSTEM : FWD - REACTION CONTROL FMEA NO 03-2F -102150-1 REV:12/08/71
 .ASSEMBLY : PROPELLANT ABORT: CRIT. FUNC: 1
 .P/N RI : MC276-0018 CRIT. HWD: 1
 .P/N VENDOR: 763010LC MISSIONS: HF VF X FF OF SM
 .QUANTITY : 6 PHASE(S): PL LG X GO X JO X LS
 . : NUMBER OF SUCCESS PATHS REMAINING
 . : THREE REQ PER PROPELLANT AFTER FIRST FAILURE: 1
 . REDUNDANCY SCREEN: A-N/A B-N/A C-N/A
 . FAILURE DETECTABLE IN FLIGHT? . YES TIME TO EFFECT:
 . LOSS OF TANK PRESSURE V42P-1310C, SECONDS TO DAYS
 . 1312C, 1313C, 1314C, 1315C TANK TEMP REFERENCE DOCUMENTS:
 . 1300 AND 1400 MJC70-0001-01b
 . GROUND TURNAROUND? N/A SD72-SH-0103-2
 . VS70-421001
 .
 .
 .
 .

PREPARED BY:	APPROVED BY:
DES C SCARLETT	DES _____
REL R DIEHL	REL _____

. ITEM: DISCONNECT, QUICK, FILL
 . PROPELLANT, SPRING LOADED POPPET & STRUCTURAL CAP (MD119-126).
 . FUNCTION:
 . TO PROVIDE FOR DRAINING, VENTING, AND BLEEDING PROPELLANT TANKS. IN
 . BOTH HORIZONTAL AND VERTICAL VEHICLE ORIENTATION.
 . FAILURE MODE: EXTERNAL LEAKAGE (S)
 . DURING FLIGHT
 . CAUSE(S):
 . VIBRATION, AND LOOSENING OF RETAINER NUT, PIECE PART STRUCTURAL FAILURE,
 . MECHANICAL SHOCK.
 . EFFECT(S): ON (A) SUBSYSTEM (B) INTERFACES (C) MISSION (D) CREW/VEHICLE:
 . (A) LOSS OF PROPELLANT OVERBOARD (1ST ORDER FAILURE FOR LOOSE RETAINING
 . NUT). (B) POSSIBLE FIRE/EXPLOSION IF FUEL REACTS WITH OXIDIZER (2ND
 . ORDER) OR EXTREME HEAT DURING RE-ENTRY. (C) POSSIBLE LOSS OF MISSION
 . DUE TO FLUID LOSS. (D) POSSIBLE LOSS OF CREW/VEHICLE IF FAILURE OCCURS
 . PRIOR TO ET SEPARATION.
 . CORRECTING ACTION:
 . INITIATE ABORT OR RESCUE OPERATIONS.
 . REMARKS/HAZARDS:
 . POTENTIAL HAZARD FROM FIRE, EXPLOSION, AND FREE PROPELLANTS. SEE
 . HAZARD 1YXX-0302-C5.

SHUTTLE CRITICAL ITEMS LIST - ORBITER 102

SUBSYSTEM : FWD - REACTION CONTROL FMEA NO 03-2F -102150-1 REV: 12/08/78
 . ASSEMBLY : PROPELLANT ABORT: CRIT. FUNC: 1
 . P/N RI : MC276-0018 CRIT. HDW: 1
 . P/N VENDOR: 76301000 MISSIONS: HF VF X FF OF SM
 . QUANTITY : 6 PHASE(S): PL LO X CC X DO X LS

. :
 . : THREE REQ PER PROPELLANT

. REDUNDANCY SCREEN: A-N/A B-N/A C-N/A

. PREPARED BY:

. DES C SCARLETT

. REL R DIEHL

APPROVED BY:

DES *C. Scarlett 12/13/8*
 REL *C. E. Dainoff 1/15/78*

APPROVED BY (NASA):

SSM *W. K. Kinsler*
 REL *J. A. Kinsler*

APPROVED WITH CHANGES

See Section 13.0

. ITEM: DISCONNECT, QUICK, FILL

. PROPELLANT, SPRING LOADED POPPET & STRUCTURAL CAP (MD119-126).

. FUNCTION:

. TO PROVIDE FOR DRAINING, VENTING, AND BLEEDING PROPELLANT TANKS. IN BOTH HORIZONTAL AND VERTICAL VEHICLE ORIENTATION.

. FAILURE MODE: EXTERNAL LEAKAGE (S)

. DURING FLIGHT

. CAUSE(S):

. VIBRATION, AND LOOSENING OF RETAINER NUT, PIECE PART STRUCTURAL FAILURE, MECHANICAL SHOCK.

. EFFECT(S): ON (A) SUBSYSTEM (B) INTERFACES (C) MISSION (D) CREW/VEHICLE:

. (A) LOSS OF PROPELLANT OVERBOARD (1ST ORDER FAILURE FOR LOOSE RETAINING NUT). (B) POSSIBLE FIRE/EXPLOSION IF FUEL REACTS WITH OXIDIZER (2ND ORDER) OR EXTREME HEAT DURING RE-ENTRY. (C) POSSIBLE LOSS OF MISSION DUE TO FLUID LOSS. (D) POSSIBLE LOSS OF CREW/VEHICLE IF FAILURE OCCURS PRIOR TO ET SEPARATION.

. DISPOSITION & RATIONALE (A) DESIGN (B) TEST (C) INSPECTION (D) FAILURE HISTORY:

. (A) CAP SEAL DESIGN DETERMINED TO BE ADEQUATE TO PRECLUDE LEAKAGE. DESIGN FACTOR OF SAFETY IS 3.0 X 710 PSIG MAX WORKING PRESSURE. CAP PLUS COUPLING CONSTITUTES DUAL SEALING. ALL RETAINER NUTS ARE PROPERLY TORQUED TO PRECLUDE LOOSENING. (B) SEALS ARE EXPOSED TO OVER 500 CYCLES DURING DEVELOPMENT. COUPLINGS ARE SUBJECTED TO 600 OPERATIONAL CYCLES IN QUAL TEST. ALL CAPS & COUPLINGS LEAK TESTED FOR 3 MIN. AT PRESSURES UP TO 1.25 MAX WORKING PRESSURE DURING ACCEPTANCE TEST. TURNAROUND LEAK CHECKS PERFORMED BEFORE EACH FLIGHT. RANDOM VIBRATION PERFORMED DURING QUAL PROGRAM. 68 MINUTES IN TWO EXES AT ANTICIPATED MISSION LEVELS. (C) TURNAROUND INSPECTION INCLUDES VISUAL INSPECTING ALL COUPLINGS THAT HAVE BEEN USED DURING TURNAROUND FOR DAMAGE PLUS INSPECTING FOR LEAKS DURING LEAK CHECKS. ALSO, PROPER BLEED SCREW TORQUE IS VERIFIED PRIOR TO REINSTALLATION OF ANY CAPS THAT HAVE BEEN REMOVED. SUPPLIER AUDIT CONDUCTED 4-5-77 VERIFIED THAT SUPPLIER INSPECTION CONTROLS RAW MATERIAL PARTS IDENTIFICATION, MFG PROCESSES, CONTAMINATION CONTROL, AND STORAGE ENVIRONMENTS. (D) NEW DESIGN FOR SHUTTLE APPLICATION. NO FLIGHT FAILURE HISTORY.

1. DOES THE FLIGHT SOFTWARE DETECT THIS FAILURE MODE (i.e., AUTOMATICALLY ANNUNCIATE OR TAKE ACTION IN RESPONSE)? YES ☐ NO ☐
- 1a. IF NOT, DOES THE HARDWARE PROVIDE INFORMATION THAT THE FLIGHT SOFTWARE COULD USE TO DETECT THE FAILURE? *YES ☐ NO ☐
2. ARE THE ANSWERS TO QUESTIONS 1 AND 1a CONSISTENT WITH THE FMEA EVALUATION OF IN-FLIGHT DETECTABILITY? YES ☐ *NO ☐
3. DOES THE FLIGHT SOFTWARE TAKE ACTION TO NEGATE THE EFFECTS OF THE FAILURE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? YES ☐ NO ☐
- 3a. IF NOT, DOES THE CAPABILITY EXIST FOR THE SOFTWARE TO COMPENSATE FOR THIS FAILURE MODE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? *YES ☐ NO ☐
4. AS A RESULT OF THIS FAILURE MODE, CAN THE SOFTWARE OVERSTRESS THE HARDWARE OR INDUCE ANOTHER FAILURE? *YES ☐ NO ☐
5. CAN THIS FAILURE MODE, IN COMBINATION WITH SOFTWARE LOGIC, ADVERSELY AFFECT OTHER FUNCTIONS? *YES ☐ NO ☐
6. HOW MANY OF THESE HARDWARE FAILURES CAN THE SHUTTLE TOLERATE (CONSIDER CREW ACTION AND HARDWARE/SOFTWARE OPERATION)? NOTE CHANGE TO FMEA CRITICALITY. *0 ☐ *1 ☐ 2 ☐
7. IF CREW ACTION IS REQUIRED TO RESPOND TO THIS FAILURE MODE, ARE CUES PROVIDED TO SIGNAL THE NEED FOR INTERVENTION AND THE REQUIRED CORRECTIVE ACTION? N/A ☐ YES ☐ NO ☐
8. IF THE ANSWER TO EITHER 1 OR 3 IS YES:
 - A. CAN THE BFS BE ENGAGED AFTER OCCURRENCE? YES ☐ *NO ☐
 - B. WILL BFS TOLERATE FAILURE WITHOUT LOSS OF CREW/VEHICLE? YES ☐ *NO ☐

*EXPLANATION REQUIRED (SEE BELOW)

CHANGE/RETENTION RATIONALE SUMMARY

- | | | |
|---|---|--|
| 1. <input type="checkbox"/> NO H/S ISSUES | 3. <input type="checkbox"/> NO SOFTWARE DETECTION | 5. <input type="checkbox"/> ACCEPTANCE RATIONALE BELOW |
| 2. <input type="checkbox"/> HARDWARE ACCEPTS RISK | 4. <input type="checkbox"/> DETECTION DURING CHECKOUT | 6. <input type="checkbox"/> RECOMMENDED CHANGES BELOW |

☐ FMEA CHANGE RECOMMENDED

EXPLANATION/COMMENTS:

Out of scope - ground operations only.

SHUTTLE FAILURE MODE AND EFFECTS ANALYSIS - ORSITER 102

```

SUBSYSTEM : FWD - REACTION CONTROL          FMEA NO 03-2F -102150-2          REV:06/27/71.
.ASSEMBLY : PROPELLANT                      ABORT:                      CRIT. FUNC:
.P/N PI    : MC276-0018                     CRIT. HWD:                   3
.P/N VENDOR: 76301000                      MISSIONS: HF VF X HF GF SM
.QUANTITY  : 6                             PHASE(S): PL X LD DD DD LS
.          :                               NUMBER OF SUCCESS PATHS REMAINING
.          : THREE REQ PER PROPELLANT AFTER FIRST FAILURE: 0
.          : REDUNDANCY SCREEN: A-PASS B-N/A C-PAS:
.FAILURE DETECTABLE IN FLIGHT?. NA          TIME TO EFFECT:
.          :                               SECONDS TO HOURS
.          :                               REFERENCE DOCUMENTS:
.          :                               MJ070-0001-01B
.          :                               SD72-SH-0103-2
.GROUND TURNAROUND?.....YES              VS70-4210C1
.GROUND EQUIPMENT FLOW RATE READ OUT

```

PREPARED BY:		APPROVED BY:
DES	C SCARLETT	DES _____
REL	R DIEHL	REL _____

- .ITEM: DISCONNECT, QUICK, FILL
- . PROPELLANT, SPRING LOADED POPPET & STRUCTURAL CAP (MO119-126).
- .FUNCTION:
- . TO PROVIDE FOR DRAINING, VENTING, AND BLEEDING PROPELLANT TANKS. IN BOTH HORIZONTAL AND VERTICAL VEHICLE ORIENTATION.
- .FAILURE MODE: FAILS CLOSED (F)
- . DURING GROUND OPERATIONS
- .CAUSE(S):
- . CONTAMINATION, PIECE PART STRUCTURAL FAILURE IMPROPER HANDLING.
- .EFFECT(S): ON (A)SUBSYSTEM (B)INTERFACES (C)MISSION (D)CREW/VEHICLE:
- . (A) LOSS OF FILL CAPABILITY. (B) INCREASED GROUND OPERATIONS REQUIREMENTS. (C) LAUNCH DELAY. (D) NONE.
- .CORRECTING ACTION:
- . REMOVE AND REPLACE FILL VALVE OR ATTEMPT RECONNECTION.
- .REMARKS/HAZARDS:
- . NONE.

- HARDWARE/SOFTWARE ANALYSIS CHECKLIST

03-2F-102170-1

SUBSYSTEM Fwd Reaction Control

FMEA NUMBER

SD75-SH-0016A

ITEM DC Solenoid Operated Valve
Vernier Thruster Manifold

FAILURE MODE Fails Closed - Premature Operation

1. DOES THE FLIGHT SOFTWARE DETECT THIS FAILURE MODE (i.e., AUTOMATICALLY ANNUNCIATE OR TAKE ACTION IN RESPONSE)? YES ☒ NO ☐
- 1a. IF NOT, DOES THE HARDWARE PROVIDE INFORMATION THAT THE FLIGHT SOFTWARE COULD USE TO DETECT THE FAILURE? *YES ☐ NO ☐
2. ARE THE ANSWERS TO QUESTIONS 1 AND 1a CONSISTENT WITH THE FMEA EVALUATION OF IN-FLIGHT DETECTABILITY? YES ☒ *NO ☐
3. DOES THE FLIGHT SOFTWARE TAKE ACTION TO NEGATE THE EFFECTS OF THE FAILURE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? YES ☐ NO ☒
- 3a. IF NOT, DOES THE CAPABILITY EXIST FOR THE SOFTWARE TO COMPENSATE FOR THIS FAILURE MODE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? *YES ☐ NO ☒
4. AS A RESULT OF THIS FAILURE MODE, CAN THE SOFTWARE OVERSTRESS THE HARDWARE OR INDUCE ANOTHER FAILURE? *YES ☐ NO ☒
5. CAN THIS FAILURE MODE, IN COMBINATION WITH SOFTWARE LOGIC, ADVERSELY AFFECT OTHER FUNCTIONS? *YES ☐ NO ☒
6. HOW MANY OF THESE HARDWARE FAILURES CAN THE SHUTTLE TOLERATE (CONSIDER CREW ACTION AND HARDWARE/SOFTWARE OPERATION)? NOTE CHANGE TO FMEA CRITICALITY. *0 ☐ *1 ☒ 2 ☐
7. IF CREW ACTION IS REQUIRED TO RESPOND TO THIS FAILURE MODE, ARE CUES PROVIDED TO SIGNAL THE NEED FOR INTERVENTION AND THE REQUIRED CORRECTIVE ACTION? N/A ☐ YES ☒ NO ☐
8. IF THE ANSWER TO EITHER 1 OR 3 IS YES:
 - A. CAN THE BFS BE ENGAGED AFTER OCCURRENCE? YES ☒ *NO ☐
 - B. WILL BFS TOLERATE FAILURE WITHOUT LOSS OF CREW/VEHICLE? YES ☒ *NO ☐

*EXPLANATION REQUIRED (SEE BELOW)

CHANGE/RETENTION RATIONALE SUMMARY

- | | | |
|--|---|--|
| 1. <input type="checkbox"/> NO H/S ISSUES | 3. <input type="checkbox"/> NO SOFTWARE DETECTION | 5. <input type="checkbox"/> ACCEPTANCE RATIONALE BELOW |
| 2. <input checked="" type="checkbox"/> HARDWARE ACCEPTS RISK | 4. <input type="checkbox"/> DETECTION DURING CHECKOUT | 6. <input type="checkbox"/> RECOMMENDED CHANGES BELOW |

☐ FMEA CHANGE RECOMMENDED

EXPLANATION/COMMENTS:

1. Manifold status on CRT and panel talk back is available.
6. One failure is all that can occur since there is no redundancy. The Shuttle can tolerate this failure since it is a criticality 3.
7. The measurements V42X1332X and V42X1232X are downlisted and available for CRT callup.

SHUTTLE FAILURE MODE AND EFFECTS ANALYSIS - ORBITER 104

SUBSYSTEM : FWD - REACTION CONTROL FMEA NO 03-2F -102170-1 REV: 12/08/77.
 .ASSEMBLY : PROPELLANT FEED ABORT: CRIT. FUNC: 2
 .P/N RI : MC284-0420-0011/-0012 CRIT. hwd: 2
 .P/N VENDOR: 73895-0011/-0012 MISSIONS: HF VF X HF GF SM
 .QUANTITY : 2 PHASE(S): FL LO OG X LO LS
 . : ONE REQ'D PER PROPELLANT NUMBER OF SUCCESS PATHS REMAINING
 . : AFTER FIRST FAILURE: 0
 . REDUNDANCY SCREEN: A-PASS B-PASS C-FAIL
 .FAILURE DETECTABLE IN FLIGHT? YES TIME TO EFFECT:
 .MANIFLD POSITN INDICATOR V42X1232E SECONDS
 .V42X1332E REFERENCE DOCUMENTS:
 . MJC70-0001-G18
 .GROUND TURNAROUND?.....YES SD72-SH-0103-2
 .SAME AS FLIGHT VS70-421001
 .
 .
 .
 . PREPARED BY: APPROVED BY:
 . DES R BURKHART DES _____
 . REL R DIEHL REL _____
 .
 .
 .ITEM: VLVE,DC SOLEN OPERATED -
 . VERNIER THRUSTER MANIFOLD, (1/4") 91-STABLE, SOLENOID DRIVEN 28VDC.
 (LV 157-158)
 .FUNCTION:
 . TO PROVIDE ISOLATION OF PROPELLANT MANIFOLD AND ASSOCIATED VERNIER
 THRUSTERS 1) SUBSEQUENT TO DOWNSTREAM FAILURE(S) 2) PRIOR TO SYSTEM
 ACTIVATION.
 .FAILURE MODE: FAILS CLOSED-PREATURE (F)
 . OPERATION
 .CAUSE(S):
 . IMPROPER ELECTRICAL SIGNAL (CONTINUOUS SHORT), PIECE PART FAILURE,
 CONTAMINATION, VIBRATION.
 .EFFECT(S): ON (A)SUBSYSTEM (B)INTERFACES (C)MISSION (D)CREW/VEHICLE:
 . (A) LOSS OF VERNIER THRUSTER FUNCTION. (B) NONE. (C) POSSIBLE EARLY
 . MISSION TERMINATION. BECAUSE LARGE THRUSTERS INADEQUATE FOR SMALL RATE
 ATTITUDE HOLD. (D) NONE.
 .CORRECTING ACTION:
 . ATTEMPT TO UTILIZE LARGE THRUSTER IN AFFECTED AXIS TO MAINTAIN SMALL
 DEADBAND.
 .REMARKS/HAZARDS:
 . POTENTIAL FOR COLLISION WITH OR LOSS OF PAYLOAD/SATELLITE. SEE
 CONSOLIDATED CONTROLS FMEA # 73895 FMEA 1.

ORIGINAL PAGE IS
OF POOR QUALITY

SHUTTLE CRITICAL ITEMS LIST - CRBITER 102

SUBSYSTEM : FWD - REACTION CONTROL FMEA NO 03-2F -102170-1 REV: 12/08/77
 .ASSEMBLY : PROPELLANT FEED ABCRT: CRIT. FUNC: 2
 .P/N RI : MC284-0420-0011/-0012 CRIT. HDW: 2
 .P/N VENDOR: 73895-0011/-0012 MISSIONS: HF VF X FF GF SM
 .QUANTITY : 2 PHASE(S): PL LD OO X OO LS
 . : ONE REQ'D PER PROPELLANT

REDUNDANCY SCREEN: A-PASS B-PASS C-FAIL

PREPARED BY: DES R BURKHART APPROVED BY: DES *[Signature]* APPROVED BY (NASA): *[Signature]*
 .REL R DIEHL REL *[Signature]* 14/5/78 SSM *[Signature]* RES *[Signature]*

ITEM: VALVE, DC SOLENOID OPERATED -
 . VERNIER THRUSTER MANIFOLD, (1/4") SI-STABLE, SOLENOID DRIVEN 28VDC.
 (LV 157-158)
 .FUNCTION:
 . TO PROVIDE ISOLATION OF PROPELLANT MANIFOLD AND ASSOCIATED VERNIER
 THRUSTERS 1) SUBSEQUENT TO DOWNSTREAM FAILURE(S) 2) PRIOR TO SYSTEM
 ACTIVATION.
 .FAILURE MODE: FAIL CLOSED-PREMATURE (F)
 . OPERATION
 .CAUSE(S):
 . IMPROPER ELECTRICAL SIGNAL (CONTINUOUS SHORT), PIECE PART FAILURE,
 CONTAMINATION, VIBRATION.
 .EFFECT(S): ON (A) SUBSYSTEM (B) INTERFACES (C) MISSION (D) CREW/VEHICLE:
 . (A) LOSS OF VERNIER THRUSTER FUNCTION. (B) NONE. (C) POSSIBLE EARLY
 MISSION TERMINATION. BECAUSE LARGE THRUSTERS INADEQUATE FOR SMALL RATE
 ATTITUDE HOLD. (D) NONE.
 .DISPOSITION & RATIONALE (A) DESIGN (B) TEST (C) INSPECTION (D) FAILURE HISTORY:
 . (A) SERIES CONTROL CIRCUITRY PROVIDED TO MINIMIZE FAILURE MODE, 100
 MICRON FILTER IS PROVIDED. MEDIA HAS BEEN FILTERED TO 25 MICRON PRIOR
 TO ENTERING TANK. SPECIAL EMPHASIS PLACED ON THE DESIGN AND LAYOUT OF
 SOLENOID WIRING TO PRECLUDE SHORTS. (B) QUAL TEST INCLUDES 48 MINUTES
 PER AXIS OF RANDOM VIBRATION AT ANTICIPATED MISSION LEVELS AND LIFE
 TESTING CONSISTING OF 2000 OPERATING CYCLES. ITEM IS USED DURING SYSTEM
 EVALUATION AT WHITE SANDS TESTING. (C) TURNAROUND INSPECTION INCLUDES
 MONITORING TESTS TO VERIFY ELECTRICAL POWER TO SOLENOID VALVE FOR
 EVIDENCE OF SHORT CIRCUIT, SUPPLIER AUDIT CONDUCTED 8-31-77 VERIFIED
 SUPPLIER INSPECTION EXERCISED CONTROL OF PARTS ID, PARTS PROTECTION, MFG
 PROCESSES, CONTAMINATION CONTROL, AND CORROSION PROTECTION VERIFICATION.
 (D) FAILURES ON APOLLO WERE MOSTLY DUE TO CONTAMINATION RESULTING FROM
 IN-HOUSE PROCESSING.

. HARDWARE/SOFTWARE ANALYSIS CHECKLIST 03-2F-111110-1

SUBSYSTEM Fwd Reaction Control

FMEA NUMBER SD75-SH-0016A

ITEM Tank Assembly and Propellant Acquisition Device

FAILURE MODE Large Rupture

1. DOES THE FLIGHT SOFTWARE DETECT THIS FAILURE MODE (i.e., AUTOMATICALLY ANNUNCIATE OR TAKE ACTION IN RESPONSE)? YES ☒ NO ☐
- 1a. IF NOT, DOES THE HARDWARE PROVIDE INFORMATION THAT THE FLIGHT SOFTWARE COULD USE TO DETECT THE FAILURE? *YES ☐ NO ☐
2. ARE THE ANSWERS TO QUESTIONS 1 AND 1a CONSISTENT WITH THE FMEA EVALUATION OF IN-FLIGHT DETECTABILITY? YES ☐ *NO ☒
3. DOES THE FLIGHT SOFTWARE TAKE ACTION TO NEGATE THE EFFECTS OF THE FAILURE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? YES ☐ NO ☒
- 3a. IF NOT, DOES THE CAPABILITY EXIST FOR THE SOFTWARE TO COMPENSATE FOR THIS FAILURE MODE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? *YES ☐ NO ☒
4. AS A RESULT OF THIS FAILURE MODE, CAN THE SOFTWARE OVERSTRESS THE HARDWARE OR INDUCE ANOTHER FAILURE? *YES ☐ NO ☒
5. CAN THIS FAILURE MODE, IN COMBINATION WITH SOFTWARE LOGIC, ADVERSELY AFFECT OTHER FUNCTIONS? *YES ☐ NO ☒
6. HOW MANY OF THESE HARDWARE FAILURES CAN THE SHUTTLE TOLERATE (CONSIDER CREW ACTION AND HARDWARE/SOFTWARE OPERATION)? NOTE CHANGE TO FMEA CRITICALITY. *0 ☒ *1 ☐ 2 ☐
7. IF CREW ACTION IS REQUIRED TO RESPOND TO THIS FAILURE MODE, ARE CUES PROVIDED TO SIGNAL THE NEED FOR INTERVENTION AND THE REQUIRED CORRECTIVE ACTION? N/A ☐ YES ☒ NO ☐
8. IF THE ANSWER TO EITHER 1 OR 3 IS YES:
 - A. CAN THE BFS BE ENGAGED AFTER OCCURRENCE? YES ☒ *NO ☐
 - B. WILL BFS TOLERATE FAILURE WITHOUT LOSS OF CREW/VEHICLE? YES ☐ *NO ☒

*EXPLANATION REQUIRED (SEE BELOW)

CHANGE/RETENTION RATIONALE SUMMARY

- | | | |
|--|---|--|
| 1. <input type="checkbox"/> NO H/S ISSUES | 3. <input type="checkbox"/> NO SOFTWARE DETECTION | 5. <input type="checkbox"/> ACCEPTANCE RATIONALE BELOW |
| 2. <input checked="" type="checkbox"/> HARDWARE ACCEPTS RISK | 4. <input type="checkbox"/> DETECTION DURING CHECKOUT | 6. <input type="checkbox"/> RECOMMENDED CHANGES BELOW |

In-Flight Detectability
☒ FMEA CHANGE RECOMMENDED

EXPLANATION/COMMENTS:

1. V42P1115C, 1116C will give a class 2 caution and warning alert.
 Gross leak indication will detect failure.

If an internal rupture occurs and helium reaches the thrusters you will get a "fail off" light from redundancy management.

6. There are no redundant tanks.

8b. Backup flight system same as primary.

SHUTTLE FAILURE MODE AND EFFECTS ANALYSIS - ORBITER 102

SUBSYSTEM : FWD - REACTION CONTROL FMEA NO 03-2F -11110-1 REV:12/19/7:
 .ASSEMBLY : PROPELLANT FEED ABORT: CRIT. FUNC: 1
 .P/N RI : MC282-0061-0001/0002 CRIT. HWD: 1
 .P/N VENDOR: 855C3320000-009/010 MISSIONS: HF VF X FF DF SM
 .QUANTITY : 2 PHASE(S): PL X LG X GU X DG X LS
 . : ONE REQ'D NUMBER OF SUCCESS PATHS REMAINING
 . : PER PROPELLANT AFTER FIRST FAILURE: 0
 . REDUNDANCY SCREEN: A-N/A B-N/A C-N/A
 .FAILURE DETECTABLE IN FLIGHT? YES TIME TO EFFECT:
 .MONITOR TANK PRESSURES V42P1310C,1312C,1316C, SECONDS
 .1116C REFERENCE DOCUMENTS:
 . : MJ070-0001-01B
 .GROUND TURNAROUND?.....YES SD72-SH-0103-2
 .SAME AS FLIGHT VS70-421001
 .
 .
 .
 .
 . PREPARED BY: APPROVED BY:
 . DES R BEMIS DES _____
 . REL R DIEHL REL _____
 .
 .
 .ITEM: TANK ASSY, PROPELLANT
 . INCLUDING PROPELLANT ACQUISITION DEVICE AND COMPARTMENT BARRIER. (TK
 103).
 .FUNCTION:
 . TO STORE/SUPPLY PROPELLANT TO REACTION CONTROL ENGINE MANIFOLDS.
 NOMINAL STORAGE PRESSURE 245 PSIG + OR -15 (1.5 SAFETY FACTOR).
 .FAILURE MODE: STRUCTURAL FAILURE - (S)
 . TANK WALL CRACK OR RUPTURE WHICH PROPGATES AROUND TANK
 .CAUSE(S):
 . VIBRATION, OVERPRESSURIZATION, MECHANICAL SHOCK, STRESS CORROSION,
 FATIGUE.
 .EFFECT(S): (A) SUBSYSTEM (B) INTERFACES (C) MISSION (D) CREW/VEHICLE:
 . (A) LOSS OF PROPELLANT SUPPLY FOR MODULE THRUSTERS. (B) POTENTIAL
 . FIRE/EXPLOSION AND CERTAIN CONTAMINATION OF SUBSYSTEMS IN RCS
 COMPARTMENT. (C) LOSS OF MISSION. (D) POTENTIAL LOSS OF CREW/VEHICLE
 FROM EXPLOSION AND/OR LACK OF PROPELLANT.
 .CORRECTING ACTION:
 . NONE AVAILABLE
 .REMARKS/HAZARDS:
 . POTENTIAL HAZARD FROM FIRE, EXPLOSION DUE TO FREE FUEL IN MODULE.
 REFERENCE HAZARDS 1YXX-0302-02 AND 1YXX-0302-04.

SHUTTLE CRITICAL ITEMS LIST - ORBITER 102

SUBSYSTEM : FWD - REACTION CONTROL FMEA NO 03-2F -111110-1 REV:11/09/77
 .ASSEMBLY : PROPELLANT FEED ABORT: CRIT. FUNC: 1
 .P/N RI : MC282-0061-0001/0002 CRIT. HDW: 1
 .P/N VENDOR: 855C3320000-009/010 MISSIONS: HF VF X FF OF SM
 .QUANTITY : 2 PHASE(S): PL X LO X ON X DO X LS
 . : ONE REQ'D
 . : PER PROPELLANT

REDUNDANCY SCREEN: A-N/A B-N/A C-N/A

PREPARED BY: DES R BEMIS APPROVED BY: DES *[Signature]* APPROVED BY (NASA): *[Signature]*
 .REL R DIEHL REL *[Signature]* SSN *[Signature]*
 .REL *[Signature]*

APPROVED WITH CHANGES
 See Section 13.0

- .ITEM: TANK ASSY, PROPELLANT
- . INCLUDING PROPELLANT ACQUISITION DEVICE AND COMPARTMENT BARRIER. (TK 103).
- .FUNCTION:
- . TO STORE/SUPPLY PROPELLANT TO REACTION CONTROL ENGINE MANIFOLDS. NOMINAL STORAGE PRESSURE 245 PSIG + OR -15 (1.5 SAFETY FACTOR).
- .FAILURE MODE: STRUCTURAL FAILURE - (S)
- . TANK WALL CRACK OR RUPTURE WHICH PROPOGATES AROUND TANK
- .CAUSE(S):
- . VIBRATION, OVERPRESSURIZATION, MECHANICAL SHOCK, STRESS CORROSION, FATIGUE.
- .EFFECT(S): ON (A)SUBSYSTEM (B)INTERFACES (C)MISSION (D)CREW/VEHICLE:
- . (A) LOSS OF PROPELLANT SUPPLY FOR MODULE THRUSTERS. (B) POTENTIAL FIRE/EXPLOSION AND CERTAIN CONTAMINATION OF SUBSYSTEMS IN RCS COMPARTMENT. (C) LOSS OF MISSION. (D) POTENTIAL LOSS OF CREW/VEHICLE FROM EXPLOSION AND/OR LACK OF PROPELLANT.
- .DISPOSITION & RATIONALE (A)DESIGN (B)TEST (C)INSPECTION (D)FAILURE HISTORY:
- . (A) DESIGN FACTR OF SAFETY IS 1.5 MIN. DEVELOPMENT TESTS INCLUDE WELD CYCLE LIFE (800 CYCLES), FRACTURE MECHANICS, FORGING EVALUATION, AND TUBE SWAGING. (B) TANKS SUBJECTED TO RADIOGRAPHIC, FLUORESCENT PENETRANT, PROOF PRESSURE (1.33 MAX OPER PRESSURE), AND EXTERNAL LEAK TESTS DURING ACCEPTANCE TESTING. TANKS SUBJECTED TO 90 DAY PROPELLANT EXPOSURE, 800 PRESSURE CYCLES, 48 MINUTES PER AXIS OF 3.9 GRMS RANDOM VIBRATION AND BURST PRESSURE DURING QUAL PROGRAM. (C) TURNAROUND INSPECTION INCLUDES MONITORING FUNCTIONAL TEST DURING PRESSURIZATION CYCLE FOR EVIDENCE OF LEAKS. VISUAL INSPECT WHERE ACCESSABLE FOR DAMAGE. AUDIT CONDUCTED 11-1-76 VERIFIED SUPPLIER INSPECTION CONTROL OF MATL IDENTIFICATION PARTS PROTECTION MFG PROCESSES, CORROSION PROTECTION PROVISIONS, NDE EXAM OF WELDS AND STORAGE ENVIRONMENTS. (D) NONE (NEW DEVELOPMENT ITEM).

. HARDWARE/SOFTWARE ANALYSIS CHECKLIST 03-2F-111110-2

SUBSYSTEM Fwd Reaction Control

FMEA NUMBER

SD75-SH-0016A

ITEM Tank Assembly and Propellant Acquisition Device FAILURE MODE Small Crack - External Leakage

1. DOES THE FLIGHT SOFTWARE DETECT THIS FAILURE MODE (i.e., AUTOMATICALLY ANNUNCIATE OR TAKE ACTION IN RESPONSE)? YES ☒ NO ☐
- 1a. IF NOT, DOES THE HARDWARE PROVIDE INFORMATION THAT THE FLIGHT SOFTWARE COULD USE TO DETECT THE FAILURE? *YES ☐ NO ☐
2. ARE THE ANSWERS TO QUESTIONS 1 AND 1a CONSISTENT WITH THE FMEA EVALUATION OF IN-FLIGHT DETECTABILITY? YES ☐ *NO ☒
3. DOES THE FLIGHT SOFTWARE TAKE ACTION TO NEGATE THE EFFECTS OF THE FAILURE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? YES ☐ NO ☒
- 3a. IF NOT, DOES THE CAPABILITY EXIST FOR THE SOFTWARE TO COMPENSATE FOR THIS FAILURE MODE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? *YES ☐ NO ☒
4. AS A RESULT OF THIS FAILURE MODE, CAN THE SOFTWARE OVERSTRESS THE HARDWARE OR INDUCE ANOTHER FAILURE? *YES ☐ NO ☒
5. CAN THIS FAILURE MODE, IN COMBINATION WITH SOFTWARE LOGIC, ADVERSELY AFFECT OTHER FUNCTIONS? *YES ☐ NO ☒
6. HOW MANY OF THESE HARDWARE FAILURES CAN THE SHUTTLE TOLERATE (CONSIDER CREW ACTION AND HARDWARE/SOFTWARE OPERATION)? NOTE CHANGE TO FMEA CRITICALITY. *0 ☒ *1 ☐ 2 ☐
7. IF CREW ACTION IS REQUIRED TO RESPOND TO THIS FAILURE MODE, ARE CUES PROVIDED TO SIGNAL THE NEED FOR INTERVENTION AND THE REQUIRED CORRECTIVE ACTION? N/A ☐ YES ☒ NO ☐
8. IF THE ANSWER TO EITHER 1 OR 3 IS YES:
 - A. CAN THE BFS BE ENGAGED AFTER OCCURRENCE? YES ☒ *NO ☐
 - B. WILL BFS TOLERATE FAILURE WITHOUT LOSS OF CREW/VEHICLE? YES ☐ *NO ☒

*EXPLANATION REQUIRED (SEE BELOW)

CHANGE/RETENTION RATIONALE SUMMARY

- | | | |
|--|---|--|
| 1. <input type="checkbox"/> NO H/S ISSUES | 3. <input type="checkbox"/> NO SOFTWARE DETECTION | 5. <input type="checkbox"/> ACCEPTANCE RATIONALE BELOW |
| 2. <input checked="" type="checkbox"/> HARDWARE ACCEPTS RISK | 4. <input type="checkbox"/> DETECTION DURING CHECKOUT | 6. <input type="checkbox"/> RECOMMENDED CHANGES BELOW |

In-Flight Detectability
☒ FMEA CHANGE RECOMMENDED

EXPLANATION/COMMENTS:

1. V42P1115C, 1116C will give a class 2 caution and warning alert. Gross leak indication will detect failure. If an internal rupture occurs and helium reaches the thrusters you will get a "fail off" light from redundancy management.
6. There are no redundant tanks.
- 8b. Backup flight system same as primary.

SHUTTLE FAILURE MODE AND EFFECTS ANALYSIS - ORBITER 102

SUBSYSTEM : FWD - REACTION CONTROL FMEA NO 03-2F -111110-2 REV:12/18/71
 .ASSEMBLY : PROPELLANT FEED ABORT: CRIT. FUNC: 2
 .P/N RI : MC282-0061-0001/0002 CRIT. FAD: 2
 .P/N VENDOR: 255C3320000-009/CIC MISSIONS: HF VF X FF OF SM
 .QUANTITY : 2 PHASE(S): PL X LO X CO X DO X LS
 . : ONE REQ'D NUMBER OF SUCCESS PATHS REMAINING
 . : PER PROPELLANT AFTER FIRST FAILURE: 0
 . REDUNDANCY SCREEN: A-N/A B-N/A C-N/A
 .FAILURE DETECTABLE IN FLIGHT?. YES TIME TO EFFECT:
 .MONITOR TANK PRESSURE V42P-1310C,1312C,1316C, DAYS
 .1116C REFERENCE DOCUMENTS:
 . MJ37C-0001-CIE
 .GROUND TURNAROUND?.....YES SD72-SH-0103-2
 .SAME AS FLIGHT AND VISUAL OBSERVATION VS70-421001
 .
 .
 .
 . PREPARED BY: APPROVED BY:
 . DES R BEMIS DES _____
 . REL R DIEHL REL _____
 .
 .
 .ITEM: TANK ASSY, PROPELLANT
 . INCLUDING PROPELLANT ACQUISITION DEVICE AND COMPARTMENT BARRIER. (TR
 103).
 .FUNCTION:
 . TO STORE/SUPPLY PROPELLANT TO REACTION CONTROL ENGINE MANIFOLDS.
 NOMINAL STORAGE PRESSURE 245 PSIG + OR -15 (1.5 SAFETY FACTOR).
 .FAILURE MODE: EXTERNAL LEAKAGE - (S)
 . TANK CRACK OR FLAW WHICH ALLOWS A LIMITED AMOUNT OF PROPELLANT TO LEAVE
 THE TANK.
 .CAUSE(S):
 . VIBRATION, STRESS CORROSION, PRESSURE CYCLES, FATIGUE OR FLANGE SEAL
 FAILURE.
 .EFFECT(S): ON (A)SUBSYSTEM (B)INTERFACES (C)MISSION (D)CREW/VEHICLE:
 . (A) LOSS OF A QUANTITY OF PROPELLANT AND HELIUM TO AN EXTENT DEPENDENT
 ON SIZE AND LOCATION OF LEAK. (B) CONTAMINATION OF SURROUNDING AREA AND
 SUBSYSTEMS. (C) LOSS OF MISSION. (D) POTENTIAL EXPLOSION AND LOSS OF
 CREW/VEHICLE IF IGNITION SOURCE PRESENT (SECOND FAILURE).
 .CORRECTING ACTION:
 . CLOSE HELIUM PRESSURIZATION ISOLATION VALVE TO MINIMIZE AMOUNT OF
 PROPELLANT/HELIUM LOST.
 .REMARKS/HAZARDS:
 . POTENTIAL HAZARD FROM FREE PROPELLANT IN MODULE. NO REDUNDANCY PROVIDED
 FOR THIS ITEM. REFERENCE HAZARD 1YXX-0302-05.

ORIGINAL PAGE IS
OF POOR QUALITY

SHUTTLE CRITICAL ITEMS LIST - ORBITER 102

SUBSYSTEM : FWD - REACTION CONTROL FMEA NO 03-2F -111110-2 REV: 11/10/79
 .ASSEMBLY : PROPELLANT FEED ABORT: CRIT. FUNC: 2
 .P/N RI : MC282-0061-0001/0002 CRIT. HDW: 2
 .P/N VENDOR: 855C3320000-009/010 MISSIONS: HF VF X FF CF SM
 .QUANTITY : 2 PHASE(S): PL X LO X CO X DO X LS
 . : ONE REQ'D
 . : PER PROPELLANT

REDUNDANCY SCREEN: A-N/A R-N/A C-N/A

PREPARED BY: APPROVED BY: APPROVED BY (NASA):
 .DES R BEMIS DES *[Signature]* SS4 *[Signature]*
 .REL R DIEHL REL *[Signature]* 12/15/75 REG 101 *[Signature]*

APPROVED WITH CHANGES
 See Section 13.0

- .ITEM: TANK ASSY, PROPELLANT
- . INCLUDING PROPELLANT ACQUISITION DEVICE AND COMPARTMENT BARRIER. (TK 103).
- .FUNCTION:
 - . TO STORE/SUPPLY PROPELLANT TO REACTION CONTROL ENGINE MANIFOLDS. NOMINAL STORAGE PRESSURE 245 PSIG + OR -15 (1.5 SAFETY FACTOR).
- .FAILURE MODE: EXTERNAL LEAKAGE - (S)
- . TANK CRACK OR FLAW WHICH ALLOWS A LIMITED AMOUNT OF PROPELLANT TO LEAVE THE TANK.
- .CAUSE(S):
 - . VIBRATION, STRESS CORROSION, PRESSURE CYCLES, FATIGUE OR FLANGE SEAL FAILURE.
- .EFFECT(S): ON (A)SUBSYSTEM (B)INTERFACES (C)MISSION (D)CREW/VEHICLE:
 - . (A) LOSS OF A QUANTITY OF PROPELLANT AND HELIUM TO AN EXTENT DEPENDENT ON SIZE AND LOCATION OF LEAK. (B) CONTAMINATION OF SURROUNDING AREA AND SUBSYSTEMS. (C) LOSS OF MISSION. (D) POTENTIAL EXPLOSION AND LOSS OF CREW/VEHICLE IF IGNITION SOURCE PRESENT (SECOND FAILURE).
- .DISPOSITION & RATIONALE (A)DESIGN (B)TEST (C)INSPECTION (D)FAILURE HISTORY:
 - . (A) DESIGN FACTOR OF SAFETY IS 1.5 MIN. DEVELOPMENT TESTS INCLUDE WELD CYCLE LIFE (800 CYCLES), FRACTURE MECHANICS, FORGING EVALUATION, AND TUBE SWAGING. (B) TANKS SUBJECTED TO RADIOGRAPHIC, FLUORESCENT PENETRANT, PROOF PRESSURE (1.33 MAX OPER PRESSURE), AND EXTERNAL LEAK TESTS DURING ACCEPTANCE TESTING. TANKS SUBJECTED TO 90 DAY PROPELLANT EXPOSURE, 800 PRESSURE CYCLES, 48 MINUTES PER AXIS OF 3.9 G RMS RANDOM VIBRATION AND BURST PRESSURE DURING QUAL PROGRAM. (C) TURNAROUND INSPECTION INCLUDES MONITORING FUNCTIONAL TEST DURING PRESSURIZATION CYCLE FOR EVIDENCE OF LEAKS. VISUAL INSPECT WHERE ACCESSIBLE FOR DAMAGE. AUDIT CONDUCTED 11-1-76 VERIFIED SUPPLIER INSPECTION CONTROL OF MATL IDENTIFICATION PARTS PROTECTION MFG PROCESSES, CORROSION PROTECTION PROVISIONS, NDE EXAM OF WELDS AND STORAGE ENVIRONMENTS. (D) NONE (NEW DEVELOPMENT ITEM).

HARDWARE/SOFTWARE ANALYSIS CHECKLIST 03-2F-111110-3

SUBSYSTEM Fwd. Reaction Control

FMEA NUMBER SD75-SH-0016A

ITEM Tank Assembly and Propellant Acquisition Device

FAILURE MODE Restricted Flow

1. DOES THE FLIGHT SOFTWARE DETECT THIS FAILURE MODE (i.e., AUTOMATICALLY ANNUNCIATE OR TAKE ACTION IN RESPONSE)? YES ☒ NO ☐
- 1a. IF NOT, DOES THE HARDWARE PROVIDE INFORMATION THAT THE FLIGHT SOFTWARE COULD USE TO DETECT THE FAILURE? *YES ☐ NO ☐
2. ARE THE ANSWERS TO QUESTIONS 1 AND 1a CONSISTENT WITH THE FMEA EVALUATION OF IN-FLIGHT DETECTABILITY? YES ☐ *NO ☒
3. DOES THE FLIGHT SOFTWARE TAKE ACTION TO NEGATE THE EFFECTS OF THE FAILURE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? YES ☐ NO ☒
- 3a. IF NOT, DOES THE CAPABILITY EXIST FOR THE SOFTWARE TO COMPENSATE FOR THIS FAILURE MODE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? *YES ☐ NO ☒
4. AS A RESULT OF THIS FAILURE MODE, CAN THE SOFTWARE OVERSTRESS THE HARDWARE OR INDUCE ANOTHER FAILURE? *YES ☐ NO ☒
5. CAN THIS FAILURE MODE, IN COMBINATION WITH SOFTWARE LOGIC, ADVERSELY AFFECT OTHER FUNCTIONS? *YES ☐ NO ☒
6. HOW MANY OF THESE HARDWARE FAILURES CAN THE SHUTTLE TOLERATE (CONSIDER CREW ACTION AND HARDWARE/SOFTWARE OPERATION)? NOTE CHANGE TO FMEA CRITICALITY. *0 ☒ *1 ☐ 2 ☐
7. IF CREW ACTION IS REQUIRED TO RESPOND TO THIS FAILURE MODE, ARE CUES PROVIDED TO SIGNAL THE NEED FOR INTERVENTION AND THE REQUIRED CORRECTIVE ACTION? N/A ☐ YES ☒ NO ☐
8. IF THE ANSWER TO EITHER 1 OR 3 IS YES:
 - A. CAN THE BFS BE ENGAGED AFTER OCCURRENCE? YES ☒ *NO ☐
 - B. WILL BFS TOLERATE FAILURE WITHOUT LOSS OF CREW/VEHICLE? YES ☐ *NO ☒

*EXPLANATION REQUIRED (SEE BELOW)

CHANGE/RETENTION RATIONALE SUMMARY

- | | | |
|--|---|--|
| 1. <input type="checkbox"/> NO H/S ISSUES | 3. <input type="checkbox"/> NO SOFTWARE DETECTION | 5. <input type="checkbox"/> ACCEPTANCE RATIONALE BELOW |
| 2. <input checked="" type="checkbox"/> HARDWARE ACCEPTS RISK | 4. <input type="checkbox"/> DETECTION DURING CHECKOUT | 6. <input type="checkbox"/> RECOMMENDED CHANGES BELOW |

☐ FMEA CHANGE RECOMMENDED

EXPLANATION/COMMENTS:

1. "Fail Off" detection in RCS RM.
6. No redundant tanks.
7. ~~No correcting action - abort.~~
- 8b. Same as primary.

SHUTTLE FAILURE MODE AND EFFECTS ANALYSIS - ORBITER 1C2

```

SUBSYSTEM : FWD - REACTION CONTROL      FMEA NO 03-2F -11111G-3      REV:12/18/71
ASSEMBLY   : PROPELLANT FEED             ABORT:                CRIT. FUNC:    1
P/N RI     : MC282-0061-0001/0002        CRIT. HWC:    1
P/N VENDOR: 855C3320GOC-CC9/GIC         MISSIONS: HF VF X FF UF SM
QUANTITY   : 2                           PHASE(S): PL LC X CD X DG X LS
          : ONE REQ'D                     NUMBER OF SUCCESS PATHS REMAINING
          : PER PROPELLANT                 AFTER FIRST FAILURE:              0
                                           REDUNDANCY SCREEN: A-N/A E-N/A C-N/A
FAILURE DETECTABLE IN FLIGHT?. YES  →    TIME TO EFFECT:
ENGINE PERFORMANCE                        SECONDS TO DAYS
                                           REFERENCE DOCUMENTS:
                                           MJ070-C001-C1B
GROUND TURNAROUND?.....NO              SD72-SH-C103-2
                                           VS70-421001
PREPARED BY:                            APPROVED BY:
DES                                             DES _____
REL                                             REL _____
ITEM: TANK ASSY, PROPELLANT
INCLUDING PROPELLANT ACQUISITION DEVICE AND COMPARTMENT BARRIER. (TK
103).
FUNCTION:
TO STORE/SUPPLY PROPELLANT TO REACTION CONTROL ENGINE MANIFOLDS.
NOMINAL STORAGE PRESSURE 245 PSIG + GR -15 (1.5 SAFETY FACTOR).
FAILURE MODE: RESTRICTED FLOW - (S)
STRUCTURAL FAILURE OF PROPELLANT ACQUISITION DEVICE WHICH BLOCKS OR
RETARDS RATE OF FLOW OF PROPELLANT INTO TANK OUTLET.
CAUSE(S):
VIBRATION, MECHANICAL SHOCK, EXCESSIVE FLOW RATES DUE TO EXCESSIVE GAS
IN THRUSTER MANIFOLD. (SEE FAILURE MODE NO. 4 ON NEXT PAGE).
EFFECT(S): ON (A) SUBSYSTEM (B) INTERFACES (C) MISSION (D) CREW/VEHICLE:
(A) LOSS OF FULL PROPELLANT FLOW CAPABILITY/HELIUM INGESTION. (B) NONE.
(C) LOSS OF MISSION DUE TO LOSS OF PROPELLANT. (D) NONE UNLESS FAILURE
OCCURS WHEN MODULE REQUIRED FOR ET SEPARATION.
CORRECTING ACTION:
NONE AVAILABLE - CLOSE DOWN FRCS AND ABORT MISSION.
REMARKS/HAZARDS:
COMPLETE LOSS OF FRCS USAGE THEREFORE ALL ATTITUDE CONTROL MUST BE
ACCOMPLISHED BY ARCS.

```

ORIGINAL PAGE IS
OF POOR QUALITY

SHUTTLE CRITICAL ITEMS LIST - ORBITER 102

SUBSYSTEM : FWD - REACTION CONTROL FMEA NO 03-2F -111110-3 REV: 11/10/76
 ASSEMBLY : PROPELLANT FEED ABORT: CRIT. FUNC: 1
 P/N RI : MC282-0061-0001/0002 CRIT. HDW: 1
 P/N VENDOR: 855C3320000-009/010 MISSIONS: HF VF X FF OF SM
 QUANTITY : 2 PHASE(S): PL LO X DO X DO X LS
 : ONE REQ'D
 : PER PROPELLANT

REDUNDANCY SCREEN: A-N/A B-N/A C-N/A

PREPARED BY: APPROVED BY: APPROVED BY: NASA
 DES R BEMIS DES *[Signature]* SSM *[Signature]*
 REL R DIEHL REL *[Signature]* 12/15/78 REL *[Signature]*
 APPROVED WITH CHANGES
 See Section 13.0

- ITEM: TANK ASSY, PROPELLANT
- INCLUDING PROPELLANT ACQUISITION DEVICE AND COMPARTMENT BARRIER. (TK 103).
- FUNCTION:
 - TO STORE/SUPPLY PROPELLANT TO REACTION CONTROL ENGINE MANIFOLDS. NOMINAL STORAGE PRESSURE 245 PSIG + OR -15 (1.5 SAFETY FACTOR).
- FAILURE MODE: RESTRICTED FLOW - (S)
 - STRUCTURAL FAILURE OF PROPELLANT ACQUISITION DEVICE WHICH BLOCKS OR RETARDS RATE OF FLOW OF PROPELLANT INTO TANK OUTLET.
- CAUSE(S):
 - VIBRATION, MECHANICAL SHOCK, EXCESSIVE FLOW RATES DUE TO EXCESSIVE GAS IN THRUSTER MANIFOLD. (SEE FAILURE MODE NO. 4 ON NEXT PAGE).
- EFFECT(S): ON (A) SUBSYSTEM (B) INTERFACES (C) MISSION (D) CREW/VEHICLE:
 - (A) LOSS OF FULL PROPELLANT FLOW CAPABILITY/HELIUM INGESTION. (B) NONE. (C) LOSS OF MISSION DUE TO LOSS OF PROPELLANT. (D) NONE UNLESS FAILURE OCCURS WHEN MODULE REQUIRED FOR ET SEPARATION.
- DISPOSITION & RATIONALE (A) DESIGN (B) TEST (C) INSPECTION (D) FAILURE HISTORY:
 - (A) 1.5 DESIGN SAFETY FACTOR. DEVELOPMENT TESTS VERIFY WELD CYCLE LIFE, SCREEN REPAIR METHOD, SCREEN CYCLE LIFE AND SCREEN FLOW. (B) PROPELLANT ACQUISITION DEVICE COMPONENTS, SUBASSEMBLIES AND TANK ASSY INTEGRITY VERIFIED BY PERFORMING BUBBLE POINT TEST. TANKS SUBJECTED TO PROPELLANT EXPOSURE, 200 EXPULSION CYCLES, 48 MINUTES PER AXIS OF 3.9 GRMS RANDOM VIBRATION AND BURST PRESSURE DURING QUAL PROGRAM. (C) TURNAROUND INSPECT INCLUDES MONITOR FLOW DURING FUNCTIONAL TESTS. AUDIT CONDUCTED 11-1-76 VERIFIED SUPPLIER INSPECTION CONTROL OF MATL IDENTIFICATION PARTS PROTECTION MFG PROCESSES, CORROSION PROTECTION PROVISIONS, NDE EXAM OF WELDS AND STORAGE ENVIRONMENTS. (D) NONE (NEW DEVELOPMENT ITEM).

. HARDWARE/SOFTWARE ANALYSIS CHECKLIST 03-2F-111110-4

SUBSYSTEM Fwd Reaction Control

FMEA NUMBER

SD75-SH-0016A

ITEM Tank Assembly and Propellant Acquisition FAILURE MODE Loss of Gas in Propellant
Device Acquisition Device

1. DOES THE FLIGHT SOFTWARE DETECT THIS FAILURE MODE (i.e., AUTOMATICALLY ANNUNCIATE OR TAKE ACTION IN RESPONSE)? YES ☒ NO ☐
- 1a. IF NOT, DOES THE HARDWARE PROVIDE INFORMATION THAT THE FLIGHT SOFTWARE COULD USE TO DETECT THE FAILURE? *YES ☐ NO ☒
2. ARE THE ANSWERS TO QUESTIONS 1 AND 1a CONSISTENT WITH THE FMEA EVALUATION OF IN-FLIGHT DETECTABILITY? YES ☐ *NO ☒
3. DOES THE FLIGHT SOFTWARE TAKE ACTION TO NEGATE THE EFFECTS OF THE FAILURE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? YES ☐ NO ☒
- 3a. IF NOT, DOES THE CAPABILITY EXIST FOR THE SOFTWARE TO COMPENSATE FOR THIS FAILURE MODE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? *YES ☐ NO ☒
4. AS A RESULT OF THIS FAILURE MODE, CAN THE SOFTWARE OVERSTRESS THE HARDWARE OR INDUCE ANOTHER FAILURE? *YES ☐ NO ☒
5. CAN THIS FAILURE MODE, IN COMBINATION WITH SOFTWARE LOGIC, ADVERSELY AFFECT OTHER FUNCTIONS? *YES ☐ NO ☒
6. HOW MANY OF THESE HARDWARE FAILURES CAN THE SHUTTLE TOLERATE (CONSIDER CREW ACTION AND HARDWARE/SOFTWARE OPERATION)? NOTE CHANGE TO FMEA CRITICALITY. *0 ☒ *1 ☐ 2 ☐
7. IF CREW ACTION IS REQUIRED TO RESPOND TO THIS FAILURE MODE, ARE CUES PROVIDED TO SIGNAL THE NEED FOR INTERVENTION AND THE REQUIRED CORRECTIVE ACTION? N/A ☐ YES ☐ NO ☒
8. IF THE ANSWER TO EITHER 1 OR 3 IS YES:
 - A. CAN THE BFS BE ENGAGED AFTER OCCURRENCE? YES ☒ *NO ☐
 - B. WILL BFS TOLERATE FAILURE WITHOUT LOSS OF CREW/VEHICLE? YES ☐ *NO ☒

*EXPLANATION REQUIRED (SEE BELOW)

CHANGE/RETENTION RATIONALE SUMMARY

- | | | |
|--|---|--|
| 1. <input type="checkbox"/> NO H/S ISSUES | 3. <input type="checkbox"/> NO SOFTWARE DETECTION | 5. <input type="checkbox"/> ACCEPTANCE RATIONALE BELOW |
| 2. <input checked="" type="checkbox"/> HARDWARE ACCEPTS RISK | 4. <input type="checkbox"/> DETECTION DURING CHECKOUT | 6. <input type="checkbox"/> RECOMMENDED CHANGES BELOW |

☒ FMEA CHANGE RECOMMENDED

EXPLANATION/COMMENTS:

1. "Fail Off" detection in RCS RM.
6. No redundant tanks.
7. No correcting action - abort.
8. Same as primary.

SHUTTLE FAILURE MODE AND EFFECTS ANALYSIS - ORBITER 102

```

SUBSYSTEM : FWD - REACTION CONTROL          FMEA NO 03-2F -111110-4          REV:12/15/70
.ASSEMBLY  : PROPELLANT FEED                ABORT:                      CRIT. FUNC:    2
.P/N R1    : MC282-CC61-0001/0002          CRIT. HAD:    2
.P/N VENDOR: 855C332000C-009/C10          MISSIONS:   HF   VF X FF   OF   SM
.QUANTITY  : 2                             .PHASE(S):   PL X LC X -OC X BD X LS
.          : ONE REQ'D                     .NUMBER OF SUCCESS PATHS REMAINING
.          : PER PROPELLANT                AFTER FIRST FAILURE:          G
.          :                               REDUNDANCY SCREEN:   A-N/A   B-N/A   C-N/A
.NOT 921657M
.FAILURE DETECTABLE IN FLIGHT? YES          TIME TO EFFECT:
.ENGINE PERFORMANCE AND C HAMBER PRESSURE.V42P1541  SECONDS
.          :                               REFERENCE DOCUMENTS:
.          :                               MJ07C-0001-C1E
.          :                               SD72-SH-C103-2
.GROUND TURNAROUND?.....NO               VS70-421001
.          :

```

PREPARED BY:

CE S

REL

R E M I S

R DIEHL

APPROVED BY:

On 5

522

- .ITEM: TANK ASSY, PROPELLANT
- . INCLUDING PROPELLANT ACQUISITION DEVICE AND COMPARTMENT BARRIER. (TK 103).
- .FUNCTION:
- . TO STORE/SUPPLY PROPELLANT TO REACTION CONTROL ENGINE MANIFOLDS. NOMINAL STORAGE PRESSURE 245 PSIG + OR -15 (1.5 SAFETY FACTOR).
- .FAILURE MODE: LOSS OF GAS RETENTION IN (S)
- . PROPELLANT ACQUISITION DEVICE (PAC).
- .CAUSE(S):
- . VIBRATION, SHOCK, PROPELLANT CONTAMINATION (CHEMICAL OR DIRT).
- .EFFECT(S): ON (A)SUBSYSTEM (B)INTERFACES (C)MISSION (D)CREW/VEHICLE:
- . (A) EXCESSIVE GAS FLOW TO THRUSTERS COULD CAUSE TANK BARRIER FAILURE.
- . (B) POTENTIAL DAMAGE TO THRUSTERS IF UNDETECTED. (C) ABORT DECISION.
- . (D) POSSIBLE LOSS OF CREW/VEHICLE IF FAILURE OCCURS PRIOR TO LT SEPARATION.
- .CORRECTING ACTION:
- . SHUT DOWN FRCS AND ABORT MISSION.
- .REMARKS/HAZARDS:
- . IF UNDETECTED, THE THRUSTERS COULD BE DAMAGED WHICH COULD CAUSE ENTRY UNCERTAINTY.

SHUTTLE CRITICAL ITEMS LIST - ORBITER 102

SUBSYSTEM : FWD - REACTION CONTROL FMEA NO 03-2F -111110-4 REV: 11/10/
 .ASSEMBLY : PROPELLANT FEED ABORT: CPIT. FUNC: 2
 .P/N RI : 4C282-0061-0001/0002 CRIT. HDN: 2
 .P/N VENDOR: 855C3320000-009/010 MISSIONS: HF VF X FF OF SM
 .QUANTITY : 2 PHASE(S): PL X LO X CO X DO X LS
 . : ONE REQ'D
 . : PER PROPELLANT
 .
 . REDUNDANCY SCREEN: A-N/A B-N/A C-N/
 .
 . PREPARED BY: APPROVED BY: APPROVED BY (NAME):
 .DES R SEMIS DES *[Signature]* SSM *[Signature]*
 .REL R DIEHL REL *[Signature]* 14/776 RED *[Signature]*
 .
 . APPROVED WITH CHANGES
 . See Section 13.0
 . ITEM: TANK ASSY, PROPELLANT
 . INCLUDING PROPELLANT ACQUISITION DEVICE AND COMPARTMENT BARRIER. (TK 103).
 . FUNCTION:
 . TO STORE/SUPPLY PROPELLANT TO REACTION CONTROL ENGINE MANIFOLDS. NOMINAL STORAGE PRESSURE 245 PSIG + OR -15 (1.5 SAFETY FACTOR).
 . FAILURE MODE: LOSS OF GAS RETENTION IN (S)
 . PROPELLANT ACQUISITION DEVICE (PAD).
 . CAUSE(S):
 . VIBRATION, SHOCK, PROPELLANT CONTAMINATION (CHEMICAL OR DIRT).
 . EFFECT(S): (A) SUBSYSTEM (B) INTERFACES (C) MISSION (D) CREW/VEHICLE:
 . (A) EXCESSIVE GAS FLOW TO THRUSTERS COULD CAUSE TANK BARRIER FAILURE.
 . (B) POTENTIAL DAMAGE TO THRUSTERS IF UNDETECTED. (C) ABORT DECISION.
 . (D) POSSIBLE LOSS OF CREW/VEHICLE IF FAILURE OCCURS PRIOR TO ET SEPARATION.
 . DISPOSITION & RATIONALE (A) DESIGN (B) TEST (C) INSPECTION (D) FAILURE HISTORY:
 . (A) DESIGN FACTOR OF SAFETY IS 1.5 MIN. DEVELOPMENT TESTS INCLUDE WELD CYCLE LIFE (800 CYCLES), FRACTURE MECHANICS, FORGING EVALUATION, AND TUBE SWAGING. (B) PROPELLANT ACQUISITION DEVICE COMPONENTS, SUBASSEMBLIES AND TANK ASSY INTEGRITY VERIFIED BY PERFORMING BUBBLE POINT TESTS. TANKS SUBJECTED TO PROPELLANT EXPOSURE, 200 EXPULSION CYCLES, 48 MINUTES PER AXIS OF 3.9 GRMS RANDOM VIBRATION AND BURST PRESSURE DURING QUAL PROGRAM. (C) TURNAROUND INSPECTION INCLUDES PERIODIC BUBBLE POINT CHECKS OF THE PAD. AUDIT CONDUCTED 11-1-76 VERIFIED SUPPLIER INSPECTION CONTROL OF MATL IDENTIFICATION PARTS PROTECTION MFG PROCESSES, CORROSION PROTECTION PROVISIONS, NDE EXAM OF WELDS AND STORAGE ENVIRONMENTS.
 . (D) NONE (NEW DEVELOPMENT ITEM).

Hardware/Software Analysis Checklist

03-2F-121308-1

SUBSYSTEM Fwd Reaction Control

FMEA NUMBER

SD75-SH-0016A

ITEM Flex Line and Fittings

FAILURE MODE

External Leakage

1. DOES THE FLIGHT SOFTWARE DETECT THIS FAILURE MODE (i.e., AUTOMATICALLY ANNUNCIATE OR TAKE ACTION IN RESPONSE)? YES ☒ NO ☐
- 1a. IF NOT, DOES THE HARDWARE PROVIDE INFORMATION THAT THE FLIGHT SOFTWARE COULD USE TO DETECT THE FAILURE? *YES ☐ NO ☐
2. ARE THE ANSWERS TO QUESTIONS 1 AND 1a CONSISTENT WITH THE FMEA EVALUATION OF IN-FLIGHT DETECTABILITY? YES ☒ *NO ☐
3. DOES THE FLIGHT SOFTWARE TAKE ACTION TO NEGATE THE EFFECTS OF THE FAILURE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? YES ☐ NO ☒
- 3a. IF NOT, DOES THE CAPABILITY EXIST FOR THE SOFTWARE TO COMPENSATE FOR THIS FAILURE MODE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? *YES ☐ NO ☒
4. AS A RESULT OF THIS FAILURE MODE, CAN THE SOFTWARE OVERSTRESS THE HARDWARE OR INDUCE ANOTHER FAILURE? *YES ☐ NO ☒
5. CAN THIS FAILURE MODE, IN COMBINATION WITH SOFTWARE LOGIC, ADVERSELY AFFECT OTHER FUNCTIONS? *YES ☐ NO ☒
6. HOW MANY OF THESE HARDWARE FAILURES CAN THE SHUTTLE TOLERATE (CONSIDER CREW ACTION AND HARDWARE/SOFTWARE OPERATION)? NOTE CHANGE TO FMEA CRITICALITY. *0 ☐ *1 ☐ 2 ☒
7. IF CREW ACTION IS REQUIRED TO RESPOND TO THIS FAILURE MODE, ARE CUES PROVIDED TO SIGNAL THE NEED FOR INTERVENTION AND THE REQUIRED CORRECTIVE ACTION? N/A ☐ YES ☒ NO ☐
8. IF THE ANSWER TO EITHER 1 OR 3 IS YES:
 - A. CAN THE BFS BE ENGAGED AFTER OCCURRENCE? YES ☒ *NO ☐
 - B. WILL BFS TOLERATE FAILURE WITHOUT LOSS OF CREW/VEHICLE? YES ☒ *NO ☐

*EXPLANATION REQUIRED (SEE BELOW)

CHANGE/RETENTION RATIONALE SUMMARY

- | | | |
|--|---|--|
| 1. <input type="checkbox"/> NO H/S ISSUES | 3. <input type="checkbox"/> NO SOFTWARE DETECTION | 5. <input type="checkbox"/> ACCEPTANCE RATIONALE BELOW |
| 2. <input checked="" type="checkbox"/> HARDWARE ACCEPTS RISK | 4. <input type="checkbox"/> DETECTION DURING CHECKOUT | 6. <input type="checkbox"/> RECOMMENDED CHANGES BELOW |

☐ FMEA CHANGE RECOMMENDED

EXPLANATION/COMMENTS:

1. V42P1115C, 1116C will give class 2 alarm.

Gross leak detection applies.

SHUTTLE FAILURE MODE AND EFFECTS ANALYSIS - ORBITER 102

SUBSYSTEM : FWD - REACTION CONTROL FMEA NO 03-2F -121308-1 REV: 11/10/70
 . ASSEMBLY : THRUSTER ABORT: CKIT. FUNC: 1
 . P/N RI : MC271-GC84. CKIT. HWU: 1
 . P/N VENDOR: 74713-THRU 74717 MISSIONS: HF VF X FF CF X SM
 . QUANTITY : 30 PHASE(S): PL X LG X UG X DG X LS X
 . : ONE FUEL AND ONE OXIDIZ. NUMBER OF SUCCESS PATHS REMAINING
 . : PER THRUSTER AFTER FIRST FAILURE: 2
 . REDUNDANCY SCREEN: A-N/A B-N/A C-N/A
 . FAILURE DETECTABLE IN FLIGHT?. YES : TIME TO EFFECT:
 . MANIFOLD PRESSURE. V#? SECONDS TO DAYS
 . REFERENCE DOCUMENTS:
 . MJ70-0001-01B
 . GROUND TURNAROUND?.....YES SD72-SH-0103-2
 . VISUAL INSPECTION VS70-421001

PREPARED BY:

DES
REL

J. TAGGART
R DIEHL

APPROVED BY:

DES
REL

. ITEM: LINE ASSEM., FLEXIBLE
AND FITTINGS.

. FUNCTION:

. TO PROVIDE COUPLING BETWEEN PROPELLANT SUBSYSTEM AND FORWARD RCS
PRIMARY AND VERNIER THRUSTER.

. FAILURE MODE: EXTERNAL LEAKAGE - (S)

. RUPTURE OF LINE OR COUPLING.

. CAUSE(S):

. FATIGUE, SHOCK, VIBRATION, HANDLING.

. EFFECT(S): ON (A) SUBSYSTEM (B) INTERFACES (C) MISSION (D) CREW/VEHICLE:

. (A) LOSS OF PROPELLANTS TO EXTENT OF LEAK SIZE. (B) INCREASED GNC

. CONTROL & USE OF ALTERNATE THRUSTERS. (C) POTENTIAL MISSION TERMINATION
PRIOR TO PLANNED TIME. (D) NO EFFECT AFTER ASCENT UNLESS LEAK IS
EXCESSIVE & RESULTS IN IGNITION WITH REACTANT (2ND ORDER FAILURE) DURING
A RTLS ABORT THE LOSS OF A MANIFOLD RESULTS IN THE LOSS OF TWO DOWN
FIRING THRUSTERS WHICH RESULTS IN CRIT 1. DURING ASCENT THE FAILURE
CANNOT BE DETECTED AND ISOLATED WHICH RESULTS IN POSSIBLE LOSS OF
VEHICLE.

. CORRECTING ACTION:

. ISOLATE THRUSTER AT MANIFOLD.

. REMARKS/HAZARDS:

. POTENTIAL HAZARD FROM FREE FUEL IN MODULE.

ORIGINAL PAGE IS
OF POOR QUALITY

SHUTTLE CRITICAL ITEMS LIST - CRBITER 102

SUBSYSTEM : FWD - REACTION CONTROL FMEA NO 03-2F -121308-1 REV: 11/10/
 .ASSEMBLY : THRUSTER ABORT: CRIT. FUNC: 1
 .P/N RI : MC271-0084 CRIT. HDW: 1
 .P/N VENDOR: 74713-THRU 74717 MISSIONS: HF VF X FF OF X SM
 .QUANTITY : 30 PHASE(S): PL X LO X OO X CO X LS X
 . : ONE FUEL AND ONE OXIDIZ.
 . : PER THRUSTER
 . REDUNDANCY SCREEN: A-N/A B-N/A C-N/
 .
 .PREPARED BY: J. TAGGART APPROVED BY: *[Signature]* APPROVED BY (NASA): *[Signature]*
 .DES DES *[Signature]* SSM *[Signature]*
 .REL R DIEHL REL *[Signature]* REL *[Signature]*
 .
 .
 .ITEM: LINE ASSEM., FLEXIBLE
 . AND FITTINGS.
 .FUNCTION:
 . TO PROVIDE COUPLING BETWEEN PROPELLANT SUBSYSTEM AND FORWARD RCS
 . PRIMARY AND VERNIER THRUSTER.
 .FAILURE MODE: EXTERNAL LEAKAGE - (S)
 . RUPTURE OF LINE OR COUPLING.
 .CAUSE(S):
 . FATIGUE, SHOCK, VIBRATION, HANDLING.
 .EFFECT(S): ON (A)SUBSYSTEM (B)INTERFACES (C)MISSION (D)CREW/VEHICLE:
 . (A) LOSS OF PROPELLANTS TO EXTENT OF LEAK SIZE. (B) INCREASED GN&C
 . CONTROL & USE OF ALTERNATE THRUSTERS. (C) POTENTIAL MISSION TERMINATION
 . PRIOR TO PLANNED TIME. (D) NO EFFECT AFTER ASCENT UNLESS LEAK IS
 . EXCESSIVE & RESULTS IN IGNITION WITH REACTANT (2ND ORDER FAILURE) DURING
 . A RTLS ABORT THE LOSS OF A MANIFOLD RESULTS IN THE LOSS OF TWO DOWN
 . FIRING THRUSTERS WHICH RESULTS IN CRIT 1. DURING ASCENT THE FAILURE
 . CANNOT BE DETECTED AND ISOLATED WHICH RESULTS IN POSSIBLE LOSS OF
 . VEHICLE. ~
 .DISPOSITION & RATIONALE (A)DESIGN (B)TEST (C)INSPECTION (D)FAILURE HISTORY:
 . (A) DESIGN BURST PRESSURE IS UP TO 3 TIMES THE MAX OPER PRESSURE OF 700
 . PSIG. PROOF PRESSURE IS UP TO 1.5 TIMES THE MAX OPER PRESSURE. THE
 . DESIGN ALLOWS SUFFICIENT MOVEMENT TO PRECLUDE EXCESSIVE STRESSES DURING
 . INSTALLATION AND OPERATION. LINES CAN BE ISOLATED AT THE MANIFOLD IN
 . CASE OF LEAKAGE. (B) POST INSTALLATION TEST AND OPERATIONAL CHECKOUTS
 . WILL VERIFY SYSTEM INTEGRITY. ALL LINES SUBJECTED TO PROOF PRESSURE
 . DURING ATP AND RANDOM VIBRATION AT ANTICIPATED MISSION LEVELS DURING
 . QUAL TESTING. LINES ARE ALSO TESTED DURING SYSTEM EVALUATION AT WHITE
 . SANDS TEST FACILITY. (C) SEE FMEA/CIL 102106-1. (D) NO HISTORY OF
 . FAILURE IN FLIGHT. (NEW DEVELOPMENT ITEM FOR MANNED FLIGHT APPLICATION.)

APPROVED WITH CHANGES
 See Section 13.0

C-2

1. DOES THE FLIGHT SOFTWARE DETECT THIS FAILURE MODE (i.e., AUTOMATICALLY ANNUNCIATE OR TAKE ACTION IN RESPONSE)? YES ☒ NO ☐
- 1a. IF NOT, DOES THE HARDWARE PROVIDE INFORMATION THAT THE FLIGHT SOFTWARE COULD USE TO DETECT THE FAILURE? *YES ☐ NO ☒
2. ARE THE ANSWERS TO QUESTIONS 1 AND 1a CONSISTENT WITH THE FMEA EVALUATION OF IN-FLIGHT DETECTABILITY? YES ☒ *NO ☐
3. DOES THE FLIGHT SOFTWARE TAKE ACTION TO NEGATE THE EFFECTS OF THE FAILURE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? YES ☐ NO ☒
- 3a. IF NOT, DOES THE CAPABILITY EXIST FOR THE SOFTWARE TO COMPENSATE FOR THIS FAILURE MODE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? *YES ☐ NO ☒
4. AS A RESULT OF THIS FAILURE MODE, CAN THE SOFTWARE OVERSTRESS THE HARDWARE OR INDUCE ANOTHER FAILURE? *YES ☐ NO ☒
5. CAN THIS FAILURE MODE, IN COMBINATION WITH SOFTWARE LOGIC, ADVERSELY AFFECT OTHER FUNCTIONS? *YES ☐ NO ☒
6. HOW MANY OF THESE HARDWARE FAILURES CAN THE SHUTTLE TOLERATE (CONSIDER CREW ACTION AND HARDWARE/SOFTWARE OPERATION)? NOTE CHANGE TO FMEA CRITICALITY. *0 ☐ *1 ☐ 2 ☒
7. IF CREW ACTION IS REQUIRED TO RESPOND TO THIS FAILURE MODE, ARE CUES PROVIDED TO SIGNAL THE NEED FOR INTERVENTION AND THE REQUIRED CORRECTIVE ACTION? N/A ☐ YES ☐ NO ☒
8. IF THE ANSWER TO EITHER 1 OR 3 IS YES:
 - A. CAN THE BFS BE ENGAGED AFTER OCCURRENCE? YES ☐ *NO ☐
 - B. WILL BFS TOLERATE FAILURE WITHOUT LOSS OF CREW/VEHICLE? YES ☐ *NO ☐

*EXPLANATION REQUIRED (SEE BELOW)

CHANGE/RETENTION RATIONALE SUMMARY:

- | | | |
|--|---|--|
| 1. <input type="checkbox"/> NO H/S ISSUES | 3. <input type="checkbox"/> NO SOFTWARE DETECTION | 5. <input type="checkbox"/> ACCEPTANCE RATIONALE BELOW |
| 2. <input checked="" type="checkbox"/> HARDWARE ACCEPTS RISK | 4. <input type="checkbox"/> DETECTION DURING CHECKOUT | 6. <input type="checkbox"/> RECOMMENDED CHANGES BELOW |

☐ FMEA CHANGE RECOMMENDED

EXPLANATION/COMMENTS:

1. "Fail Off" in RCS RM if sufficiently blocked.

SHUTTLE FAILURE MODE AND EFFECTS ANALYSIS - ORBITER 102

```

SUBSYSTEM : FWC - REACTION CONTROL          FMEA NO 03-2F -121311-1      REV:11/14/7.
.ASSEMBLY : THRUSTER, PRIMARY                ABORT: ABORT              CRIT. FUNC: 1R
.P/N R1 : MC467-0028                        RTLS                     CRIT. HWD: 3
.P/N VENDOR:X30868                          MISSIONS: HF VF X HF GF SM
.QUANTITY : 14                             PHASE(S): PL LG X GL X DO X LS
. : ONE INJECTOR PROVIDED FOR NUMBER OF SUCCESS PATHS REMAINING
. : R EACH PRIMARY THRUSTER AFTER FIRST FAILURE: 2
. REDUNDANCY SCREEN: A-FAIL B-FAIL C-FAIL
.FAILURE DETECTABLE IN FLIGHT?. NO          TIME TO EFFECT:
. : SECONDS
. : REFERENCE DOCUMENTS:
. : MJ070-CC01-GIA
.GROUND TURNAROUND?.....NO              SD72-SH-0100-2
. : VS70-421001

```

PREPARED BY:

DES S

REL

W SEARCY

R DIEHL

APPROVED BY:

DES

REL

.ITEM: INJECTOR, PLATE

• FUNCTION:

- TO RECEIVE FUEL AND OXIDIZER FROM THRUSTER INLET VALVES AND PROVIDE DOUBLET MIXING AT 1.60 OX TO FUEL (WEIGHT) RATIO FOR A HYPERGOLIC REACTION WHICH PRODUCES 825 POUNDS OF THRUST AT 70,000 FEET. ALSO CONTROL CHAMBER WALL COOLING.

•FAILURE MODE: FAILS TO DELIVER PROPS (F)

- AT PROPER MIXTURE RATIO AND FAILS TO PROVIDE ADEQUATE COOLING OF THE COMBUSTOR WALL.

• CAUSE(S):

- CONTAMINATION, BLOCKED ORIFICES.

• EFFECT(S): ON (A) SUBSYSTEM (B) INTERFACES (C) MISSION (D) CREW/VEHICLE:

- (A) LOSS OF ONE THRUSTER IN A GIVEN AXIS. (B) GN&C CONTROL SWITCHING REQUIRED. (C,D) NO EFFECT. (E) POSSIBLE LOSS OF VEHICLE IF FAILURE OCCURS BEFORE ET SEPARATION. DOWN FIRING THRUSTERS REQUIRED FOR ET SEPARATION.

•CORRECTING ACTION:

- SWITCH TO REDUNDANT THRUSTER IN AFFECTED AXIS. ISOLATE MANIFOLD CONTAINING FAILED THRUSTER.

REMARKS/HAZARDS:

- POSSIBLE LOCAL HOT SPOT RESULTING IN COATING DAMAGE OR COMBUSTION BURN THROUGH.

ORIGINAL PAGE IS
OF POOR QUALITY

SHUTTLE CRITICAL ITEMS LIST - ORBITER 102

SUBSYSTEM : FWD - REACTION CONTROL FMEA NO 03-2F -121311-1 REV: 11/14/78
 .ASSEMBLY : THRUSTER, PRIMARY ABORT: ABORT CRIT. FUNC: 1R
 .P/N RI : 4C467-0028 RTLS CRIT. HDN: 3
 .P/N VENDOR: X30888 MISSIONS: HF VF X FF OF SM
 .QUANTITY : 14 PHASE(S): PL LD X OD X DO X LS
 . : ONE INJECTOR PROVIDED FO
 . : R EACH PRIMARY THRUSTER

REDUNDANCY SCREEN: A-FAIL B-FAIL C-FAIL

PREPARED BY: APPROVED BY: APPROVED BY (NASA):
 .DES W SEARCY DES *[Signature]* SSM *[Signature]*
 .REL R DIEHL REL *[Signature]* REL *[Signature]*

DELETE
 See Section 13.0

.ITEM: INJECTOR, PLATE

.FUNCTION:

. TO RECEIVE FUEL AND OXIDIZER FROM THRUSTER INLET VALVES AND PROVIDE
 DOUBLET MIXING AT 1.60 OX TO FUEL (WEIGHT) RATIO FOR A HYPERGOLIC
 REACTION WHICH PRODUCES 825 POUNDS OF THRUST AT 70,000 FEET. ALSO
 CONTROL CHAMBER WALL COOLING.

.FAILURE MODE: FAILS TO DELIVER PROPS (F)

. AT PROPER MIXTURE RATIO AND FAILS TO PROVIDE ADEQUATE COOLING OF THE
 COMBUSTOR WALL.

.CAUSE(S):

. CONTAMINATION, BLOCKED ORIFICES.

.EFFECT(S): ON (A)SUBSYSTEM (B)INTERFACES (C)MISSION (D)CREW/VEHICLE:

. (A) LOSS OF ONE THRUSTER IN A GIVEN AXIS. (B) GN&C CONTROL SWITCHING
 REQUIRED. (C,D) NO EFFECT. (E) POSSIBLE LCSS OF VEHICLE IF FAILURE
 OCCURS BEFORE ET SEPARATION. DOWN FIRING THRUSTERS REQUIRED FOR ET
 SEPARATION.

.DISPOSITION & RATIONALE (A)DESIGN (B)TEST (C)INSPECTION (D)FAILURE HISTORY:

. (A) 75 MICRON FILTER PROVIDED UPSTREAM TO PRECLUDE CONTAMINATION
 FUEL HAS BEEN FILTERED TO 25 MICRONS PRIOR TO ENTERING TANK. ACOUSTIC
 CAVITIES PRECLUDE OCCURRENCE OF COMBUSTION INSTABILITY IN THE EVENT OF
 POOR DISTRIBUTION. (B) TOTAL FLOW & FLOW DISTRIBUTION CHECKED BY WATER
 FLOW TEST AND VERIFIED BY BURN TEST DURING THRUSTER ACCEPTANCE TESTS.
 (C) FIBER OPTICS USED TO VISUALLY INSPECT INJECTOR HOLES FOR EVIDENCE
 OF BURRS AND CONTAMINATION PRIOR TO ASSEMBLY AUDIT CONDUCTED ON 9-2-76
 VERIFIED THAT SUPPLIER INSPECTION CONTROLS RAW MATL VERIFICATION, PARTS
 PROTECTION, MFG FAB AND ASSY OPERATIONS, CONTAMINATION CONTRL, CORROSION
 CONTROL PROVISIONS AND STORAGE ENVIRONMENTS. TURN AROUND INSPECTION TO
 INCLUDE USE OF OPTICS INSPECTION WHERE ACCESSABLE FOR EVIDENCE OF DAMAGE
 & SYSTEM FLUID SAMPLINGS FOR DETECTION OF CONTAMINATION. (D) NO
 FAILURES OF THIS TYPE ON APCLO.

SUBSYSTEM Fwd. Reaction Control

FMEA NUMBER

SD75-SH-0016A

ITEM Thrust ChamberFAILURE MODE Burn Through

1. DOES THE FLIGHT SOFTWARE DETECT THIS FAILURE MODE (i.e., AUTOMATICALLY ANNUNCIATE OR TAKE ACTION IN RESPONSE)? YES ☒ NO ☐
- 1a. IF NOT, DOES THE HARDWARE PROVIDE INFORMATION THAT THE FLIGHT SOFTWARE COULD USE TO DETECT THE FAILURE? *YES ☐ NO ☐
2. ARE THE ANSWERS TO QUESTIONS 1 AND 1a CONSISTENT WITH THE FMEA EVALUATION OF IN-FLIGHT DETECTABILITY? YES ☒ *NO ☐
3. DOES THE FLIGHT SOFTWARE TAKE ACTION TO NEGATE THE EFFECTS OF THE FAILURE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? YES ☐ NO ☒
- 3a. IF NOT, DOES THE CAPABILITY EXIST FOR THE SOFTWARE TO COMPENSATE FOR THIS FAILURE MODE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? *YES ☐ NO ☒
4. AS A RESULT OF THIS FAILURE MODE, CAN THE SOFTWARE OVERSTRESS THE HARDWARE OR INDUCE ANOTHER FAILURE? *YES ☐ NO ☒
5. CAN THIS FAILURE MODE, IN COMBINATION WITH SOFTWARE LOGIC, ADVERSELY AFFECT OTHER FUNCTIONS? *YES ☐ NO ☒
6. HOW MANY OF THESE HARDWARE FAILURES CAN THE SHUTTLE TOLERATE (CONSIDER CREW ACTION AND HARDWARE/SOFTWARE OPERATION)? NOTE CHANGE TO FMEA CRITICALITY. *0 ☐ *1 ☐ 2 ☒
7. IF CREW ACTION IS REQUIRED TO RESPOND TO THIS FAILURE MODE, ARE CUES PROVIDED TO SIGNAL THE NEED FOR INTERVENTION AND THE REQUIRED CORRECTIVE ACTION? N/A ☐ YES ☒ NO ☐
8. IF THE ANSWER TO EITHER 1 OR 3 IS YES:
- A. CAN THE BFS BE ENGAGED AFTER OCCURRENCE? YES ☒ *NO ☐
- B. WILL BFS TOLERATE FAILURE WITHOUT LOSS OF CREW/VEHICLE? YES ☒ *NO ☐

*EXPLANATION REQUIRED (SEE BELOW)

CHANGE/RETENTION RATIONALE SUMMARY

1. ☐ NO H/S ISSUES 3. ☐ NO SOFTWARE DETECTION 5. ☐ ACCEPTANCE RATIONALE BELOW
2. ☒ HARDWARE ACCEPTS RISK 4. ☐ DETECTION DURING CHECKOUT 6. ☐ RECOMMENDED CHANGES BELOW

☒ FMEA CHANGE RECOMMENDEDEXPLANATION/COMMENTS:

FMEA change - Measurement numbers V42X1541X through V42X1556X should be listed as V42P1541A through V42P1556A.

1. RM uses thrust chamber pressure transducers to sense the low pressure in question and give a "fail off" in RCS RM.

7. The thrust chamber measurements are downlinked.

SHUTTLE FAILURE MODE AND EFFECTS ANALYSIS - ORBITER 102

SUBSYSTEM : FWD - REACTION CONTROL FMEA NO 03-2F -121312-1 REV:11/10/7
 .ASSEMBLY : THRUSTER, PRIMARY ABORT: CRIT. FUNC: 1
 .P/N RI : MC467-C028 CRIT. HWD: 1
 .P/N VENDOR: X3C958 MISSIONS: HF VF X FF GF SM
 .QUANTITY : 14 PHASE(S): PL LG X OO X DU X LS
 . : ONE PER THRUSTER NUMBER OF SUCCESS PATHS REMAINING
 . : AFTER FIRST FAILURE: 2
 . REDUNDANCY SCREEN: A-N/A B-N/A C-N/A
 .FAILURE DETECTABLE IN FLIGHT?. YES TIME TO EFFECT:
 .INCIPIENT BURN-THRU DETE CTORS V42X1541X THROUGH SECONDS
 .V42X1556X PC TRANS DUCER IF LEAKAGE REFERENCE DOCUMENTS:
 .IS GROSS ⁽¹⁾ MJ070-0001-G1B
 .GROUND TURNAROUND?.....YES SD72-SH-0103-2
 .VISUAL EXAMINATION VS70-421C01

PREPARED BY:

DES

REL

W SEARCY

R DIEHL

APPROVED BY:

DES

REL

.ITEM: THRUST CHAMBER

. FROM INJECTOR TO NOZZLE EXTENSION (COATED COLUMBIUM).

.FUNCTION:

. TO CONTAIN HYPERGOLIC REACTION OF PROPELLANTS AND TO EXPAND COMBUSTION PRODUCTS TO PRODUCE THRUST THROUGH NOZZLE EXTENSION TO PROVIDE IMPULSE TO VEHICLE.

.FAILURE MODE: OVERHEAT/BURNTHROUGH (S)

. DUE TO INADEQUATE COOLING.

.CAUSE(S):

. BLOCKED (CONTAMINATED) COOLANT (FUEL) INJECTOR HOLES, POOR BOUNDARY FLOW CONDITIONS COMBUSTION INSTABILITY, SEPARATION OR FRACTURE OF PROTECTIVE DISLICIDE COATING.

.EFFECT(S): ON (A)SUBSYSTEM (B)INTERFACES (C)MISSION (D)CREW/VEHICLE:

. (A) LOSS OF A PRIMARY THRUSTER IN A GIVEN AXIS. (B) INCREASED GNCC CONTROL AUTHORITY REQUIRED. (C) POTENTIAL LOSS OF MISSION ABORT DECISION. (D) POTENTIAL LOSS OF VEHICLE. CRITICAL DAMAGE COULD OCCUR BEFORE FAILURE IS DETECTED.

.CORRECTING ACTION:

. ISOLATE THRUSTER AND UTILIZE REDUNDANT THRUSTER IN AFFECTED AXIS. (AUTOMATIC FUNCTION).

.REMARKS/HAZARDS:

. POTENTIAL HAZARD FROM ESCAPING HOT GASES IN MODULE AND POTENTIAL PROPAGATION OF FAILURE IF NOT ISOLATED IN A TIMELY MANNER.

SHUTTLE CRITICAL ITEMS LIST - ORBITER 102

SUBSYSTEM : FWD - REACTION CONTROL FMEA NO 03-2F -121312-1 REV: 11/10/78
 ASSEMBLY : THRUSTER, PRIMARY ABORT: CRIT. FUNC: 1
 P/N RI : MC467-0029 CRIT. HDW: 1
 P/N VENDOR: X30958 MISSIONS: HF VF X FF OF SM
 QUANTITY : 14 PHASE(S): PL LO X DO X DO X LS
 : ONE PER THRUSTER

REDUNDANCY SCREEN: A-N/A B-N/A C-N/A

PREPARED BY: DES W SEARCY APPROVED BY: DES *[Signature]* APPROVED BY: (NASA) *[Signature]*
 REL R DIEHL REL *[Signature]* 12/15/78 SSM *[Signature]*
 APPROVED WITH CHANGES
 See Section 13.0

ITEM: THRUST CHAMBER
 FROM INJECTOR TO NOZZLE EXTENSION (COATED COLUMBIUM).
 FUNCTION:
 TO CONTAIN HYPERGOLIC REACTION OF PROPELLANTS AND TO EXPAND COMBUSTION PRODUCTS TO PRODUCE THRUST THROUGH NOZZLE EXTENSION TO PROVIDE IMPULSE TO VEHICLE.
 FAILURE MODE: OVERHEAT/BURNTHROUGH (S)
 DUE TO INADEQUATE COOLING.
 CAUSE(S):
 BLOCKED (CONTAMINATED) COOLANT (FUEL) INJECTOR HOLES, POOR BOUNDARY FLOW CONDITIONS COMBUSTION INSTABILITY, SEPARATION OR FRACTURE OF PROTECTIVE DISILICIDE COATING.
 EFFECT(S): ON (A) SUBSYSTEM (B) INTERFACES (C) MISSION (D) CREW/VEHICLE:
 (A) LOSS OF A PRIMARY THRUSTER IN A GIVEN AXIS. (B) INCREASED GN&C CONTROL AUTHORITY REQUIRED. (C) POTENTIAL LOSS OF MISSION ABORT DECISION. (D) POTENTIAL LOSS OF VEHICLE. CRITICAL DAMAGE COULD OCCUR BEFORE FAILURE IS DETECTED.
 DISPOSITION & RATIONALE (A) DESIGN (B) TEST (C) INSPECTION (D) FAILURE HISTORY:
 INTERMETALLIC DIFFUSION LAYER FORMS AN INTEGRAL BOND BETWEEN THE DISILICIDE COATING AND THE PARENT COLUMBIUM MATERIAL AND TENDS TO RESIST SHOCK LOADING. 75 MICRON FILTER IN VALVE INLET UPSTREAM OF INJECTOR HOLES WILL PRECLUDE ENTRY OF CONTAMINANTS. ACOUSTIC CAVITIES DAMPEN THE FREQUENCIES THAT EXCITE INSTABILITY. (B) SIMULATED THRUSTERS AND THRUSTER NO. 5 VIBRATION TESTS HAVE DEMONSTRATED THE ABILITY OF THE DISILICIDE COATING TO WITHSTAND 2.0 G SQUARED PER HERTZ RANDOM VIBRATION STRESSES. THRUSTER IS SUBJECTED TO RANDOM VIBRATION AT ANTICIPATED MISSION LEVELS DURING THE QUAL. PROGRAM. (C) COATING THICKNESS AND QUALITY WILL BE CONTROLLED BY SUPPLIER INSPECTION PROCEDURE MPS 525 WHICH REQUIRES CERTIFICATION THAT COATING PROCESS CONFORMS TO THE PROCESS SPEC. VISUAL INSPECTION, VERIFICATION OF COATING THICKNESS AND A SMOKE TEST THAT VERIFIES COAT INTEGRITY. TURNAROUND INSPECTION TO INCLUDE VISUAL INSPECTION FOR EVIDENCE OF BURN THRU. (D) NO FLIGHT FAILURE HISTORY. (2) DEVELOPMENT FAILURES HAVE OCCURRED ON SHUTTLE PROGRAM. ONE FAILURE DUE TO DOUBLET DESIGN WHICH HAS BEEN CHANGED AND ONE FAILURE DUE TO THIN COAT OF DISILICIDE COATING. THIN COAT STILL WITHSTOOD MORE FIRING TIME THAN IS NORMALLY SEEN BY THE THRUSTER IN NORMAL 100 MISSION LIFE.

SUBSYSTEM Fwd Reaction Control

FMEA NUMBER

SD75-SH-0016AITEM Nozzle ExtensionFAILURE MODE Burn-Thru

1. DOES THE FLIGHT SOFTWARE DETECT THIS FAILURE MODE (i.e., AUTOMATICALLY ANNUNCIATE OR TAKE ACTION IN RESPONSE)? YES ☐ NO ☒
- 1a. IF NOT, DOES THE HARDWARE PROVIDE INFORMATION THAT THE FLIGHT SOFTWARE COULD USE TO DETECT THE FAILURE? *YES ☐ NO ☐
2. ARE THE ANSWERS TO QUESTIONS 1 AND 1a CONSISTENT WITH THE FMEA EVALUATION OF IN-FLIGHT DETECTABILITY? YES ☒ *NO ☐
3. DOES THE FLIGHT SOFTWARE TAKE ACTION TO NEGATE THE EFFECTS OF THE FAILURE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? YES ☐ NO ☒
- 3a. IF NOT, DOES THE CAPABILITY EXIST FOR THE SOFTWARE TO COMPENSATE FOR THIS FAILURE MODE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? *YES ☒ NO ☐
4. AS A RESULT OF THIS FAILURE MODE, CAN THE SOFTWARE OVERSTRESS THE HARDWARE OR INDUCE ANOTHER FAILURE? *YES ☐ NO ☒
5. CAN THIS FAILURE MODE, IN COMBINATION WITH SOFTWARE LOGIC, ADVERSELY AFFECT OTHER FUNCTIONS? *YES ☐ NO ☒
6. HOW MANY OF THESE HARDWARE FAILURES CAN THE SHUTTLE TOLERATE (CONSIDER CREW ACTION AND HARDWARE/SOFTWARE OPERATION)? NOTE CHANGE TO FMEA CRITICALITY. *0 ☐ *1 ☐ 2 ☒
7. IF CREW ACTION IS REQUIRED TO RESPOND TO THIS FAILURE MODE, ARE CUES PROVIDED TO SIGNAL THE NEED FOR INTERVENTION AND THE REQUIRED CORRECTIVE ACTION? N/A ☐ YES ☒ NO ☐
8. IF THE ANSWER TO EITHER 1 OR 3 IS YES:
- A. CAN THE BFS BE ENGAGED AFTER OCCURRENCE? YES ☒ *NO ☐
- B. WILL BFS TOLERATE FAILURE WITHOUT LOSS OF CREW/VEHICLE? YES ☒ *NO ☐

*EXPLANATION REQUIRED (SEE BELOW)

CHANGE/RETENTION RATIONALE SUMMARY

1. ☐ NO H/S ISSUES 3. ☐ NO SOFTWARE DETECTION 5. ☐ ACCEPTANCE RATIONALE BELOW
2. ☒ HARDWARE ACCEPTS RISK 4. ☐ DETECTION DURING CHECKOUT 6. ☐ RECOMMENDED CHANGES BELOW

☐ FMEA CHANGE RECOMMENDEDEXPLANATION/COMMENTS:

3a. Instrumentation is available for software redesign.

SHUTTLE FAILURE MODE AND EFFECTS ANALYSIS - ORBITER 102

SUBSYSTEM : FWD - REACTION CONTROL	FMEA NO 03-2F -121213-1	REV: 12/18/71
.ASSEMBLY : THRUSTER, PRIMARY	ABORT: ABORT,	CRIT. FUNC: 1
.P/N RI : MC467-0028	RTLS	CRIT. HWD: 1
.P/N VENDOR: X30872	MISSIONS: HF VF X FF UF SM	
.QUANTITY : 14	PHASE(S): PL LG X GO X DO X LS	
. : ONE PER THRUSTER	NUMBER OF SUCCESS PATHS REMAINING	
. :	AFTER FIRST FAILURE:	2
. :	REDUNDANCY SCREEN: A-N/A B-N/A C-N/A	
.FAILURE DETECTABLE IN FLIGHT?. NO	TIME TO EFFECT:	
. :	IMMEDIATE	
. :	REFERENCE DOCUMENTS:	
.GROUND TURNAROUND?.....YES	MJ070-0001-01E	
.VISUAL INSPECTION	SD72-SH-0103-2	
. :	VS70-421001	

PREPARED BY:

DES

REL

W SEARCY

R DIEHL

APPROVED BY:

DES

REL

.ITEM: NOZZLE EXTENSION,
 . COATED COLUMBIUM (WITH INSULATION BLANKET).
 .FUNCTION:
 . TO PROVIDE FOR EXPANSION OF COMBUSTION GASES TO M>1 SUCH THAT THE
 REQUIRED THRUST IS PRODUCED.
 .FAILURE MODE: STRUCTURAL FAILURE, (S)
 . BURN-THRU.
 .CAUSE(S):
 . HIGH TEMPERATURE IN LOCAL SPOT DUE TO FILM COOLING FAILURE (CONTAMINATED
 INJECTOR COOLANT HOLES) VIBRATION, SHOCK, WELD OR MATERIAL DEFECT.
 .EFFECT(S): ON (A) SUBSYSTEM (B) INTERFACES (C) MISSION (D) CREW/VEHICLE:
 . (A) LOSS OF A THRUSTER IN A GIVEN AXIS. (B) INCREASED GN&C CONTROL
 AUTHORITY REQUIRED. (C) NO EFFECT. (D) NO EFFECT UNLESS FAILURE
 PROPAGATES-CRIT1 FOR RTLS ABORT IF THRUSTER IS ISOLATED AT MANIFOLD
 LEVEL
 .CORRECTING ACTION:
 . ISOLATE THRUSTER AT INLET VALVE OR MANIFOLD AND UTILIZE ALTERNATE IN
 AFFECTED AXIS..
 .REMARKS/HAZARDS:
 . POTENTIAL FOR FAILURE PROPAGATION TO ADJACENT THRUSTERS IF INSULATION
 BLANKET DOES NOT PRECLUDE GAS/LIQUID ESCAPING. REFERENCE HAZARD
 IYXX-0302-01.

ORIGINAL PAGE IS
 OF POOR QUALITY

SHUTTLE CRITICAL ITEMS LIST - ORBITER 102

SUBSYSTEM : FWD - REACTION CONTROL FMEA NO 03-2F -121313-1 REV: 11/14/
 .ASSEMBLY : THRUSTER, PRIMARY ABORT: ABORT, CRIT. FUNC: 1
 .P/N RI : MC467-0028 RTLS CRIT. HDW: 1
 .P/N VENDOR: X30872 MISSIONS: HF VF X FF OF SM
 .QUANTITY : 14 PHASE(S): PL LO X GO X DO X LS
 . : ONE PER THRUSTER
 . :
 . :

REDUNDANCY SCREEN: A-N/A B-N/A C-N/

.PREPARED BY:

.DES W SEARCY
 .REL R DIEHL

APPROVED BY:

DES *[Signature]*
 REL *[Signature]*

APPROVED BY (NASA):

SSM *[Signature]*
 REL *[Signature]*

APPROVED WITH CHANGES
 See Section 13.0

- .ITEM: NOZZLE EXTENSION,
- . COATED COLUMBIUM (WITH INSULATION BLANKET).
- .FUNCTION:
- . TO PROVIDE FOR EXPANSION OF COMBUSTION GASES TO $H>1$ SUCH THAT THE REQUIRED THRUST IS PRODUCED.
- .FAILURE MODE: STRUCTURAL FAILURE, (S)
- . BURN-THRU.
- .CAUSE(S):
- . HIGH TEMPERATURE IN LOCAL SPOT DUE TO FILM COOLING FAILURE (CONTAMINATED INJECTOR COOLANT HOLES) VIBRATION, SHOCK, WELD OR MATERIAL DEFECT.
- .EFFECT(S): ON (A) SUBSYSTEM (B) INTERFACES (C) MISSION (D) CREW/VEHICLE:
- . (A) LOSS OF A THRUSTER IN A GIVEN AXIS. (B) INCREASED GNC CONTROL AUTHORITY REQUIRED. (C) NO EFFECT. (D) NO EFFECT UNLESS FAILURE PROPAGATES-CRIT1 FOR RTLS ABORT IF THRUSTER IS ISOLATED AT MANIFOLD LEVEL
- .DISPOSITION & RATIONALE (A) DESIGN (B) TEST (C) INSPECTION (D) FAILURE HISTORY.
- . (A) INTERMETALLIC DIFFUSION LAYER FORMS INTEGRAL BOND TO RESIST SHOCK. COATING PROCESS CONTROLLED. INJECTOR DESIGN INCORPORATES ACOUSTIC CAVITIES WHICH REDUCED POSSIBILITY OF INSTABILITY. DUCTILE PROPERTIES OF C-103 COLUMBIUM PRECLUDES FRAGMENTATION OR CATASTROPHIC MODE OF FAILURE. (B) DEV VIBRATION TESTS DEMONSTRATE ABILITY OF DISILICIDE COATING TO WITHSTAND 2.0 G SQUARED/HZ RANDOM VIBRATION. TEMP TESTS DEMONSTRATE EXCELLENT DUCTIBLE/BRITTLE QUALIFIES FOR COATED C-103 COLUMBIUM. (C) TURNAROUND INSPECTION TO INCLUDE VISUAL INSPECTION FOR EVIDENCE OF BURN THROUGH & WHERE ACCESSABLE, USE OF FIBER-OPTICS NOE TO INSPECT FOR SURFACE FLAWS. SUPPLIER INSPECTION INCLUDES FLOUORESCENT PENETRATE INSPECTION PRIOR TO COATING TO DETECT SURFACE DEFECTS AND X-RAY INSPECTION IS REQUIRED FOR DETECTION OF INTERNAL DEFECTS. AUDIT CONDUCTED 9-2-76 VERIFIED THAT SUPPLIER INSPECTION CONTROLS RAW MAT'L, IDENTIFICATION OF PARTS, MFG PROCESSES, CORROSION PROTECTION, CONTAMINATION CONTROL AND ENVIRONMENTS. (D) 4 OCCURANCES OF BELL FAILURES CAUSED BY BRITTLE HETEROGENEOUS GRAIN STRUCTURE DUE TO VIBRATION FATIGUE ON APOLLO LM/SM RCS ENGINES.

1. DOES THE FLIGHT SOFTWARE DETECT THIS FAILURE MODE (i.e., AUTOMATICALLY ANNUNCIATE OR TAKE ACTION IN RESPONSE)? YES ☒ NO ☐
- 1a. IF NOT, DOES THE HARDWARE PROVIDE INFORMATION THAT THE FLIGHT SOFTWARE COULD USE TO DETECT THE FAILURE? *YES ☐ NO ☐
2. ARE THE ANSWERS TO QUESTIONS 1 AND 1a CONSISTENT WITH THE FMEA EVALUATION OF IN-FLIGHT DETECTABILITY? YES ☒ *NO ☐
3. DOES THE FLIGHT SOFTWARE TAKE ACTION TO NEGATE THE EFFECTS OF THE FAILURE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? YES ☒ NO ☐
- 3a. IF NOT, DOES THE CAPABILITY EXIST FOR THE SOFTWARE TO COMPENSATE FOR THIS FAILURE MODE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? *YES ☐ NO ☐
4. AS A RESULT OF THIS FAILURE MODE, CAN THE SOFTWARE OVERSTRESS THE HARDWARE OR INDUCE ANOTHER FAILURE? *YES ☐ NO ☒
5. CAN THIS FAILURE MODE, IN COMBINATION WITH SOFTWARE LOGIC, ADVERSELY AFFECT OTHER FUNCTIONS? *YES ☐ NO ☒
6. HOW MANY OF THESE HARDWARE FAILURES CAN THE SHUTTLE TOLERATE (CONSIDER CREW ACTION AND HARDWARE/SOFTWARE OPERATION)? NOTE CHANGE TO FMEA CRITICALITY. *0 ☐ *1 ☒ 2 ☐
7. IF CREW ACTION IS REQUIRED TO RESPOND TO THIS FAILURE MODE, ARE CUES PROVIDED TO SIGNAL THE NEED FOR INTERVENTION AND THE REQUIRED CORRECTIVE ACTION? N/A ☐ YES ☒ NO ☐
8. IF THE ANSWER TO EITHER 1 OR 3 IS YES:
 - A. CAN THE BFS BE ENGAGED AFTER OCCURRENCE? YES ☒ *NO ☐
 - B. WILL BFS TOLERATE FAILURE WITHOUT LOSS OF CREW/VEHICLE? YES ☒ *NO ☐

*EXPLANATION REQUIRED (SEE BELOW)

CHANGE/RETENTION RATIONALE SUMMARY

- | | | |
|--|---|--|
| 1. <input type="checkbox"/> NO H/S ISSUES | 3. <input type="checkbox"/> NO SOFTWARE DETECTION | 5. <input type="checkbox"/> ACCEPTANCE RATIONALE BELOW |
| 2. <input checked="" type="checkbox"/> HARDWARE ACCEPTS RISK | 4. <input type="checkbox"/> DETECTION DURING CHECKOUT | 6. <input type="checkbox"/> RECOMMENDED CHANGES BELOW |

☐ FMEA CHANGE RECOMMENDEDEXPLANATION/COMMENTS:

1. RM uses thrust chamber pressure transducers to sense the low pressure in question and give a "fail off" in RCS RM.
3. The GN&C RM program will automatically deselect a failed jet under certain conditions (provided it is not inhibited). See FSSR "10" paragraph 4.1.7.1.6.3 for the conditions.
6. This failure can be tolerated since it is criticality 2.
7. The thrust chamber pressures can be downlinked.

SHUTTLE FAILURE MODE AND EFFECTS ANALYSIS - ORBITER 102

SUBSYSTEM : FWD - REACTION CONTROL FMEA NO 03-2F -131310-1 REV: 11/14/77
 .ASSEMBLY : THRUSTER ASSY ABORT: CRIT. FUNC: 2
 .P/N RI : MC467-0029 CRIT. HWO: 2
 .P/N VENDOR: MISSIONS: HF VF X HF GF SM
 .QUANTITY : 2 PHASE(S): PL LO DO X DO LS
 . : ONE REQ'D PER SIDE NUMBER OF SUCCESS PATHS REMAINING
 . : (DOWN FIRING) AFTER FIRST FAILURE: C
 . REDUNDANCY SCREEN: A-N/A B-N/A C-N/A
 .FAILURE DETECTABLE IN FLIGHT?. YES TIME TO EFFECT:
 .THRUSTER CHAMBER PRESS V42P-1555A, 1556A IMMEDIATE
 . REFERENCE DOCUMENTS:
 . MJG70-0001-015
 . GROUND TURNAROUND?.....YES SD72-SH-0103-2
 .POSITION INDICATION VS70-4210C1

PREPARED BY:

DES

REL

J TAGGART

R DIEHL

APPROVED BY:

DES

REL

.ITEM: THRUSTER, VERNIER

. (EN 157/158).

.FUNCTION:

. TO PROVIDE THRUST FOR LOW LEVEL ACCELERATIONS ASSOCIATED WITH POINTING MANEUVERS AND THREE AXIS ATTITUDE HOLD. THRUSTER FIRES IN +Z DIRECTION FOR + PITCH AND -Z ACCELERATION. INCLUDES INLET VALVE, INJECTOR, THRUST CHAMBER, NOZZLE EXTENSION, HEATER, INSULATION, PRESS/TEMP XSDUCERS.

.FAILURE MODE: LOSS OF OUTPUT (F)

. INLET VALVES/BLOCKED INJECTOR/STAND-OFF'S.

.CAUSE(S):

. CONTAMINATION, PIECE PART STRUCTURAL FAILURE, IMPROPER SOLENOID ACTUATION, VIBRATION

.EFFECT(S): ON (A)SUBSYSTEM (B)INTERFACES (C)MISSION (D)CREW/VEHICLE:

. (A) LOSS OF VERNIER FUNCTION. (B) NO EFFECT. (C) POTENTIAL EARLY MISSION TERMINATION. LOSS OF TIGHT DEADBAND ATTITUDE CONTROL. (D) NO EFFECT.

.CORRECTING ACTION:

. UTILIZE LARGE THRUSTERS FOR ATTITUDE CONTROL IN AFFECTED AXIS (INCREASED PROPELLANT QUANTITY DEPLETION)

.REMARKS/HAZARDS:

. POTENTIAL HAZARD IF FAILURE OCCURS DURING CRITICAL MANEUVERS - TIME CRITICAL. NO REDUNDANCY IS PROVIDED FOR THIS COMPONENT.

SHUTTLE CRITICAL ITEMS LIST - OPBITER 102

SUBSYSTEM : FWD - REACTION CONTROL FMEA NO 03-2F -131310-1 REV: 11/14/76
 ASSEMBLY : THRUSTER ASSY ABORT: CRIT. FUNC: 2
 P/N RI : MC467-0029 CRIT. HDW: 2
 P/N VENDOR: MISSIONS: HF VF X FF OF SM
 QUANTITY : 2 PHASE(S): PL LO CO X DO LS
 : ONE REQ'D PER SIDE
 : (DOWN FIRING)

REDUNDANCY SCREEN: A-N/A B-N/A C-N/A

PREPARED BY:
 DES J TAGGART
 REL R DIEHL

APPROVED BY:
 DES [Signature]
 REL C.E. Danner 12/15/76

APPROVED BY INASA:
 SSM [Signature]
 REL [Signature]

ITEM: THRUSTER, VERNIER
 (EN 157/158).

FUNCTION:

- TO PROVIDE THRUST FOR LOW LEVEL ACCELERATIONS ASSOCIATED WITH POINTING MANEUVERS AND THREE AXIS ATTITUDE HOLD. THRUSTER FIRES IN +Z DIRECTION FOR + PITCH AND -Z ACCELERATION. INCLUDES INLET VALVE, INJECTOR, THRUST CHAMBER, NOZZLE EXTENSION, HEATER, INSULATION, PRESS/TEMP XSDUCERS.

FAILURE MODE: LOSS OF OUTPUT (F)

- INLET VALVES/BLOCKED INJECTOR/STAND-OFF'S.

CAUSE(S):

- CONTAMINATION, PIECE PART STRUCTURAL FAILURE, IMPROPER SCLENCID ACTUATION, VIBRATION

EFFECT(S): ON (A) SUBSYSTEM (B) INTERFACES (C) MISSION (D) CREW/VEHICLE:

- (A) LOSS OF VERNIER FUNCTION. (B) NO EFFECT. (C) POTENTIAL EARLY MISSION TERMINATION. LOSS OF TIGHT DEADBAND ATTITUDE CONTROL. (D) NO EFFECT.

DISPOSITION & RATIONALE (A) DESIGN (B) TEST (C) INSPECTION (D) FAILURE HISTORY:

- (A) VALVE INCORPORATES A 25 MICRON FILTER TO PRECLUDE CONTAMINATION. VALVE HAS BEEN DESIGNED TO PRECLUDE SELF GENERATED CONTAMINATES. SPECIAL EMPHASIS PLACED ON SOLENOID AND WIRING TO PRECLUDE SHORTS. (B) PRE/POST FLIGHT CHECKOUT AND VALVE SIGNATURE TESTS WHEN MODULE REMOVED. VALVE SUBJECTED TO RANDOM VIBRATION AT ANTICIPATED MISSION LEVELS DURING QUAL PROGRAM. LENGTH OF TIME FOR VIBRATION TO EQUAL 100 MISSION LIFE EXPECTANCY. (C) AUDIT CONDUCTED 9-2-76 VERIFIED THAT SUPPLIER INSPECTION CONTROLS RAW MAT'L, IDENTIFICATION OF PARTS, MFG PROCESSES, CORROSION PROTECTION, CONTAMINATION CONTROL, AND ELECTRICAL TERMINATIONS. TURNAROUND INSPECTION INCLUDES MONITORING FUNCTIONAL TEST DURING PRESSURIZATION CYCLE FOR EVIDENCE OF ERRATIC OPERATION. (D) NO FAILURE HISTORY APPLICABLE TO THIS FAILURE MODE.

SUBSYSTEM Fwd Reaction Control
ITEM Vernier Thruster

HARDWARE/SOFTWARE ANALYSIS CHECKLIST 03-2F-131310-3
FMEA NUMBER SD75-SH-0016A
FAILURE MODE Erratic Operation

1. DOES THE FLIGHT SOFTWARE DETECT THIS FAILURE MODE (i.e., AUTOMATICALLY ANNUNCIATE OR TAKE ACTION IN RESPONSE)? YES ☐ NO ☒
- 1a. IF NOT, DOES THE HARDWARE PROVIDE INFORMATION THAT THE FLIGHT SOFTWARE COULD USE TO DETECT THE FAILURE? *YES ☐ NO ☐
2. ARE THE ANSWERS TO QUESTIONS 1 AND 1a CONSISTENT WITH THE FMEA EVALUATION OF IN-FLIGHT DETECTABILITY? YES ☒ *NO ☐
3. DOES THE FLIGHT SOFTWARE TAKE ACTION TO NEGATE THE EFFECTS OF THE FAILURE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? YES ☒ NO ☐
- 3a. IF NOT, DOES THE CAPABILITY EXIST FOR THE SOFTWARE TO COMPENSATE FOR THIS FAILURE MODE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? *YES ☐ NO ☐
4. AS A RESULT OF THIS FAILURE MODE, CAN THE SOFTWARE OVERSTRESS THE HARDWARE OR INDUCE ANOTHER FAILURE? *YES ☐ NO ☒
5. CAN THIS FAILURE MODE, IN COMBINATION WITH SOFTWARE LOGIC, ADVERSELY AFFECT OTHER FUNCTIONS? *YES ☐ NO ☒
6. HOW MANY OF THESE HARDWARE FAILURES CAN THE SHUTTLE TOLERATE (CONSIDER CREW ACTION AND HARDWARE/SOFTWARE OPERATION)? NOTE CHANGE TO FMEA CRITICALITY. *0 ☐ *1 ☒ 2 ☐
7. IF CREW ACTION IS REQUIRED TO RESPOND TO THIS FAILURE MODE, ARE CUES PROVIDED TO SIGNAL THE NEED FOR INTERVENTION AND THE REQUIRED CORRECTIVE ACTION? N/A ☐ YES ☒ NO ☐
8. IF THE ANSWER TO EITHER 1 OR 3 IS YES:
 - A. CAN THE BFS BE ENGAGED AFTER OCCURRENCE? YES ☒ *NO ☐
 - B. WILL BFS TOLERATE FAILURE WITHOUT LOSS OF CREW/VEHICLE? YES ☒ *NO ☐

*EXPLANATION REQUIRED (SEE BELOW)

CHANGE/RETENTION RATIONALE SUMMARY

- | | | |
|--|---|--|
| 1. <input type="checkbox"/> NO H/S ISSUES | 3. <input type="checkbox"/> NO SOFTWARE DETECTION | 5. <input type="checkbox"/> ACCEPTANCE RATIONALE BELOW |
| 2. <input checked="" type="checkbox"/> HARDWARE ACCEPTS RISK | 4. <input type="checkbox"/> DETECTION DURING CHECKOUT | 6. <input type="checkbox"/> RECOMMENDED CHANGES BELOW |

No In-Flight Detectability

☒ FMEA CHANGE RECOMMENDED

EXPLANATION/COMMENTS:

1. May not be detected unless 3 consecutive low pressures.

SHUTTLE FAILURE MODE AND EFFECTS ANALYSIS - ORBITER 102

SUBSYSTEM : FWD - REACTION CONTROL FMEA NO 03-2F -13131C-3 REV:11/10/7
 .ASSEMBLY : THRUSTER ASSY ABORT: CRIT. FUNC: 2
 .P/N RI : MC467-0029 CRIT. FWD: 2
 .P/N VENDOR: MISSIONS: HF VF X FF GF SM
 .QUANTITY : 2 PHASE(S): PL LO OO X DO LS
 . : ONE REQ'D PER SIDE NUMBER OF SUCCESS PATHS REMAINING
 . : (DOWN FIRING) AFTER FIRST FAILURE: C
 . REDUNDANCY SCREEN: A-N/A B-N/A C-N/A
 .FAILURE DETECTABLE IN FLIGHT?. YES TIME TO EFFECT:
 .THRUSTER CHAMBER PRESS. INDICATION V42P-1555A IMMEDIATE
 .1556A REFERENCE DOCUMENTS:
 . MJ070-0001-C16
 .GROUND TURNAROUND?.....NO SD72-SH-0103-2
 . VS70-421001
 .
 .
 .
 .
 . PREPARED BY: APPROVED BY:
 . DES J TAGGART DES _____
 . REL R DIEHL REL _____
 .
 .
 . ITEM: THRUSTER, VERNIER
 . (EN 157/158).
 .FUNCTION:
 . TO PROVIDE THRUST FOR LOW LEVEL ACCELERATIONS ASSOCIATED WITH POINTING
 MANEUVERS AND THREE AXIS ATTITUDE HOLD. THRUSTER FIRES IN +Z DIRECTION
 FOR + PITCH AND -Z ACCELERATION. INCLUDES INLET VALVE, INJECTOR,
 THRUST CHAMBER, NOZZLE EXTENSION, HEATER, INSULATION, PRESS/TEMP
 XSDUCERS.
 .FAILURE MODE: ERRATIC OPERATION (F)
 . LOW/HIGH THRUST OR INTERMITTENT OPERATION
 .CAUSE(S):
 . CONTAMINATION, IMPROPER SOLENOID ACTUATION.
 .EFFECT(S): ON (A)SUBSYSTEM (B)INTERFACES (C)MISSION (D)CREW/VEHICLE:
 . (A) LOSS OF VERNIER CONTROL B) INTERFACE SWITCHING OF POWER AND
 . GN&C CONTROL TO LARGE THRUSTERS. (C) POSSIBLE EARLY MISSION TERMINATION
 BOTH VERNIER THRUSTERS WOULD HAVE TO BE ISOLATED SUCH THAT TIGHT DEADBAND
 ATTITUDE CONTROL WOULD BE LOST. (D) NONE.
 .CORRECTING ACTION:
 . SHUT DOWN/ISOLATE FAILED THRUSTER AND UTILIZE LARGE THRUSTER IN
 AFFECTED AXIS
 .REMARKS/HAZARDS:
 . POTENTIAL HAZARD FROM COLLISION. NO REDUNDANCY IS PROVIDED FOR THIS
 COMPONENT.

SHUTTLE CRITICAL ITEMS LIST - ORBITER 102

SUBSYSTEM : FWD - REACTION CONTROL FMEA NO 03-2F -131310-3 REV: 11/10/
 ASSEMBLY : THRUSTER ASSY ABORT: CRIT. FUNC: 2
 P/N RI : 40467-0029 CRIT. HOW: 2
 P/N VENDOR: MISSIONS: HF VF X FF OF SM
 QUANTITY : 2 PHASE(S): PL LO OO X OO LS
 : ONE REQ'D PER SIDE
 : (DOWN FIRING)

REDUNDANCY SCREEN: A-N/A B-N/A C-N/

PREPARED BY: J TAGGART APPROVED BY: *[Signature]* APPROVED BY (NASA): *[Signature]*
 DES DES *[Signature]* SSM *[Signature]*
 REL REL *[Signature]* REL *[Signature]*

ITEM: THRUSTER, VERNIER
 (EN 157/158).

FUNCTION:

- TO PROVIDE THRUST FOR LOW LEVEL ACCELERATIONS ASSOCIATED WITH POINTING MANEUVERS AND THREE AXIS ATTITUDE HOLD. THRUSTER FIRES IN +Z DIRECTION FOR + PITCH AND -Z ACCELERATION. INCLUDES INLET VALVE, INJECTOR, THRUST CHAMBER, NOZZLE EXTENSION, HEATER, INSULATION, PRESS/TEMP XSOURCES.

FAILURE MODE: ERRATIC OPERATION (F)

- LOW/HIGH THRUST OR INTERMITTENT OPERATION

CAUSE(S):

- CONTAMINATION, IMPROPER SOLENOID ACTUATION.

EFFECT(S): ON (A) SUBSYSTEM (B) INTERFACES (C) MISSION (D) CREW/VEHICLE:

- (A) LOSS OF VERNIER CONTROL (B) INTERFACE SWITCHING OF POWER AND GN&C CONTROL TO LARGE THRUSTERS. (C) POSSIBLE EARLY MISSION TERMINATION BOTH VERNIER THRUSTERS WOULD HAVE TO BE ISOLATED SUCH THAT TIGHT DEADBAND ATTITUDE CONTROL WOULD BE LOST. (D) NONE.

DISPOSITION & RATIONALE (A) DESIGN (B) TEST (C) INSPECTION (D) FAILURE HISTORY:

- (A) VALVE INCORPORATES A 75 MICRON FILTER TO PRECLUDE CONTAMINATION. VALVE HAS BEEN DESIGNED TO PRECLUDE SELF GENERATED CONTAMINATES. SPECIAL EMPHASIS PLACED ON SOLENOID AND WIRING TO PRECLUDE SHORTS. (B) PRE/POST FLIGHT CHECKOUT AND VALVE SIGNATURES TESTS WHEN MODULE REMOVED. VALVE SUBJECTED TO RANDOM VIBRATION AT ANTICIPATED MISSION LEVELS DURING QUAL PROGRAM. LENGTH OF TIME FOR VIBRATION TO EQUAL 100 MISSION LIFE EXPECTANCY. (C) AUDIT CONDUCTED 9-2-75 VERIFIED THAT SUPPLIER INSPECTION CONTROLS RAW MAT'L, IDENTIFICATION OF PARTS, MFG PROCESSES, CORROSION PROTECTION, CONTAMINATION CONTROL, AND ELECTRICAL TERMINATIONS. TURNAROUND INSPECTION INCLUDES MONITORING FUNCTIONAL TEST DURING PRESSURIZATION CYCLE FOR EVIDENCE OF ERRATIC OPERATION. (D) NO FAILURE HISTORY CONCERNING THIS FAILURE MODE.

SUBSYSTEM Fwd. Reaction Control

FMEA NUMBER

SD75-SH-0016A

ITEM Vernier ThrusterFAILURE MODE Burn-Thru

1. DOES THE FLIGHT SOFTWARE DETECT THIS FAILURE MODE (i.e., AUTOMATICALLY ANNUNCIATE OR TAKE ACTION IN RESPONSE)? YES ☒ NO ☐
- 1a. IF NOT, DOES THE HARDWARE PROVIDE INFORMATION THAT THE FLIGHT SOFTWARE COULD USE TO DETECT THE FAILURE? *YES ☐ NO ☐
2. ARE THE ANSWERS TO QUESTIONS 1 AND 1a CONSISTENT WITH THE FMEA EVALUATION OF IN-FLIGHT DETECTABILITY? YES ☒ *NO ☐
3. DOES THE FLIGHT SOFTWARE TAKE ACTION TO NEGATE THE EFFECTS OF THE FAILURE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? YES ☒ NO ☐
- 3a. IF NOT, DOES THE CAPABILITY EXIST FOR THE SOFTWARE TO COMPENSATE FOR THIS FAILURE MODE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? *YES ☐ NO ☐
4. AS A RESULT OF THIS FAILURE MODE, CAN THE SOFTWARE OVERSTRESS THE HARDWARE OR INDUCE ANOTHER FAILURE? *YES ☐ NO ☒
5. CAN THIS FAILURE MODE, IN COMBINATION WITH SOFTWARE LOGIC, ADVERSELY AFFECT OTHER FUNCTIONS? *YES ☐ NO ☒
6. HOW MANY OF THESE HARDWARE FAILURES CAN THE SHUTTLE TOLERATE (CONSIDER CREW ACTION AND HARDWARE/SOFTWARE OPERATION)? NOTE CHANGE TO FMEA CRITICALITY. *0 ☒ *1 ☐ 2 ☐
7. IF CREW ACTION IS REQUIRED TO RESPOND TO THIS FAILURE MODE, ARE CUES PROVIDED TO SIGNAL THE NEED FOR INTERVENTION AND THE REQUIRED CORRECTIVE ACTION? N/A ☐ YES ☒ NO ☐
8. IF THE ANSWER TO EITHER 1 OR 3 IS YES:
- A. CAN THE BFS BE ENGAGED AFTER OCCURRENCE? YES ☒ *NO ☐
- B. WILL BFS TOLERATE FAILURE WITHOUT LOSS OF CREW/VEHICLE? YES ☐ *NO ☒

*EXPLANATION REQUIRED (SEE BELOW)

CHANGE/RETENTION RATIONALE SUMMARY:

- | | | |
|--|---|--|
| 1. <input type="checkbox"/> NO H/S ISSUES | 3. <input type="checkbox"/> NO SOFTWARE DETECTION | 5. <input type="checkbox"/> ACCEPTANCE RATIONALE BELOW |
| 2. <input checked="" type="checkbox"/> HARDWARE ACCEPTS RISK | 4. <input type="checkbox"/> DETECTION DURING CHECKOUT | 6. <input type="checkbox"/> RECOMMENDED CHANGES BELOW |

☐ FMEA CHANGE RECOMMENDEDEXPLANATION/COMMENTS:

1. The GN&C RM Program will automatically deselect a failed jet and issue an alert. Detectable in thrust chamber but not in nozzle.

6. This is a criticality 1 failure and cannot be tolerated.

7. The thrust chamber pressures can be downlinked.

8B. Same as primary.

SHUTTLE FAILURE MODE AND EFFECTS ANALYSIS - ORBITER 1C2

SUBSYSTEM : FWD - REACTION CONTROL FMEA NO 03-2F -131310-4 REV:12/08/76
 .ASSEMBLY : THRUSTER ASSY ABORT: CRIT. FUNC: 1
 .P/N RI : MC467-0029 CRIT. HWD: 1
 .P/N VENDOR: MISSIONS: HF VF X FF OF SM
 .QUANTITY : 2 PHASE(S): PL LO DO X DO LS
 . : ONE REQ'D PER SIDE NUMBER OF SUCCESS PATHS REMAINING
 . : (DOWN FIRING) AFTER FIRST FAILURE: 2
 . REDUNDANCY SCREEN: A-N/A B-N/A C-N/A
 .FAILURE DETECTABLE IN FLIGHT?. YES TIME TO EFFECT:
 . MINOR LEAKAGE OR INCIPIENT FAILURE SECONDS
 . REFERENCE DOCUMENTS:
 .GROUND TURNAROUND?.....YES MJC70-0001-018
 .VISUAL EXAMINATION SD72-SH-0103-2
 . VS70-421001
 .
 .
 . PREPARED BY: APPROVED BY:
 . DES J TAGGART DES _____
 . REL R DIEHL REL _____
 .
 .
 .ITEM: THRUSTER, VERNIER
 . (EN 157/158).
 .FUNCTION:
 . TO PROVIDE THRUST FOR LOW LEVEL ACCELERATIONS ASSOCIATED WITH POINTING
 MANEUVERS AND THREE AXIS ATTITUDE HOLD. THRUSTER FIRES IN +Z DIRECTION
 FOR + PITCH AND -Z ACCELERATION. INCLUDES INLET VALVE, INJECTOR,
 THRUST CHAMBER, NOZZLE EXTENSION, HEATER, INSULATION, PRESS/TEMP
 XSOURCES.
 .FAILURE MODE: OVERHEAT/BURNTHROUGH (F)
 .
 .CAUSE(S):
 . MAX PRESSURE SPIKES, SURFACE DEFECTS IN THE PROTECTIVE DISILICIDE
 COATING FOR CHAMBER WALL AND VIBRATION.
 .EFFECT(S): CN (A)SUBSYSTEM (B)INTERFACES (C)MISSION (D)CREW/VEHICLE:
 . (A) LOSS OF VERNIER THRUSTER. (B) POTENTIAL DAMAGE. (C) POTENTIAL
 . EARLY MISSION TERMINATION. (D) POTENTIAL LOSS OF VEHICLE. CRITICAL
 DAMAGE COULD OCCUR BEFORE FAILURE IS DETECTED.
 .CORRECTING ACTION:
 . ISOLATE FAILED THRUSTER AND USE OTHER THRUSTERS.
 .REMARKS/HAZARDS:
 . POTENTIAL HAZARD FROM ESCAPING HOT GASES IN THE MODULE AND POTENTIAL
 PROPAGATION OF FAILURE IF NOT ISOLATED IN A TIMELY MANNER.

SHUTTLE CRITICAL ITEMS LIST - ORBITER 102

SUBSYSTEM : FWD - REACTION CONTROL FMEA NO 03-2F -131310-4 REV:12/08/78
 .ASSEMBLY : THRUSTER ASSY ABORT: CRIT. FUNC: 1
 .P/N RI : MC467-0029 CRIT. HDW: 1
 .P/N VENDOR:
 .QUANTITY : 2 MISSIONS: HF VF X FF OF SM
 PHASE(S): PL LO OO X DO LS
 . : ONE REQ'D PER SIDE
 . : (DOWN FIRING)

REDUNDANCY SCREEN: A-N/A B-N/A C-N/A

.PREPARED BY:
 .DES J TAGGART
 .REL R DIEHL

APPROVED BY:
 DES *[Signature]*
 REL *[Signature]* 14/5/77

APPROVED BY (NASA):
 SSM *[Signature]*
 REL *[Signature]*

APPROVED WITH CHANGES
 See Section 13.0

.ITEM: THRUSTER, VERNIER
 . (EN 157/158).

.FUNCTION:

. TO PROVIDE THRUST FOR LOW LEVEL ACCELERATIONS ASSOCIATED WITH POINTING MANEUVERS AND THREE AXIS ATTITUDE HOLD. THRUSTER FIRES IN +Z DIRECTION FOR + PITCH AND -Z ACCELERATION. INCLUDES INLET VALVE, INJECTOR, THRUST CHAMBER, NOZZLE EXTENSION, HEATER, INSULATION, PRESS/TEMP XSDUCERS.

.FAILURE MODE: OVERHEAT/BURNTHROUGH (F)

.CAUSE(S):

. MAX PRESSURE SPIKES, SURFACE DEFECTS IN THE PROTECTIVE DISILICIDE COATING FOR CHAMBER WALL AND VIBRATION.

.EFFECT(S): ON (A)SUBSYSTEM (B)INTERFACES (C)MISSION (D)CREW/VEHICLE:

. (A) LOSS OF VERNIER THRUSTER. (B) POTENTIAL DAMAGE. (C) POTENTIAL EARLY MISSION TERMINATION. (D) POTENTIAL LOSS OF VEHICLE. CRITICAL DAMAGE COULD OCCUR BEFORE FAILURE IS DETECTED.

.DISPOSITION & RATIONALE (A)DESIGN (B)TEST (C)INSPECTION (D)FAILURE HISTORY:

. (A) INTERMETALLIC DIFFUSION LAYER FORMS AN INTEGRAL BOND BETWEEN THE DISILICIDE COATING AND THE PARENT COLUMBIUM MATERIAL (C-103) AND TENDS TO RESIST SHOCK LOADING. (B) PRIOR TESTS CONDUCTED ON THE R1-1 THRUSTER HAVE DEMONSTRATED THE ABILITY OF THE DISILICIDE COATING TO WITHSTAND IMPACT LEVELS AND THERMAL STRESSES PRODUCED BY TEMPERATURES IN EXCESS OF 2900 DEGREES F. TORCH TESTS HAVE DEMONSTRATED THE INSENSITIVITY OF THE R512A COATING TO THERMAL SHOCK. (C) AUDIT CONDUCTED 9-2-76 VERIFIED THAT THE SUPPLIER INSPECTION CONTROLS RAW MAT'L, IDENTIFICATION OF PARTS MFG. PROCESSES, CORROSION PROTECTION, CONTAMINATION CONTROL, AND FLOURESCENT PENETRANT INSPECTION PRIOR TO COATING TO DETECT SURFACE FLAWS AND X-RAY INSPECTION IS REQUIRED FOR DETECTION OF INTERNAL DEFECTS. COATING THICKNESS AND QUALITY IS CONTROLLED BY MPS 525 WHICH WILL REQUIRE CERTIFICATION THAT COATING PROCESS CONFORMS TO THE PROCESS SPECIFICATION, VISUAL INSPECTION, VERIFICATION OF COATING THICKNESS & TEST TO VERIFY COATING INTEGRITY. TURNAROUND INSPECTION TO INCLUDE VISUAL INSPECTION FOR EVIDENCE OF BURN THROUGH AND WHERE ACCESSIBLE. USE OF FIBER OPTICS NDE TO INSPECT FOR SURFACE FLAWS.
 (D) NO FLIGHT FAILURE HISTORY.

Meeting Minutes

Review of JSC 14651, Hardware/Software Interaction Analysis Volume VIII,
Forward Reaction Control System Part 1 of 2.

1. Meeting held at Rockwell International, Downey, 1:00PM to 2:30PM, 9/24/79.

<u>Attendees</u>	<u>Organization</u>	<u>Phone</u>
Edward Vonusa	NASA	X-1470
Dave Latham	JSC Reliability (Boeing)	527-0323 FTS
Rudy Kubica	RI Propulsion/RCS	X-4720
Larry Gladu	RI System Engineering	X-1189
Bill Meyers	RI System Engineering	X-1726
Bob Diehl	RI Reliability	X-2098

3. The following changes were discussed and will be incorporated in the final release of Forward Reaction Control System Hardware/Software Interaction Analysis and will be reflected in next update of Fwd RCS FMEA:

03-2F-101010-1: Change "SMU" to "SM". Insert "SM Alert" before "blue light."

03-2F-101013-1: Same as 03-2F-101010-1.

03-2F-101020-3: Same as 03-2F-101010-1.

03-2F-101020-4: Same as 03-2F-101010-1.

03-2F-101030-1: Add "X" in No. Block, question 1a.

03-2F-101030-2: Add V42P1116C to Explanation 1. and 2.

03-2F-101060-1: Show class 3 alarm with blue light and class 2 alarm with red light. Add V421116C. (Explanation 1.)

03-2F-101060-2: Add "X", No Block, question 1a.

03-2F-101060-3: Same as 03-2F-101060-1.

03-2F-101060-4: Same as 03-2F-101060-1.

03-2F-101060-5: Same as 03-2F-101060-1.

03-2F-101070-1: Under 1 & 2 Explanation, add V421113C, 1114C. Change class 2 to 3.

03-2F-101080-1: Change FMEA to show detectability method.

03-2F-101090-1: Under 1 & 2 Explanation, change V42P1110C, 1112C to 1113C, 1114C. Change class 2 to 3. Add gross leakage detectability (see 03-2F-101080-1).

- 03-2F-101095-2: Change "X" from Yes Block to No Block, question 1. Under Explanation, delete 1 & 2 (failure is one leg only - requires failure of both legs to actuate C & W).
- 03-2F-102106-1: Under 1 Explanation, add gross leakage detectability (see 03-2F-101080-1). Under 7 Explanation and FMEA change add V42P1115C. Change FMEA to show detectability.
- 03-2F-102108-1: Under 1 Explanation, add gross leakage detectability (see 03-2F-101080-1) Under 7 Explanation add V42P1115C.
- 03-2F-102120-1: Under 1 Explanation, add oxidizer measurement numbers, and add "failed off thruster will give "failed jet on C & W".
- 03-2F-102150-1: Same as 03-2F-102120-1 plus retain V42P1312C and delete 1313C and 1314C.
- 03-2F-102170-1: Under 1 Explanation, add measurements V42X1333X, 1233X. Change class 2 to 3.
- 03-2F-111110-1: Under 1 Explanation, add V42P1210C, 1212C, 1216C and add to FMEA detectability. Add X in FMEA change recommended block.
- 03-2F-111110-2: Same as 03-2F-111110-1.
- 03-2F-111110-3: Under 1 Explanation, add gross leakage detectability (see 03-2F-101080-1)
- 03-2F-11111-4: Change X from No Block to Yes block for question 1. Under Explanation, delete 1st paragraph and 1. (White Sands Test on vernier showed complete loss chamber pressure which is detectable. Similar gas bubbles in propellant tests are planned for primary thrusters).
- 03-2F-121308-1: Under 1 Explanation, the class 3 alarm is doubtful. Check and verify findings with Bill Meyers RI Systems Engineering. Also add gross leakage detectability (see 03-2F-101080-1).
- 03-2F-121311-1: Change Failure Mode to agree with failure mode in FMEA.
- 03-2F-121312-1: Under 1 Explanation, add "If failure is upstream of throat it will be detected by PC; if failure is downstream of throat it will not be detected."
- 03-2F-121313-1: Change X from Yes Block to No Block, question 1. Delete 1. under Explanation (failure is downstream of throat and will not be detected by PC).
- 03-2F-131310-3: Change X from Yes Block to No Block, question 1. Add X to FMEA change recommended block. Under 1. Explanation, delete entire sentence (the pressure transducers are snubbed by an orifice and will not detect the erratic operation). Change FMEA to indicate no detectability.

Approved by:

RG
Wm

Larry Glad
Larry Glad, RI
System Engineering

Dave Latham
Dave Latham
JSC Reliability (Boeing)

Edward M. Vonusa
Edward Vonusa
NASA QARSO

Document Number: JSC 14651

Title: HARDWARE/SOFTWARE INTERACTION ANALYSIS
Volume VIII, Forward Reaction Control System, Part 1 of 2

Prepared by: NB - Reliability Division

Distributed by: NB - SR&QA Data Center

Authorized Distribution

NASA/JSC

EH/J. F. Hanaway (2)

JM6/(3) ←

MG/A. D. Aldrich

NA/M. L. Raines/L. T. Spence

SR&QA Data Center (Boeing, HS-01)

NB/J. H. Levine/H. L. Williams

W. L. Bunce (Boeing, HS-02)

J. A. Homerstad

ND/T. J. Adams

S. Costello (Boeing, HS-03)

NE3/E. Vonusa

NS/J. B. Hammack

Rockwell-Downey

041-AD45/C. O. Baker, Jr./V. P. Ostrander

041-FA46/G. A. Phelps

041-FA46/L. W. Gladu

041-FA46/W. A. Harris

041-FB75/W. B. Fouts